**Indian Point 3 Nuclear Power Plant** P.O. Box 215 Buchanan, New York 10511 914 736.8001



Robert J. Barrett Site Executive Officer

June 9, 1998 IPN-98-066

**U.S. Nuclear Regulatory Commission** ATTN: Document Control Center Washington, D.C. 20555

SUBJECT:

Indian Point 3 Nuclear Power Plant Docket No. 50-286 License No. DPR-64 Licensee Event Report 1997-021-01

One Train of Engineered Safeguards Logic Out-of-Service: A Condition Prohibited by Technical Specifications

**REFERENCE:** 

1. NYPA letter (IPN-97-136) to NRC, regarding LER 97-021-00, dated October 6, 1997.

Dear Sir:

The attached Licensee Event Report (LER) 1997-021-01 is a revision to the initial LER submitted in Reference 1. The Abstract and the Event Description are revised to clarify the basis for the decision to deenergize one train of the Engineered Safeguards Logic for replacement of a failed relay. In addition, the Description is revised to correct the stated function of the relay that had failed. The attached meets the reporting criteria defined in 10 CFR 50.73 (a)(2)(i)(B).

The Authority is making no new commitments in this letter.

Very truly yours An

Robert J. Barrett Site Executive Officer Indian Point 3 Nuclear Power Plant

> 7806170167 78060 ADOCK

050

cc: next page

PDR

Docket No. 50-286 IPN-98-066 Page 2 of 2

Mr. Hubert J. Miller Regional Administrator Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406-1415

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

cc:

U.S. Nuclear Regulatory Commission Resident Inspectors' Office Indian Point 3 Nuclear Power Plant