Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 736.8001



Robert J. Barrett Site Executive Officer

June 26, 1998 IPN-98-076

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

SUBJECT:

Indian Point 3 Nuclear Power Plant

Docket No. 50-286 License No. DPR-64

Licensee Event Report # 1998-003-00

Automatic Actuation of Emergency Diesel Generator 32 Due to an Undervoltage Condition on 480 Volt Bus 6A Caused by Personnel Error

Dear Sir:

The attached Licensee Event Report (LER) 1998-003-00 is hereby submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(iv).

The Authority is making no new commitments in this LER.

Robert J. Barrett

Very truly yours,

Site Executive Officer

Indian Point 3 Nuclear Power Plant

cc: See next page

IEZZ

Docket No. 50-286 IPN-98-076 Page 2 of 2

Mr. Hubert J. Miller cc:

Regional Administrator

Region I

U. S. Nuclear Regulatory Commission

475 Allendale Road

King of Prussia, Pennsylvania 19406-1415

INPO Record Center 700 Galleria Parkway

Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission Resident Inspectors' Office

Indian Point 3 Nuclear Power Plant