

Indian Point 3  
Nuclear Power Plant  
P.O. Box 215  
Buchanan, New York 10511  
914 736.8001



Robert J. Barrett  
Site Executive Officer

October 9, 1998  
IPN-98-108

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555


SUBJECT: Indian Point 3 Nuclear Power Plant  
Docket No. 50-286  
License No. DPR-64  
Licensee Event Report # 1998-005-01  
**Operation in A Condition Prohibited by Technical  
Specifications Due to Inoperable City Water Check  
Valves For Which No Allowed Outage Time Is Specified**

Dear Sir:

The attached Licensee Event Report (LER) 1998-005-01 is a supplement that revises LER 1998-005-00 submitted by letter dated September 17, 1998 (IPN-98-099). This supplement provides the results of an assessment of a similar event that occurred on September 11, 1998, and subsequent events during maintenance activities. This supplement is being submitted as required by 10 CFR 50.73. These events are of the type defined in 10 CFR 50.73 (a)(2)(i)(B).

The Authority is making no new commitments in this LER.

Very truly yours,

  
Robert J. Barrett  
Site Executive Officer  
Indian Point 3 Nuclear Power Plant

cc: See next page

9810190051 981009  
PDR ADDCK 05000286  
S PDR

cc: Mr. Hubert J. Miller  
Regional Administrator  
Region I  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, Pennsylvania 19406-1415

INPO Record Center  
700 Galleria Parkway  
Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission  
Resident Inspectors' Office  
Indian Point 3 Nuclear Power Plant