

William J. Cahill, Jr.
Vice President

CENTRAL Files

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

May 17, 1979

Indian Point Station
Docket Nos. 50-3
50-247

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:


This letter is being provided in response to your April 17, 1979 letter which forwarded IE Bulletin No. 79-09. This bulletin requested information regarding GE type AK-2 circuit breakers in safety related systems in the Indian Point Unit Nos. 1 and 2 plants.

With respect to Indian Point Unit No. 1, the unit was shutdown on October 31, 1974 and is presently in the defueled condition awaiting a decision by the Company whether or not to install an emergency core cooling system in accordance with the Commission's regulations. The information requested in the bulletin will be provided if an affirmative decision is reached to return the unit to service.

With respect to Indian Point Unit No. 2, there are no GE type AK-2 circuit breakers in safety related systems.

Should you have additional questions, we would be pleased to discuss them with you.

Very truly yours,


William J. Cahill, Jr.
Vice President

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

Mr. T. Rebelowski, Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, N. Y. 10511

AO2
CCP

7906270 204