John D. O'Toole Vice President

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, NY 10003 Telephone (212) 460-2533

October 22, 1981

Re: Indian Point Unit Nos. 1 and 2 Docket Nos. 50-03, 50-247

Mr. Ronald C. Haynes, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, Pa. 19406

Dear Mr. Haynes:

In accordance with 10 CFR 50.54(q) Con Edison submits herewith three (3) controlled copies of page changes to the Emergency Procedures Document for Indian Point Unit Nos. 1 and 2. These changes do not reduce the effectiveness of the Emergency Plan and the Emergency Plan continues to meet the standards of 50.47(b) and the requirements of Appendix E to 10CFR Part 50.

As recommended in Generic Letter 81-27, "Privacy and Proprietary Materials in Emergency Plans," the following pages, as marked are designated proprietary:

Implementations Procedures(IP)	Pages
IP 1002	IP-1002-1, 2, 3, 4, 5, 7, 8
IP 1007	IP-1007-3
IP 1015	IP-1015-1
IP 1040	IP-1040-3, 4
IP 1043	IP-1043-3

Please sign and return the controlled copy sign off sheet as indicated thereon, to acknowledge receipt of these changes.

Should you or your staff have any questions, please contact us.

Very truly yours, m.L.

8111060262 811102 PDR ADOCK 05000003 F PDR



Attachments

cc: Mr. Harold R. Denton, Director (10 copies)/
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. T. Rebelowski, Senior Resident Inspector U. S. Nuclear Regulatory Commission P. O. Box 38 Buchanan, New York 10511