

William J. Cahill, Jr.
Vice President

RELATED CORRESPONDENCE



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 400-3819

March 29, 1977
Re: Indian Point Unit No. 3
Docket No. 50-286

Director of Nuclear Reactor Regulation
ATTN: Mr. Robert W. Reid, Chief
Operating Reactors Branch No. 4
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555


Dear Mr. Reid:

In accordance with and in satisfaction of the conditions contained in paragraphs 2.C (4) (a), (b) and (d) of Amendment No. 2 to the Indian Point Unit No. 3 Facility Operating License (DPR-64), forwarded herewith please find forty (40) copies of a report prepared by Dames & Moore entitled, "Geotechnical Investigation of Ramapo Fault System in the Region of the Indian Point Generating Station, "Volumes I and II.

The report addresses in detail all of the areas of work contained in Attachment I to the Detailed Work Plan - Part I, "Supplemental Geological Investigations" which was submitted to Mr. Vassallo by letter dated June 1, 1976.

This report, together with the on-site geological report submitted in December 1975, substantiates the conclusion that the Ramapo Fault System is not capable within the meaning of Appendix A to 10CFR Part 100.

Very truly yours,


William J. Cahill, Jr.
Vice President

copy to: George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N.Y. 10019