

NMS:FJM
70-687
50-54

NOV 2 1970

Distribution

PDR
Dockets 70-687 & 50-54, w/rpt
CKBeck, DR, w/o rpt
LDLow, CO, w/o rpt
CO:I, w/rpt
LJohnson, DML, w/rpt
DLCrowson, SMM, w/rpt
GC, w/o rpt
SO-I, w/o rpt
HJMcAlduff, OR, w/rpt
NMS Case File, w/rpt
NMS Reading, w/o rpt
DR Reading, w/o rpt
VJD

Union Carbide Corporation
Nuclear Division, Research Center
Attn: Dr. V. A. Yarborough
Laboratory Director
P. O. Box 324
Tuxedo, New York 10987

Gentlemen:

On August 20 and 21, 1970, the District I Safeguards Office made a safeguards inspection of the special nuclear material possessed by your company pursuant to AEC License Nos. SNM-639 and R-81.

As a result of the inspection, it appears that certain of your activities were not conducted in full compliance with the safeguards requirements contained in Title 10, Code of Federal Regulations, Part 70, in that, contrary to 10 CFR 70.51(b)(1) you did not establish and maintain written material control procedures.

During the closeout meeting with Mr. Gundersen of the District I Safeguards Office you agreed to take corrective action and indicated that full compliance with 10 CFR Part 70 would be achieved by November 30, 1970.

Our District I Safeguards Office will review the corrective action you have taken during their next visit to your facility.

Sincerely,

151

C. D. W. Thornton, Director
Division of Nuclear Materials
Safeguards

OFFICE >	NMS	NMS	NMS			
SURNAME >	FJMiraglia; kb	VJD'Anico	CDWThornton			
DATE >	10/28/70	10/ /70	10/ /70			