RADIATION WORK PERMIT
FACILITY: OC 1 YEAR: 09 RWP NUMBER: 00054 REVISION: 00 TYPE: SPC
LOCATION: CWST CAA ELEVATION: ROOM: AREA: TITLE: CONDENSATE STORAGE TANK- CLEAN, DESLUDGE AND INSPECT CST INTERNALS
INITIATED: 03/20/09 SCHEDULED START: 05/06/09 EXPECTED COMPLETE: 01/01/10 ALARA CATEGORY : 0
PROTECTIVE CLOTHING AND RESPIRATORY PROTECTION REQUIREMENTS
DOSIMETRY REQUIREMENTS
EXTREMITY - HANDS : MULTIPLE DOSIMETRY: ION CHAMBER ALARMING DOSIMETER: Y SET TO ALARM AT: 80 MREM OR AT: 400 MREM/HR
ADMINISTRATIVE / EXPOSURE CONTROL REQUIREMENTS
MINIMUM TEDE BALANCE OF PRE-JOB MEETING REQUIRED : <u>200</u> MREM REQUIRED FOR ENTRY WORK ORDER NUMBER REQUIRED : <u>Y</u> N SIGNATURE CHECK AT SIGN-IN: <u>Y</u>
HEALTH PHYSICS COVERAGE AND MONITORING PERIOD
SURVEY FREQ: <u>1</u> <u>ROUTINE SURVE</u> REQD-IF: BREACH OF SYSTEM HP COVERAGE: POSITIVE
SPECIAL INSTRUCTIONS / REMARKS
CONDENSATE STORAGE TANK- CLEAN, DESLUDGE AND INSPECT CST INTERNALS. * ALARA PLAN# 2009-054, ALL PERSONNEL TO READ AND COMPLY WITH ALARA PLAN. * ALL PERSONNEL TO READ AND COMPLY WITH SAFETY PLAN AND RP-AA-461. * KNOWLEDGE OF RAD CONDITIONS REQ'D PRIOR TO ENTRY INTO RCA WYOUT RPT ESCORT. * CONTAINMENT DEVICE WHEN REMOVING MANWAY AND WHERE POTENTIAL FOR LEAKS EXIST * SURVEY REQUIRED AT SYSTEM OPENING, AT UNDERWATER DIVE LOCATIONS, ON SLUDGE DRUMS AND PER RP.
 AIR SAMPLING PER RP-TO INCLUDE AIR SAMPLE OUTSIDE TANK WHEN MANWAY IS OPEN. * WORKERS SHALL WEAR DOSIMETRY SO THEIR EXPOSURE CAN BE MONITORED IN ANY RCA. * PC REQUIREMENTS PER RADIOLOGICAL POSTINGS OR PER RP. * TENT (ENCLOSURE) SHALL BE CONSTRUCTED AT TANK OPENING AS PER ALARA PLAN. * SAFETY REQUIREMENTS PER NRP & CONFINED SPACE PERMIT. (SPECIAL INSTRUCTIONS ARE CONTINUED ON NEXT PAGE)
APPROVALS / TERMINATION
NameDateSignaturesPREPARED BY :RAYMENT, J03/20/09WORK SUPERVISOR:HAWKINS, MIKE05/06/09HP SUPERVISOR :HEFFNER, ROBERT05/06/09TERMINATED BY :POST JOB REVIEW:

"

RADIATION WORK PERMIT
FACILITY: <u>OC 1</u> YEAR: <u>09</u> RWP NUMBER: <u>00054</u> REVISION: <u>00</u> TYPE: <u>SPC</u>
LOCATION: CWST CAA ELEVATION: ROOM: AREA: TITLE: CONDENSATE STORAGE TANK- CLEAN, DESLUDGE AND 'INSPECT CST INTERNALS
SPECIAL INSTRUCTIONS / REMARKS
* WORKERS EXITING CST RCA ARE TO GO TO FRISK HANDS & FEET AND PROCEED TO NEAREST PCM/PM7 FOR MONITORING.
* OE-JUST-IN-TIME OPERATING EXPERIENCE(OE-OE 8317,3302,&SER 36-85).

TASK NBR DESCRIPTION

100

HP - OTHER

J

**** *** END OF WORK PERMIT REPORT ***