Subject: tside of Scope	New items 10/7
itside of Scope	
new steam general evidence that the control of the	iscovered a 1/2 inch crack in containment concrete during work on containment to install itors (plant is shutdown for SG replacement). Bruce Mallett indicates that there is some crack may be all the way around the containment circumference (360 crack) and there is neern. As it happens, the Chairman is scheduled to visit Crystal R. this Friday.
utside of Scope	

