

U.S. NUCLEAR REGULATORY COMMISSION TELEPHONE CONVERSATION RECORD		Conversation Date: March 2005	
		Time: 10:00 am	
Mail Control No.:	License No.:	Docket No.:	
	NR-688-D-101-E (SSD)		
Licensee/Applicant Participant(s):	Organization:	Telephone No.:	
Terry Garland Manager, D&A Project Development	Kidde Fenwal	508-881-2000 (ext. 2364)	
Person(s) Calling: MSIB: Jonathan Rivera, Dr. John Jankovich			
Subject: Conference call to go over issues to address in email dated 3/18/05, and answer any questions from Kidde Fenwal.			
<p>Summary:</p> <p>MSIB participants explained the Deficiency Issues to Address / Clarifications Needed outlined in the attachment to the email dated 3/18/05.</p> <p>In regards to Item No. 3 in this attachment, Mr. Garland explained that the detector assembly is soldered onto the PC Board. Un-soldering would need to be applied to take the assembly off and therefore gain access to the source.</p> <p>Item No. 5 in the email attachment was disregarded. Quality Control and Quality Assurance was addressed on the second page of the application, dated September 17, 2004,, under Item No. 10.7, where it is stated that there is no change from the current units.</p> <p>Terry Garland will provide an email response to all the issues.</p>			
Action Required/Taken:			
Prepared By: Jonathan Rivera 		Date: March 29, 2005	

5-175