


From: Wiebe, Joel
Sent: Tuesday, March 30, 2010 3:16 PM
To: Wiebe, Joel
Cc: Raghavan, Rags; Milano, Patrick; Lamb, John; WBN2HearingFile Resource
Subject: Safety Evaluation Input for Section 3.13, "Threaded Fasteners"
Attachments: Joel S Wiebe.vcf

SSER Supplement 21 to NUREG-0847, Section 1.7, identified Section 3.13.0, "Threaded Fasteners," as an issue, but did not list the issue status. Bulletin 82-002, "Degradation of Threaded Fasteners in the Reactor Coolant Pressure Boundary of PWR Plants," addressed threaded fasteners. In TVA's letter dated March 20, 2008, TVA committed to implement Bulletin 82-02 in Unit 2 with the same approach as Unit 1. NRC inspection report 50-390/85-08 and 50-391/85-08 documented receipt and review of TVA's February 6, 1985, letter responding to Bulletin 82-02 and closed Bulletin 82-02 based upon the response and the inspector verification of TVA actions.

The staff considers the approach for addressing this issue to be acceptable based upon TVA's commitment to implement Bulletin 82-02 for Unit 2 with the same approach as Unit 1.



E-mail Properties

Mail Envelope Properties (F371D08C516DE74F81193E6D891DC4AF304C1706AB)

Subject: Safety Evaluation Input for Section 3.13, "Threaded Fasteners"
Sent Date: 3/30/2010 3:15:39 PM
Received Date: 3/30/2010 3:15:00 PM
From: Wiebe, Joel

Created By: Joel.Wiebe@nrc.gov

Recipients:

Joel.Wiebe@nrc.gov (Wiebe, Joel)
Tracking Status: None
Rags.Raghavan@nrc.gov (Raghavan, Rags)
Tracking Status: None
Patrick.Milano@nrc.gov (Milano, Patrick)
Tracking Status: None

John.Lamb@nrc.gov (Lamb, John)
Tracking Status: None
WBN2HearingFile.Resource@nrc.gov (WBN2HearingFile Resource)
Tracking Status: None

Post Office:
HQCLSTR02.nrc.gov

Files	Size	Date & Time
MESSAGE	27785	3/30/2010
Joel S Wiebe.vcf	9947	
image001.jpg	11520	

Options

Expiration Date:
Priority: olImportanceNormal
ReplyRequested: False
Return Notification: False

Sensitivity: olNormal
Recipients received: