

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT TYPE ALL REQUIRED INFORMATION)

01 NYIP S 2 00-00000-00 34 1111 4 5

01 REPORT SOURCE L 05 000247 7 072878 8 082278 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 While in the hot shutdown condition, the main steam isolation valve
03 (MS-1) for Loop 23 failed to completely close during the process of
04 isolating the secondary plant for maintenance. All other MSIV's
05 closed as required. This event is reportable under the provisions of
06 Technical Specification 3.4.A(5).

09 SYSTEM CODE HB 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE VALV EX 14 COMP. SUBCODE C 15 VALVE SUBCODE D 16
17 LER-RO REPORT NUMBER 78 21 22 SEQUENTIAL REPORT NO. 021 24 26 OCCURRENCE CODE 03 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32 33 ACTION TAKEN E 18 34 FUTURE ACTION Z 19 35 EFFECT ON PLANT Z 20 36 SHUTDOWN METHOD Z 21 37 HOURS 0000 40 ATTACHMENT SUBMITTED N 23 41 NPRD-4 FORM SUB. N 24 42 PRIME COMP. SUPPLIER N 25 43 COMPONENT MANUFACTURER A585 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 A 28-inch Atwood and Morrill Co. valve, Mark No. 28XP36, (Dwg. No.
11 20728-H) failed to fully close because its stem packing restricted valve
12 motion. The packing gland was subsequently adjusted, and the valve was
13 tested several times to verify its closure within the time limit of
14 Tech. Spec. 3.4.A(5).

15 FACILITY STATUS G 28 29 % POWER 000 30 OTHER STATUS NA 31 METHOD OF DISCOVERY A 32 DISCOVERY DESCRIPTION Operator Observation

16 ACTIVITY CONTENT Z 33 34 RELEASED OF RELEASE NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

DUP OF 7809050007

John M. Makepeace

NRC USE ONLY

914-739-8823

1
William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

RE: Indian Point Units 1,2&3
Docket Nos. ~~50-3~~, 50-247 &
~~50-286~~
LER-78-020/04T-0

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA. 19406

Dear Mr. Grier

The attached Licensee Event Report LER-70-020/04T-0 is hereby submitted in accordance with the requirements of Section 5.6.2.2 of the Environmental Technical Specification Requirements (ETSR). The event is of the type described in ETSR Section 5.6.2.2.a.

An anomolous measurement report was initially submitted on June 9, 1978 without the LER. That report is now resubmitted as an attachment to this LER to comply with present documentation requirements.

Three copies of this letter and attachment are enclosed as required.

Very truly yours



enc.

CC: Mr. Edson G. Gase, Deputy Director
Office of Nuclear Reactor Regulation
c/o Distribution Services Branch, DDC,ADM
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Copy HQ 8-14-78

003
SE
11
7906040 284 S

