


NRC FORM 591M PART 1 <small>(4-2008) 10 CFR 2.201</small>		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: GeoTek, Inc 320 East Corporate Drive Suite 300 Meridian, Idaho 83642 REPORT NO: 2010-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
3. DOCKET NUMBER 030-87200-36587	4. LICENSE NUMBER 11-27776-01	5. DATE OF INSPECTION March 15-30, 2010	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:			
<input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.			
<input type="checkbox"/> 2. Previous violation(s) closed.			
<input checked="" type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.			
<input checked="" type="checkbox"/> Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):			
A. Failure to do annual audits pursuant 10 CFR 20.1101 (c) from 2005 to 2009. License conducted an audit on September 18, 2009 and will incorporate the requirement into its radiation safety program.			
B. Failure to provide dosimetry for second, third and fourth quarters 2009. License resumed dosimetry in the 1 st quarter of 2010 and will send future shipments to vendor by certified mail.			
<input checked="" type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.			
A. Failure to conduct hazmat refresher training every 3 years pursuant to 49 CFR 49.172.704(c)(2). 2 gauges users did not have the required refresher training. Both users received training on March 23, 2010.			
B. Failure to perform a public dose assessment pursuant to 10 CFR 20.1301. License conducted the required survey on March 16, 2010 and additionally ordered area monitor TLDs from the vendor for placement in unrestricted areas to provide dose assessment for members of the general public.			
Licensee's Statement of Corrective Actions for Item 4, above.			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	David Waite		3/30/2010
NRC INSPECTOR	Lawrence Donovan		3/30/2010

NRC FORM 591M PART 1 (Rev. by RIV 3/09)

S:\DNMS\IN\MB\BRANCH FORMS\591M FORMS\Part1 Publicly Available.doc

Non-Public Sensitive - Security-Related

Public Non-Sensitive

ADAMS # ML10100486
 Template _____
 Date 4/20/10 OCC'd by ST

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: GeoTek, Inc 320 East Corporate Drive Suite 300 Meridian, Idaho 83642 REPORT NO: 2010-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125
3. DOCKET NUMBER 030- 37206 36587	4. LICENSE NUMBER 11-27776-01	5. DATE OF INSPECTION March 15-30, 2010

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
 - 2. Previous violation(s) closed.
 - 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- A. Failure to do annual audits pursuant 10 CFR 20.1101 (c) from 2005 to 2009. License conducted an audit on September 18, 2009 and will incorporate the requirement into its radiation safety program.
 - B. Failure to provide dosimetry for second, third and fourth quarters 2009. License resumed dosimetry in the 1st quarter of 2010 and will send future shipments to vendor by certified mail.
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
- A. Failure to conduct hazmat refresher training every 3 years pursuant to 49 CFR 49.172.704(c)(2) . 2 gauges users did not have the required refresher training. Both users received training on March 23, 2010.
 - B. Failure to perform a public dose assessment pursuant to 10 CFR 20.1301. License conducted the required survey on March 16, 2010 and additionally ordered area monitor TLDs from the vendor for placement in unrestricted areas to provide dose assessment for members of the general public.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Lawrence Donovan	<i>Lawrence Donovan</i>	3/30/2010

TRANSMISSION VERIFICATION REPORT

TIME : 03/30/2010 10:05
NAME : USNRC RIV
FAX : 8178608263
TEL :
SER.# : BROL2J847623

DATE, TIME	03/30 10:05
FAX NO./NAME	712088887924
DURATION	00:00:29
PAGE(S)	02
RESULT	COVERPAGE
MODE	OK
	STANDARD
	ECM




UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

DIVISION OF NUCLEAR MATERIALS SAFETY

DATE / TIME:

3/30/10

PRIORITY:
IMMEDIATELY
1-HOUR
2-4 HOUR



MESSAGE TO:

DAVID WAITE, Geotek

MESSAGE FROM:

Larry DUNDUAN, NRC

NUMBER OF PAGES

PLUS TRANSMITTAL SHEET

TELECOPY NUMBER:

208-888-7924 VERIFICATION NUMBER: _____

CONTACT:

SPECIAL INSTRUCTIONS / ATTACHMENTS:

Sign, date & return by fax 817-860-8263