

Franke, Mark

From: Chou, Rich *RS*
Sent: Friday, October 16, 2009 12:42 PM
To: Zeiler, John
Cc: McCoy, Gerald; Wright, Donna; Martin, Robert; Franke, Mark; Williams, Robert; Chou, Rich
Subject: RE: Questions Re Summer Past Containment Concrete Work Activities

John:

Thank you very much for your importance information.

From: Zeller, John *RS*
Sent: Friday, October 16, 2009 11:58 AM
To: Chou, Rich
Cc: McCoy, Gerald; Wright, Donna; Martin, Robert
Subject: Questions Re Summer Past Containment Concrete Work Activities

Rich,

As discussed over the phone earlier, the licensee's SG replacement was conducted in 1994; during which time they brought them in through the equipment hatch and did not have to make any containment cutting to get them in.

The licensee told me (Jason Weathersby @ 803-345-4914), that they have not found any records where there was any activity where the containment concrete has been cut into or repaired that may have afforded an opportunity to look for any potential degradations similar to Crystal River issues over the life of the plant. Likewise they have already been reviewing their previous records of containment inspection results and have not identified where any past problems have been noted above the expected amount of concrete surface imperfections.

As an added note, Dale Krause is their civil engineering expert, and he is actually on the present Crystal River licensee inspection root cause team. From his reports back to the site, he does not expect Summer to have any similar problems based on his knowledge of the concern, mainly because Summer was constructed 10 years after Crystal River, with higher concrete design specification standards, especially in the area of radial structural supports in the specific area that Crystal River is seeing problems in.

John Zeiler
Senior Resident Inspector
Virgil C. Summer Nuclear Station
Region II, USNRC
803-345-5683 (office)
(b)(6) cell)

E44

Information in this record was deleted in
accordance with the Freedom of Information Act.
Exemptions b
FOI/PA 2010-0116

D-4