NRC FORM 591M PART 1 (4-2008)		1	U.S. NUCLEAR REGULATO	ORY COMMISSION
10 CFR 2.201	SPECTION REPORT	AND COMPLIANCE	INSPECTION	
LICENSEE/LOCATION INSPECTED: Chevron Mining, Inc- Kemmerer Mine P.O. Box 950 Kemmerer, Wyoming 83101 PERCENTAGE		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125		
REPORT NO: 2010-001 3. DOCKET NUMBER 4. LICENSE NUMBER			5. DATE OF INSPECTIO	iN
030-33273	49-17605-04		April 21, 2010	
LICENSEE: The inspection was an examination of the active Regulatory Commission (NRC) rules and regulatory procedures and representative records, interviolation. X 1. Based on the inspection findings,	lations and the conditions of ews with personnel, and ob	of your license. The inspection of your license. The inspector.	on consisted of selective ex	aminations of
Previous violation(s) closed. The violations(s), specifically described identified, non-repetitive, and corrediscretion, were satisfied.	ribed to you by the inspecto active action was or is being	or as non-cited violations, ar g taken, and the remaining c	e not being cited because the riteria in the NRC Enforcement	ney were self- ent Policy to exercise
4. During this inspection certain of your cited. This form is a NOTICE OF N	our activities, as described l	below and/or attached, were subject to posting in accord	in violation of NRC requirer ance with 10 CFR 19.11.	ments and are being
		ective Actions for Ite		
I hereby state that, within 30 days, the actio corrective actions is made in accordance with date when full compliance will be achieved Title Police State of the complex	the requirements of 10 CF	R 2.201 (corrective steps alnown and Received Received to NRC)	ready taken, corrective steps	s which will be taken, 🛛
REPRESENTATIVE				
NRC INSPECTOR Lawrer	ice Donovan	/	// RA //	April 21, 2010
NRC FORM 591M PART 1 (Rev. by RIV 3/09) Non-Public Sensitive – S	S:\ security-Related	DNMS\!NMIB\BRANCH FO		rublicly Available.doc