### Robinson Nuclear Plant March 28, 2010 Event Review



#### Nuclear Regulatory Commission May 12, 2010





### Introduction

- Participants
- Purpose
  - Event overview
  - Event Review Team
  - Corrective actions
  - Lessons being shared with fleet/industry
  - Summary





#### Tom Natale Event Review Team Member





### • Event Initiated at 1852

- Procedure flow
- Equipment challenges
- Operator response/actions
- Timeline Review





4KV SYSTEM LOADS KVAC-FIGURE-5

- 4160 V BUS NO. 1 REACTOR COOLANT PUMP "A" 52/1 MAIN FEEDWATER PUMP "A" 52/3 CIRCULATING WATER PUMP "A" 52/2 CONDENSATE PUMP "A" 52/6 HEATER DRAIN PUMP "A" 52/5 STATION SERVICE TRANSFORMER 2B 52/4 BUS 1 AND 2 TIE BREAKER 52/10
- 4160 V BUS NO. 2 REACTOR COOLANT PUMP "C" 52/14 STATION SERVICE TRANSFORMER 2A and 2F 52/13
- 4160 V BUS NO. 3 STATION SERVICE TRANSFORMER 2C and 2G 52/15
- 4160 V BUS NO. 4 REACTOR COOLANT PUMP "B" 52/27 MAIN FEEDWATER PUMP "B" 52/26 CIRCULATING WATER PUMP "B" 52/23 CONDENSATE PUMP "B" 52/22 HEATER DRAIN PUMP "B" 52/25 STATION SERVICE TRANSFORMER 2D 52/28 BUS 3 AND 4 TIE BREAKER 52/19 4160 V BUS 5 52/24

4160 V BUS NO. 5 CIRCULATING WATER PUMP "C" 52/33 STATION SERVICE TRANSFORMER 2E 52/32













## **Event Review Team**

Bob Duncan Team Lead





### **Event Review**

- Event Response Team Makeup:
  - Bob Duncan (VP NOD) Team Lead
  - Mark Rigsby (Manager, Site Support CR3) Organizational Effectiveness Lead
  - George Attarian (Manager, Major Projects) Technical Engineering Lead





#### **Event Review**







### **Event Review**

- External Assistance
  - Fire Forensics Richard Hanson and Associates
  - Fire Modeling Hughes Associates
  - Breakers/Switchgear Homewood Products, Westinghouse, Areva
  - Reactor Coolant Pump parameters Westinghouse, Areva
  - Cables EPRI
- Investigation Methods





## **Investigation Results: Operations**

Monitoring of Critical Safety Functions

- Sub-criticality
- Core cooling
- Heat sink
- RCS integrity
- RCS inventory
- Containment integrity





## **Investigation Results: Equipment**

- Cable Modifications (1986)
  - Cable specifications
  - Cable installation/support
- Breaker 52/24
  - Control power fuse
  - Knowledge gap pertaining to control power circuit
  - Evaluation of work order





## **Investigation Results: Equipment**

### VCT – RWST Auto Swap

- Comparator jumper configuration
- Post-maintenance testing
- Instrument Bus 3





## **Investigation Results: Operations**

- Command and Control/Communication Challenges
  - Safety injection anticipation
  - RCS cooldown mitigation
  - Procedure utilization (APPs, AOP closure)
  - Status briefs/crew updates
  - MCR distraction management
  - Alert declaration





## **Investigation Results: Operations**

- Additional Insights
  - Path 1 & foldout strategy
  - AOP-041
- Monitoring of Key Parameters
  - RCP seal cooling
    - FCV-626 closure
    - Volume control tank level
    - Charging pump suction swap-over
  - RCS temperature and pressure





## **Investigation Results: Organization**

- Operator Training
- Site Event Response
- Organizational Effectiveness
- Operating Experience





# Robinson Nuclear Plant March 28, 2010 Event Review

## **Corrective Actions**





# Equipment

### Warren Farmer Manager RNP Engineering





## **Corrective Actions: Equipment**

- Inspect RCP Seals (R)
- Inspect B Charging Pump (R)
- Replace UAT (R)
- Health Assessment of SUT (R)
- 4 KV Cable Extent of Condition Inspection (R)
- Fleet MV Cable Review





## **Corrective Actions: Equipment**

- FCV-626 RCP Thermal Barrier Isolation Modification Implementation (R)
- Implement Modification for Battery Charger Autorestart (R)
- Troubleshooting Instrument Bus 3 (R)
- Review and Conduct as Necessary PMTs on Past NUS Comparator Replacements (R)
- Develop Fleet Standard for PMT on Protection and Control Circuits
- Develop Configuration Document for NUS Modules





## Operations

#### Scott Saunders Plant General Manager





## **Corrective Actions: Operations**

- Leadership Assessment (R)
- Crew Reconstitution (R)
- Training Actions (R)
- Command and Control (R)
- Key Parameter Monitoring (R)
- Fleet PGM Challenge of Start-up (R)





## Procedures

Scott Saunders Plant General Manager





### **Corrective Actions: Procedures**

- CAPR to revise work management process to provide specific guidance for impact reviews of new Work Requests including:
  - Guidance for Operations impact reviews
  - Guidance for the Work Order prioritization
  - Clarification of expectations for what "Validation" of a deficiency entails
  - Guidance for conversion of Work Requests to Work Orders





### **Corrective Actions: Procedures**

- EOP Foldout revision (R)
- AOP-041 Strategy (R)
- GP-004 Post-trip stabilization (R)
- AOP-024 Loss of instrument bus





# Organization

Eric McCartney Vice-President





## **Corrective Actions: Organization**

- Review of Outstanding WR/WO (R)
  - Priority
  - Scope
  - Risk
- Training
  - Breaker control power
  - Breaker indicating lights





### **Corrective Actions: Organization**

- Performance Improvement
  - Formalize follow up to Oversight and Fleet identified performance issues
  - Implement CR3 Performance Improvement Model across the fleet
- Equipment Performance
  - Case study employee and leadership training
  - Revise PMT strategy for risk informed application
- Organizational Response
  - Revise event response procedures to provide for a technical support response for both forced outage and non-forced outage events





# **Plant Design Changes**

#### Warren Farmer RNP Manager Engineering

#### Bob Rishel Manager Probabilistic Safety Assessment





## **Plant Design Changes**

### Event Related Risk Profile Improvements

- Battery Charger Auto-load Modification (R)
- FCV-626 Power Dependency Modification (R)
- 4 KV Ground Detection Seal-In Circuit (R)
- Dedicated Shutdown Diesel Auto-Start
- ERFIS Seal Flow Annunciation
- 2<sup>nd</sup> Start Up Transformer
- Independent Emergency Power for Deep-Well Pumps





### **Plant Design Changes**

- Additional Modifications for Overall Risk Profile Improvement
  - SW Cross-Connect Isolation Valve (R)
  - 4<sup>th</sup> AFW Pump





# Fleet & Industry Lessons Learned

#### Chris Burton Vice-President – Harris Plant

Wayne Gurganious Director Fleet Training





## **Fleet & Industry Lessons Learned**

### Operations

- Stronger pursuit of abnormal plant conditions
- Electrical systems fundamental knowledge
- Crew composition considerations
- Training
  - Scenario design
  - Evaluation standards
- Procedures
  - EOP and AOP improvements





## **Operating Experience**

- PWROG
- INPO
  - Issued Significant Event Notification
  - On-site during investigation
  - Post to Nuclear Network
- Chief Nuclear Officer
  - Shared insights with peers at INPO Executive Advisory Group conference





## Summary

Eric McCartney Vice-President

#### Jim Scarola Sr. Vice-President and Chief Nuclear Officer





# Appendices





## Seal Injection / Charging / VCT Level







### **RCP Labyrinth Seal dP**





### **RCP Bearing Water Temperature**







### **RCP Seal Leakoff Temperature**







### **RCS** Temperature and Pressure

