





References 2.4.11-7, 2.4.11-10

PSEG Power, LLC
PSEG Site ESPA
Part 2, Site Safety Analysis Report

Negative Surge Caused by
Hurricane Gloria

FIGURE 2.4.11-4

Rev. 0