

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: MYERS ENGINEERING 1033 CRAWFORD STREET TERRE HAUTE, IN 47807 REPORT NUMBER(S) 2010/001	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351
--	--

3. DOCKET NUMBER(S) 030-37796	4. LICENSEE NUMBER(S) 13-32705-01	5. DATE(S) OF INSPECTION 5/11/10
----------------------------------	--------------------------------------	-------------------------------------

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:


- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Edward Kulzer		5/11/10

JKS

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Myers Engineering, Inc. REPORT NUMBER(S) 2010-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-37796	4. LICENSE NUMBER(S) 13-32705-01	5. DATE(S) OF INSPECTION May11, 2010	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Robin Myers	4. TELEPHONE NUMBER 812-238-9731
----------------------------	------------------	------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: May. 2011

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is a private engineering/consulting company located in Terre Haute, Indiana. They perform soil density in the Terre Haute, Indiana area. The licensee has no gauges. The licensee rents gauges as needed from Humbolt. When the licensee rents the gauges, the gauges are stored at the temporary job site. The licensee has four authorized gauge users who have completed the manufacturer's training. The licensee does not perform any service or maintenance activities on the gauges.

Performance Observations

The licensee had no gauges at the time of this inspection, but is planning a project for next spring that will include gauge rental. The licensee had let its NRC license lapse and was placed in an initial inspection priority. They are still due for an inspection and will have the gauge next spring.