

Pressley, Lundy

From: Nielsen, Adam *RA*
Sent: Monday, May 03, 2010 8:55 AM
To: Morris, Eddie; Niebaum, Phillip
Cc: Bonser, Brian
Subject: FW: Update on Hatch Pullbox

FYI

-----Original Message-----

From: Lloyd, Mary B. [mailto:MBLLOYD@southernco.com]
Sent: Friday, April 30, 2010 10:36 AM
To: Jim Hardeman
Cc: Coleman, Violet M.; Gilbert, Don M.; Moorer, Tom C.
Subject: Update on Hatch Pullbox

The plant performed an integrity test on the CST-2 transfer pump moat and found that there were 2 small holes (breaks in the moat) where the water from the moat was going to directly to the pullbox (via ducts which connect the moat to the pullbox). As we previously discussed, approximately 325 gallons of water were pumped out of the pullbox and disposed of as radwaste. At this point, the plant has no indication that the moat/pullbox contents have reached groundwater. The nearest monitoring well does not show a significant increase in tritium activity. An update will be provided should any other pertinent info become available. Let me know if you have any questions.

Thank you!

Mary Beth Lloyd
Southern Nuclear Operating Company
Environmental Affairs
8-992-5062 / 205-992-5062
mbllloyd@southernco.com

J-29