

A unit of American Electric Power

Indiana Michigan Power One Cook Place Bridgman, MI 49106 IndianaMichiganPower.com

AEP-NRC-2010-56 10 CFR 50.55a

July 1, 2010

Docket No.: 50-315

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Donald C. Cook Nuclear Plant Unit 1 OWNER'S ACTIVITY REPORT FOR INSERVICE INSPECTION ACTIVITIES

This letter provides Form OAR-1, Owner's Activity Report, for inservice inspection activities performed at Donald C. Cook Nuclear Plant Unit 1, National Board State of Michigan Number 20761 (Mich. M-096762-M), located in Bridgman, Michigan, for the period of April 29, 2008 to April 9, 2010. The plant is owned by Indiana Michigan Power Company, P.O. Box 60, Fort Wayne, Indiana, 46801. This summary report satisfies the reporting requirements described in American Society of Mechanical Engineers (ASME) Code Case N-532-4, Repair/Replacement Activity Documentation Requirements and Inservice Summary Report Preparation and Submission, Section XI, Division 1.

The Authorized Code Inspector is Mr. R. K. Schenck, who is employed by One CIS Insurance Co., of Boston, Massachusetts.

There are no new or revised commitments in this letter. Should you have any questions, please contact Mr. Michael K. Scarpello., Regulatory Affairs Manager, at (269) 466-2649.

Sincerely,

Michael H. Carlson Vice President – Site Support Services

MCS/jmr

Attachment: D.C. Cook Nuclear Plant, Form OAR-1 Owner's Activity Report

U. S. Nuclear Regulatory Commission Page 2

c: R. Aben - DLEG/BCCFS/BD K. D. Curry - AEP Ft. Wayne, w/o attachment J. T. King – MPSC, w/o attachment MDEQ – WHMD/RPS, w/o attachment NRC Resident Inspector M. A. Satorius – NRC Region III P.S. Tam – NRC Washington DC U. S. Nuclear Regulatory Commission Page 3

AEP-NRC-2010-56

bc: M. H. Carlson J. M. Fitchuk J. P. Gebbie C. R. Lane Q. S. Lies J. E. Newmiller J. M. Petro, Jr. R. G. Pickard L. J. Weber

190 - 1

D.C. Cook Nuclear Plant Form OAR-1 Owner's Activity Report

Report Number	1-2010-3-3-02						
Plant	ant Donald C. Cook						
			(Name and Address of Plant)				
Unit No. 1	· ·	Commercial Service Date	8/23/1975 Refueling Outage No. U1C23				
(if	applicable)	SUPPO	 DRTS				
Current Inspection Interva	1	3rd for Components and Supprt	s (C&S) and 2nd for Containment ISI (CISI) Program				
Ourse at lass stice Devied		RKS REU 6	්යුදු/බව/උ (1st, 2nd, 3rd, 4th, other)				
Current Inspection Period	- -	3rd for C&S and 1st for CISI	(1st, 2nd, 3rd)				
		- -					
Edition and Addenda of S	ection XI applicabl	e to the inspection plans	1989 Edition/No Addenda for C&S	·			
Date and Revision of insp	ection plans	2/19/2010, Revision 8 for	2004 Edition for CISI				
		11/10/2009, Revision 0 fo					
Edition and Addenda of Security Edition and Addenda is th			, if different than the inspection plans				
Code Cases used:		-1, N-481, N-491-2, N-498-4, N-5 N-722, N-729-1 for C&S and N-6	09, N-521, N-524, N-532-4, N-533, N-616, N-623, N-627, N 549 for CISI	1-652-1,			
· · · .			(If applicable)	······································			
		CERTIFICATE O	F CONFORMANCE				
Signed	ts of Section XI. Hall 13	PROGRAM Duck AL R((Refueling On B. RCKARD Date 6/17/2010	utage Number)			
· · ·							
1, the undersigned, holding	a valid commissi		INSERVICE INSPECTION of Boiler and Pressure Vessel Inspectors and the State or				
Province of Michigan		and employed by One CIS Ins	surance Co. of Boston, MA				
-		wner's ActivityReport, and state eport in accordance with the requ	that, to the best of my knowledge and belief, the Owner has uirements of Section XI.	3			
and evaluation described i	n this report. Furt		warranty, expressed or implied, concerning the repair/replac or his employer shall be liable in any manner for any person				
	1						
1 Coul KS U		Commissions Michigan 30	00959, NB 11412, Endorsements; A,N & I				
Rever K. Sch	en cu	· · · · · · · · · · · · · · · · · · ·	National Board, State, Province, and Endorsements				
	7-2010						

D.C. Cook Nuclear Plant

Table 1

Items with flaws or relevant conditions that required evaluation for continued service

Examination Category	ltem Number	Item Description	Evaluation Description
B-N-2	B13.60	Interior Attachments Beyond Beltline Region	AR 2010-1804-18, Unit 1 Reactor Vessel Core Support Lug Bolting Anomalies
F-A	F1.10A	Class 1 Piping Supports	1-GCS-R-540 AWAY# 2010-0733, Identified discrepancies during visual examination
F-A	F1.30A	Class 3 Piping Supports	1-GCCW-R-60 eSAT# 10042044, Identified discrepancies during visual examination
F-A	F1.30A	Class 3 Piping Supports	1-GCCW-R-22 eSAT# 10042048, Identified discrepancies during visual examination
F-A	F1.30A	Class 3 Piping Supports	1-GCCW-L-236 eSAT# 10013050, Identified discrepancies during visual examination
F-A	F1.30A	Class 3 Piping Supports	1-GFW-R-179 eSAT# 10013056, Identified discrepancies during visual examination
F-A	F1.30WB	Class 3 Piping Supports	1-AFW-L-915, AR 00861050-01, NCE for broken lug on piping, found outside normal ISI examination

D.C. Cook Nuclear Plant

Table 2

Abstract of repair/replacement activities required for continued service

ч. ч. н.	Code Class		Item Description	Description of Work	Date Complete	Repair / Replacement Plan Number
,		· . ·				
	1		Class 1 Piping Support	Replace Bolt	3/21/2010	55359762-01