

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

*EMERY SAPP & SONS, INC
2602 N STADIUM BLVD
COLUMBIA, MO 65202
REPORT NUMBER(S) 2010/001*

2. NRC/REGIONAL OFFICE

**U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Suite 210
Lisle, Illinois 60532-4351**

3. DOCKET NUMBER(S)

030-38051

4. LICENSEE NUMBER(S)

24-32751-01

5. DATE(S) OF INSPECTION

7/7/10

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Edward Kulzer	<i>E. I. Kulzer</i>	<i>7/7/10</i>

226

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Emory Sapp & Sons, Inc., REPORT NUMBER(S) 2010-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-38051	4. LICENSE NUMBER(S) 24-32751-01	5. DATE(S) OF INSPECTION July 7, 2010	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Jeff Stephens	4. TELEPHONE NUMBER 573-445-8331
----------------------------	------------------	--------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: July 2015
 Field Office _____
 Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is a private engineering/consulting company that stored its gauge at its facility in Columbia, Missouri. They perform soil density in the Columbia, Missouri area. The licensee has one Troxler gauge. At the time of the inspection; the licensee has one authorized gauge user who had completed training. The licensee does not perform any service or maintenance activities on the gauges.

Performance Observations

There were no temporary job sites at the time of the inspection. Interviews of licensee personnel indicated an adequate level of knowledge of radiation safety.

Independent demonstrations of how the gauge was transported to temporary job sites in Missouri indicated that there were two locks securing the gauge and gauge case during transport. Personnel were monitored and had minimal exposures. The licensee secures the gauge in covered and locked open bed pick-up truck using two locks and two chains. The gauge case has two locks. All leak tests were current. All records were in order.

225