



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

July 30, 2010

MEMORANDUM TO: Duane White, Health Physicist (MS-8F5)
Radioactive Materials Safety Branch
Division of Materials Safety & State Agreements

FROM: Vivian Campbell, Chief *ADG for*
Nuclear Materials Safety Branch A
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for July 2010. In addition, enclosed are the licensee event report evaluation forms for the events closed in June 2010, detailing Region IV's response to these events.

Enclosures:

1. July 2010 RIV DNMS Licensee
Event Reports Summary Table
2. LER evaluation forms for RIV events
closed in June 2010

Duane White

- 2 -

cc via email w/Enclosure 1:

E. Collins

A. Howell

C. Cain

V. Campbell

J. Whitten


D. Spitzberg

J. Thompson

D. Huntsman [Dante.Huntsman@inl.gov]

LER File

S:\DNMS\INMIB\LERs\2010\07-2010.doc

ADAMS	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> SUNSI Review Complete	Reviewer Initials: JLT
		<input checked="" type="checkbox"/> Publicly Available	<input checked="" type="checkbox"/> Non-sensitive	
		<input type="checkbox"/> Non-publicly Available	<input type="checkbox"/> Sensitive	
KEYWORD: SUNSI Review Complete				
RIV:DNMS/NMSB-A			C:NMSB-A	
JLThompson;dlf			VHCampbell	
7/29/2010 			ADG for	
			7/30/2010	

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - JULY 2010									
ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status	
ML100040500	12/21/09	12/22/09	FMC Corporation	49-04295-01	10 CFR 30.50	Damage to fixed gauge and shutter malfunction	Razo	Open	
45773	3/17/2010	3/17/2010	Accurate NDE and Inspection	150-00017 LA 10207-L01	10 CFR 20.2201	Loss of a 7 curie iridium-192 sealed source while performing radiography	Thompson	Open	
46110	6/24/2010	7/20/2010	Global X-Ray & Testing	17-29308-01	10 CFR 34.101	Radiography source disconnect	Hanson	Open	
ML101800188 ML102110409	5/23/2010	5/28/2010	Pathfinder	17-27623-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed, report attached	
45865 ML102110503	4/20/2010	4/21/2010	Halliburton Energy Services	42-01068-01	10 CFR 20.2201	Loss of nuclear gauges in offshore Federal waters	Hanson	Closed, report attached	
45891 ML102110461	4/26/2010	5/1/2010	Particle Drilling Technologies	150-00042 TX G02344	10 CFR 30.50	Shutter on nuclear gauge stuck open	Razo	Closed, report attached	
45758 ML102110462	3/11/2010	3/11/2010	Bozeman Deaconess Hospital	25-10994-04	10 CFR 20.2201	Loss of a 30millicurie vial of samarium-153	Munoz	Closed, report attached	
ML101680455 ML102110468	5/25/2010	6/8/2010	Acuren USA	42-32443-01	10 CFR 34.101	Radiography source could not be retracted due to kinked guide tube	Hammond	Closed, report attached	
46051 ML102110492	6/29/2010	6/29/2010	Kakivik Asset Management	50-27667-01	10 CFR 30.50	Radiography source could not be retracted to shielded position	Hammond	Closed, report attached	
46052 ML102110499	6/29/2010	6/29/2010	Kakivik Asset Management	50-27667-01	10 CFR 30.50	Radiography source could not be retracted to shielded position	Hammond	Closed, report attached	