

Morrissey, Thomas

From: Chou, Rich *RT*
Sent: Tuesday, October 06, 2009 4:54 PM
To: Franke, Mark
Cc: Carrion, Robert; Blake, Jerome; Plisco, Loren; Sykes, Marvin; Morrissey, Thomas; Reyes, Rogerio; Chou, Rich
Subject: FW: Crystal River U3 Containment cracks
Attachments: Picture 031.JPG; DSC00009.JPG; DSC00011.JPG; DSC00012.JPG; DSC00014 (2).JPG; DSC00015.JPG; DSC00032.JPG; DSC00033.JPG; DSC00051 (2).JPG; Picture 010.JPG; Picture 020.JPG

Mark:

(b)(5)



From: Reyes, Rogerio *VR*
Sent: Tuesday, October 06, 2009 4:18 PM
To: Sykes, Marvin
Cc: Chou, Rich
Subject: Crystal River U3 Containment cracks

EX 5

Marvin and Rich, attached are the pictures of the containment. All four sides of the opening have cracks. As we discussed, the licensee is modifying the base plate for anchor bolting for SG replacement.

J. Rogerio Reyes, P.E.
U.S. Nuclear Regulatory Commission
Resident Inspector
Crystal River Nuclear Power Plant

G-4