

NRC STAFF EXHIBIT LIST

August 13, 2010

Document	Exhibit No.
Safety Evaluation Report Related to the License Renewal of Prairie Island Nuclear Generating Plant, Units 1 and 2 (October 2009)	1
Safety Evaluation Report With Open Items Related to the License Renewal of Prairie Island Nuclear Generating Plant Units 1 and 2 (June 2009)	2
Advisory Committee on Reactor Safeguards Report on Safety Aspects of the License Renewal Application for the Prairie Island Nuclear Generating Plant, Units 1 & 2 (December 10, 2009)	3
NUREG-1800 Standard Review Plan for Review of License Renewal Applications for Nuclear Power Plants (SRP-LR) (September 2005).	4
NUREG-1800 Standard Review Plan for Review of License Renewal Applications for Nuclear Power Plants (SRP-LR) (September 2005) (Excerpt) Corrected	4A
Prairie Island May 20, 2010 Annual Assessment Meeting Slides	5
Inspection Manual Chapter 308 "Reactor Oversight Process (ROP) Basis Document"	6
Inspection Manual Chapter 0308 "Reactor Oversight Process (ROP) Basis Document," Attachment 3 "Significance Determination Process Basis Document"	7
Inspection Manual Chapter 2515 "Light-Water Reactor Inspection Program-Operations Phase"	8
Inspection Manual Chapter 2515 Appendix A, "Risk Informed baseline Inspection Program"	9
Inspection Manual Chapter 305 "Operating Reactor Assessment Program"	10
Inspection Manual Chapter 305 "Operating Reactor Assessment Program" Exhibit 4-Action Matrix	11
Inspection Manual Chapter 609 "Significance Determination Process"	12
Inspection Manual Chapter 0612 "Power Reactor Inspection Reports"	13
Inspection Manual Chapter 0608 "Performance Indicator Program"	14
Inspection Manual Chapter 0307 "Reactor Oversight Process Self-Assessment Program"	15
Inspection Manual Chapter 0307 "Reactor Oversight Process Self-Assessment Program" Appendix A	16
Inspection Manual Chapter 1245 "Qualification Program for Operating Reactor Programs"	17
Inspection Manual Chapter 0313 "Industry Trends Program"	18

Inspection Manual Chapter 0310 “Components Within the Cross Cutting Areas”	19
Inspection Manual Chapter 71003 “Post Approval Site Inspection for License Renewal”	20
Inspection Procedure 71152 “Problem Identification and Resolution”	21
Inspection Procedure 95001 “Inspection for One or Two White Inputs in a Strategic Performance Area”	22
Inspection Procedure 95002 “Inspection for One Degraded Cornerstone or Any Three White Inputs in a Strategic Performance Area”	23
Inspection Procedure 95003 “Supplemental Inspection for Repetitive Degraded Cornerstones, or Multiple Yellow Inputs, or One Red Input”	24
Inspection Procedure Attachment 95003.02 “Guidance for Conducting an Independent NRC Safety Culture Assessment”	25
F.W. Guldenmund, “The Nature of Safety Culture: A Review of Theory and Research” <i>Safety Science</i> 34 (2000) pp. 215-257	26
Kathryn Mearns et al., “Safety climate, Safety Management Practice and Safety Performance in Offshore Environments” <i>Safety Science</i> 41(2003) pp. 641–680	27
Benjamin Schneider et al., “Creating a Climate and Culture for Sustainable Organizational Change” 1996	28
Institute for Nuclear Power Operations “Principles for a Strong Nuclear Safety Culture” November 2004	29
Douglas A. Wiegmann, et al. “A Synthesis of Safety Culture and Safety Climate Research” June 2002	30
Terry L. von Thaden & Alyssa M. Gibbons “The Safety Culture Indicator Scale Measurement System (SCISMS)” July 2008	31
<i>Safety Culture: A Report by the International Nuclear Safety Advisory Group (INSAG). INSAG-4</i> , International Atomic Energy Agency Vienna, Austria 1991	32
<i>Safety Culture: A Report by the International Nuclear Safety Advisory Group (INSAG). INSAG-10</i> , International Atomic Energy Agency Vienna, Austria 1996	33
<i>Management of Operational Safety at Nuclear Power Plants: A Report by the International Nuclear Safety Advisory Group (INSAG), INSAG-13</i> International Atomic Energy Agency Vienna, Austria 1999	34
“Policy Statement on the Conduct of Nuclear Power Plant Operations,” 54 Fed. Reg. 3424 (January 24, 1989)	35
“Freedom of Employees in the Nuclear Industry to Raise Safety Concerns Without Fear of Retaliation,” 61 Fed. Reg. 24336 (May 14, 1996)	36
SRM COMGBJ-08-0001 “A Commission Policy Statement on Safety Culture,” (February 25, 2008)	37

SECY-09-0075 "Safety Culture Policy Statement" (March 18, 2009)	38
SRM-SECY-09-0075 "Safety Culture Policy Statement" (October 16, 2009)	39
"Draft Safety Culture Policy Statement: Request for Public Comments," 74 Fed. Reg. 57525 (November 6, 2009)	40
"Draft Safety Culture Policy Statement: Request for Public Comments; Extension of Comment Period" 75 Fed. Reg. 1656 (January 12, 2010)	41
SRM-SECY-04-0111 "Recommended Staff Actions Regarding Agency Guidance in the Areas of Safety Conscious Work Environment and Safety Culture" (August 30, 2004)	42
SRM-SECY-05-0187 "Status of Safety Culture Initiatives and Schedule for Near-Term Deliverables" (December 21, 2005)	43
Regulatory Information Summary 2006-13, "Information on the Changes to the Reactor Oversight Process to More Fully Address Safety Culture" (July 31, 2006)	44
Palo Verde Nuclear Generating Station NRC Supplemental Inspection 95003 Inspection Report February 1, 2008	45
Prairie Island Nuclear Generating Plant Supplemental Inspection Report 0500282/200911 (October 15, 2009)	46
Prairie Island Nuclear Generating Plant Supplemental Inspection Report 0500282(306)/2009015 (January 12, 2009)	47
Mid-Cycle Performance Review and Inspection Plan- Prairie Island Nuclear Generating Plant, Units 1 & 2 (September 1, 2009)	48
Biennial Problem Identification and Resolution Inspection Report 2009009 (September 25, 2009)	49
NRC Integrated Inspection Report No. 0500282/2010003; 05000306/2010003 (July 26, 2010)	50
Prairie Island Nuclear Generating Station Final Significance Determination NRC Inspection Report No. 05000282/2008008 (January 27, 2009)	51
NRC Special Inspection Report 05000282/2008008; 05000306/2008008 Preliminary White Finding (November 7, 2008)	52
Final Significance Determination for White Finding and Notice of Violation; NRC Inspection Report 05000282/2009008; 05000306/2009008 (May 6, 2009)	53
NRC Inspection Report 05000282/2008009; 05000306/2008009 Preliminary Significance Determination for Yellow Finding (February 10, 2009)	54
Final Significance Determination for White Findings and Notice of Violation NRC Inspection Report 05000306/2009013 (September 3, 2009)	55
NRC Inspection Report 05000282/2009010; 05000306/2009010 (August 5, 2009)	56
Reactor Containment Diagram	57

Steven Yule et al., "The Role of Management and Safety Climate in Preventing Risk-taking at Work," Int. J. Risk Assessment and Management, Vol. 7, No. 2 (2007)	58
Biennial Problem Identification and Resolution Inspection Report 05000282/2007006 AND 05000306/2007006 (December 27, 2009)	59
SECY 06-0122 "Safety Culture Initiative Activities to Enhance the Reactor Oversight Process and Outcomes of the Initiatives" (May 24, 2006)	60
NRC Staff Slide from Public Meeting with the Nuclear Energy Institute and Industry Representatives Re: Nuclear Safety Culture Assessment Pilot (February 24, 2010)	61
Summary of July 28, 2010 Public Meeting to Discuss Observations and Lessons Learned During the Pilot Application of the Nuclear Energy Institute's Nuclear Safety Culture Assessment Process (August 4, 2010)	62
<i>Boric Acid Corrosion Guidebook, Revision 1: Managing Boric Acid Corrosion Issues at PWR Power Stations</i> , EPRI, Palo Alto, CA (2001) 1000975 (Pages 4-25 & 4-26)	63