

Sengupta, Abhijit

From: Miller, Garry [garry.miller@pgnmail.com]
Sent: Thursday, December 10, 2009 9:01 AM
To: Lake, Louis
Subject: FW: Updated Root Cause Chart
Attachments: P71 - Buttress 5 (35H Series).jpg; QC Inspection of SGR Opening.10.pdf

1 page each

Garry Dale Miller
General Manager
Nuclear Plant Development
Progress Energy
Caronet: 770-6107
Direct: (919)-546-6107
Mobile: (b)(6)
Fax: (919)-546-7209
E-mail: garry.miller@pgnmail.com

From: Miller, Garry
Sent: Thursday, December 10, 2009 8:50 AM
To: 'louis.lake@nrc.gov'
Subject: RE: Updated Root Cause Chart

Lou... hope you are doing well.

I thought it might be useful for me to brief you on ongoing containment delamination activities.

Just call my cell when convenient.

Thanks,
Garry

Garry Dale Miller
General Manager
Nuclear Plant Development
Progress Energy
Caronet: 770-6107
Direct: (919)-546-6107
Mobile: (b)(6)
Fax: (919)-546-7209
E-mail: garry.miller@pgnmail.com

From: Miller, Garry
Sent: Friday, December 04, 2009 3:23 PM
To: louis.lake@nrc.gov
Cc: Williams, Charles R.
Subject: Updated Root Cause Chart

Lou... thought you might be interested in the updated Root Cause Analysis Failure Mode chart.

9/8

Thanks,
Garry

Information in this record was deleted in accordance with the Freedom of Information Act Exemptions 2010-0116
FOIA/PA

Garry Dale Miller

General Manager

Nuclear Plant Development

Progress Energy

Caronet: 770-6107

Direct: (919)-546-6107

Mobile: (b)(6)

Fax: (919)-546-7209

E-mail: garry.miller@pgnmail.com





TABLE

CRACK ON LEFT RIGHT EDGE OF WALL, CONC
BEHIND 26" FROM RIGHT EDGE HOLE CONCRETE
50-60"