10 CFR 2.201	SAFETY INSPECTION R	EPORT AND COMPLIANCE INSPECTION
1. LICENSEE/LOCATION INSPECTED: Dakota Coal Company Wyoming Lime Producers P.O. Box 5540/ 30 Highway 310 Frannie, Wyoming 82423		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125
REPORT NO: 2010-00	01	Annigion, rexas 70011-4125
3. DOCKET NUMBER 030-32878	4. LICENSE N 33-27444	
LICENSEE:	######################################	nder your license as they relate to radiation safety and to compliance with the
2. Previous violat 3. The violations(     identified, non-r     discretion, were	s), specifically described to you by the repetitive, and corrective action was one satisfied.	dentified. e inspector as non-cited violations, are not being cited because they were selfor is being taken, and the remaining criteria in the NRC Enforcement Policy to e g the following requirement(s) and Corrective Action(s):
		escribed below and/or attached, were in violation of NRC requirements and are a may be subject to posting in accordance with 10 CFR 19.11.
	n is a NOTICE OF VIOLATION, which	
I hereby state that, within corrective actions is made	n is a NOTICE OF VIOLATION, which <b>Licensee's Statement</b> n 30 days, the actions described by m in accordance with the requirements	n may be subject to posting in accordance with 10 CFR 19.11.
I hereby state that, within corrective actions is made date when full complian	n is a NOTICE OF VIOLATION, which <b>Licensee's Statement</b> n 30 days, the actions described by m in accordance with the requirements ice will be achieved). I understand that	of Corrective Actions for Item 4, above. The to the inspector will be taken to correct the violations identified. This statem of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be the to further written response to NRC will be required, unless specifically reque