

OHara, Timothy

From: OHara, Timothy *TI*
Sent: Thursday, April 29, 2010 5:52 PM
To: 'Berrick, Howard G.'
Subject: RE: Scanned image from PX082MP0

Howard,

I'm not sure why you sent this information to me.

I'm looking for a copy of procedure SH.MD-sp.ZZ-0010(Q), Revision 3 which was used by Mr. Van Dorn on Saturday 4/24/10. The copy needs to show signatures/initials and supervisory review so that I can verify that the replaced AFW piping was coated correctly. Thanks.

Tim OHara

-----Original Message-----

From: Berrick, Howard G. [mailto:Howard.Berrick@pseg.com]
Sent: Thursday, April 29, 2010 10:22 AM
To: OHara, Timothy
Subject: FW: Scanned image from PX082MP0

Attached is the information on AFW painting/coating work

Howard Berrick
PSEG Nuclear LLC
Salem Regulatory Assurance
PSEG Nuclear - Salem Generating Stations
(W) 856-339-1862
(Fax) 856-339-1448

(Bpr (b)(6))



Ex 6

D-86