

Outside of Scope

**BRANCH 3
DAILY
STATUS**

Outside of Scope

4/30/10

Highlighted items were discussed at DRP/DRS Coordination meeting
BOLD items are new

Outside of Scope

outside of scope

SALEM ONE

Weekend Coverage: Dan

AL1=(9X)>0.07

AL2=(2of3)>0.11

AL3=(1X)>0.13

Outside of Scope

Degraded Equipment

- Design records for as installed AFW piping on Unit 1 & 2 not found

Outside of Scope

Information in this record was deleted in
accordance with the Freedom of Information Act.
Exemptions outside scope
FOIAPA 2010-0334

D-90

Outside of Scope

scam

- Unit 2 AFW Testing - PSEG determined that they did not perform ASME code required pressure drop test for the buried sections of the 22 and 24 headers. NRC evaluating if performing a risk assessment to meet Technical Specification 4.0.5 is appropriate if a test was never performed verses missed – Conte/Ennis, discussions ongoing, no apparent ongoing compliance issues

Outside of Scope

Additional Items

Status Board Items:

- Salem 1 AFW buried piping generic communications

Outside of Scope

Outside of Scope