

**Burritt, Arthur**

---

**From:** Burritt, Arthur *RI*  
**Sent:** Thursday, July 22, 2010 2:28 PM  
**To:** Ennis, Rick  
**Cc:** Cline, Leonard  
**Subject:** RE: Input Needed for NRR Management Meeting

Both bullets need to be updated. We plan to include you when we send out the mid cycle packages for review. The Salem mid cycle package has our most up to date discussions on both topics.

**From:** Ennis, Rick *NRR*  
**Sent:** Wednesday, July 21, 2010 3:23 PM  
**To:** Burritt, Arthur  
**Cc:** Cline, Leonard; Schroeder, Daniel  
**Subject:** Input Needed for NRR Management Meeting

Art,

To support an NRR management meeting, DORL PMs have been asked to provide write-ups which include any significant technical issues for their respective plants. As a starting point we are using the write-ups that we provide for the periodic discussions between the Region and the Chairman on plant status (last update was in May). Here are 2 items for Salem that may need to be updated/revise:

Outside of Scope

- During the spring 2010, Salem Unit 1 refueling outage, PSEG identified significant degradation for some of the buried auxiliary feedwater (AFW) piping. Based on preliminary UT measurements of the piping, the licensee determined that AFW system operability could not be assured through the next operating cycle. PSEG replaced all of the affected buried pipe. As part of the extent of condition review, PSEG is assessing the operability of the Salem Unit 2 AFW buried piping. NRC Regional and Headquarters staff are closely following the licensee's activities.

I would appreciate any feedback from Region I for these items. Note, my input is due on Monday, so I request that you provide any comments by COB Friday.

Thanks,

Rick

Information in this record was deleted in accordance with the Freedom of Information Act.  
Exemptions Outside Scope  
FOI/PA 2010-0334

*D-115*

*OUT OF SCOPE*