



Acuren USA
Anchorage, Alaska
Phone: (907) 569-5000
Materials Engineering and Testing
A Rockwood Company

October 25, 2010

U.S. Nuclear Regulatory Commission
ATTN: Regional Administrator, Region IV
612 E. Lamar Blvd., Suite 400
Arlington, Texas, 76011

RECEIVED

NOV - 2 2010

DNMS

SUBJECT: REPLY TO A NOTICE OF VIOLATION

REFERENCE: Docket: 030-36217
License: 42-32443-01

1. Reason for the violation was an unintentional failure to notice or consider 10 CFR 34.41(c).
2. Corrective action that has taken place by submission to the NRC, is an Acuren Procedure for Conducting Radiographic Operations at Off-shore, Production Platform, Lay-barges, and Remote Sites.
3. The procedure, dated September 25, 2010, was submitted for approval September 26, 2010. Upon approval, full compliance will be achieved.

Should you have any questions regarding this response, please contact me at any time.
Sincerely,

A handwritten signature in black ink, appearing to read "R. Jefferson", with a long horizontal flourish extending to the right.

Robert L. Jefferson
Radiation Safety Officer
Acuren USA, Alaska
(907) 440-9012
rjefferson@acuren.com