

**U.S. NUCLEAR REGULATORY COMMISSION****Date:** 11-30-10**TELEPHONE CONVERSATION RECORD****Time:** 3:00 PM**Mail Control  
or Report No(s).**

573582

**License No(s).** 44-13760-01**Docket No(s).** 03003294**Name of Licensee:** Brattleboro Memorial Hospital**Name of Participant(s):** Vicky Jelly, CNMT, Lead Nuclear Medicine Technologist  
Jan Nguyen**Telephone No.** (802) 257-8256**Subject:** Request for additional information in order to remove old nuclear medicine wing from  
(NOTE: This will be used as the license  
Documents Title in ADAMS)

I spoke to Vicky Jelly to confirm the areas that were decommissioned and were able to be removed from the license tie-downs under license condition 15. The close-out surveys that were submitted decommissioned the old nuclear medicine wing (which was on the tie-down dated March 22, 1994) and included the stress lab that was located in X-Ray Room 4 (which was on the tie-down dated February 8, 2002). However, the diagram for the close-out survey of the stress lab appeared to be of the stress lab located on the 3<sup>rd</sup> room of the Respiratory Therapy Department (which was on the tie-down dated April 14, 1994). Vicky said that the diagram of the close-out survey was correct and was of X-Ray Room 4, but had contained old information about what was around the stress lab. The stress lab on the 3<sup>rd</sup> floor had not been used since 2002 when X-Ray Room 4 had been converted to a stress lab. All 3 tie-downs are okay to be removed since those areas were decommissioned and are no longer areas of radioactive material use.

**Action Required: Remove tie-downs from March 22, 1994, April 14, 1994, and February 8, 2002 and process amendment.****Document Availability:** **Publicly Available** **Non-Publicly Available** **Non-Sensitive**  
 **Sensitive – Privacy Act/ PII**  
 **Immediate Release** **Non-Sensitive Copyright**  
 **Sensitive – Internal**  
**Normal Release Date: 12/8/2010** **Sensitive- Proprietary**  
 **Sensitive – Security-Related**  
**Delayed Release Date:****SUNSI Review Completed By:** Janice Nguyen / RA /**Document Accession #:** ML103400423