

ESBWR DCD Tier 2 Chapter 19

26A6642BY Revision 8 to Revision 9 Change List

Item	Location	Description of Change
1.	Entire Chapter	Header changed from Rev 8 to Rev 9.
2.	S19D4.3	First 2 paragraphs have been revised to clarify that at least 1 division of safety-related equipment remains unaffected by the aircraft impact and the resulting fire. Also, it was clarified that a separation of safety-related equipment by quadrant was spatial and that the physical separation was either by quadrant or by a small portion of the quadrant. Reference MFN 10-346.
3.	T19D-1	Added rows to denote that the existing fire barriers for elevation 13570 Penetration Rooms 1610, 1620, 1630, and 1640 are key design features based on revised interpretation of guidance for determining damage propagation. Reference MFN 10-346.
4.	T19D-1	Added row to describe the horizontal barriers in the Non-Divisional Commodity chases 1294 and 1295 as key design features based on revised interpretation of guidance for determining damage propagation. Reference MFN 10-346.