

U.S. NUCLEAR REGULATORY COMMISSION**Date:** 12/10/2010**Time:** 12:10 PM**TELEPHONE CONVERSATION RECORD****Mail Control
or Report No(s).**LER 2010- License No(s). 06-15099-01
012**Docket No(s).** 03008562**Name of Licensee:** Canberra Industries, Inc.**Name of Participant(s):** Terry Schwager, RSO for Canberra and Kathy Modes, NRC**Telephone No.** 203-639-2462**Subject:** Leaking Eu-152/Am-241 source(NOTE: This will be used as the
Documents Title in ADAMS)

I asked the licensee to provide the following additional information:

1. Cause: what caused the source to leak...was it the fragility of the mylar window? Currently unknown (licensee considering changing source vendors)
2. Provide copy of last two leak tests (the one before identification of the leak and the most current)
3. Provide copy of radiation survey of physics laboratory
4. Licensee indicated that these sources are not distributed to customers who purchase the ISOCs units.

Action Required: Response due 12/17/2010**Document Availability:****Publicly Available****Non-Publicly Available****Non-Sensitive** **Sensitive – Privacy Act/ PII** **Immediate Release****Non-Sensitive Copyright****Sensitive – Internal****Normal Release Date: 12/20/2010****Sensitive- Proprietary****Sensitive – Security-Related****Delayed Release Date:****SUNSI Review Completed By:** K Modes/ RA /**Document Accession #:** ML103430439