

**NRC FORM 581M PART 1**  
(4-2008)  
10 CFR 2.201

**U.S. NUCLEAR REGULATORY COMMISSION**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

<b>1. LICENSEE/LOCATION INSPECTED:</b> DBI Inc. 1909 Salt Creek Highway Casper, Wyoming 82601		<b>2. NRC/REGIONAL OFFICE</b>  U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
<b>REPORT NO:</b> 030-37817/2010-001			
<b>3. DOCKET NUMBER</b> 030-37817	<b>4. LICENSE NUMBER</b> 49-23901-01	<b>5. DATE OF INSPECTION</b> November 15, 2010	

**LICENSEE:**  
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 34.43 (e) requires that the RSO or designee conduct an inspection program of the job performance of each radiographer and radiographer assistant to ensure that the Commission's regulations, license requirements and the applicant's operating and emergency procedures are followed. The inspection program must (1) include observation of the performance of each radiographer and radiographer assistant during an actual industrial radiographic operation at intervals not to exceed 6 months.

Contrary to the above, a review of records indicated that the site RSO, who was assigned responsibility for evaluating the performance of the other radiographers, was last evaluated for performance in 2008 (12/12/08). Use logs for the cameras indicate that the site RSO worked as a radiographer on September 28, 2010 and September 29, 2010 and should have been evaluated before being allowed to participate in radiographic operations.

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Pennie Frye	<i>Pennie Frye</i>	12/13/10
NRC INSPECTOR	Martha Poston-Brown	<i>Martha Poston-Brown</i>	12/7/10
NRC INSPECTOR	Vivian Campbell	<i>Vivian Campbell</i>	12/7/2010