



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406-1415

December 15, 2010

Docket No. 03030394
Control No. 144681

License No. 52-24969-01

Luis E. Bonnet-Aleamar, M.D.
Director and Radiation Safety Officer
The Radiology Institute Imaging Center
Clínica Las Américas, Suite 202
Nuclear Medicine Laboratory
400 F. D. Roosevelt Avenue
Hato Rey, PR 00918-2129

SUBJECT: THE RADIOLOGY INSTITUTE IMAGING CENTER, CORRECTED COPY OF
LICENSE, CONTROL NO. 144681

Dear Dr. Bonnet-Aleamar:

Enclosed is the Corrected Copy of Amendment No. 8 for License No. 52-24969-01. In accordance with a telephone conversation with Mr. Armando Bonnet on December 1, 2010, three new license conditions were added requiring physical inventories and leak tests and prohibiting opening of stored sealed sources and devices possessed under the license.

We apologize for any inconvenience this error may have caused. In addition, please note that the license does not authorize the medical use of byproduct material. In order to reinstate medical use, the license must be amended.

Sincerely,

***Original signed by Penny Lanzisera
for***

Marc Ferdas, Chief
Medical Branch
Division of Nuclear Materials Safety

Enclosure:
Corrected Copy of Amendment No. 8

DOCUMENT NAME: G:\WordDocs\Current\Lic Cvr Letter\L52-24969-01.144681.doc

SUNSI Review Complete: HBermúdez

After declaring this document "An Official Agency Record" it **will** be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI	N	DNMS/RI		
NAME	HBermudez/PL for HB		MFerdas/PL for MF				
DATE	12/15/2010		12/15/2010				

OFFICIAL RECORD COPY