




plant status daily enter daily plant status saf  
 archives in

Ocone Information for 08/24/2009 (Modify/Update)

Outside of Scope




Outside  
of  
Scope

Significant TS / Issues:

The licensee performed a boroscope inspection of the internal portions of the pipe and identified at least one location that is leaking. The guided wave UT was unsuccessful at obtaining meaningful results. The licensee is attempting to perform a different type of UT in order to characterize the flaw as input into their PDO (prompt determination of operability). The licensee is not planning on performing a weld repair of the flaw, rather a modification is being planned to install a new discharge line for the U2 portion of piping. This mod will consume most (if not all) of the 45-day maintenance AOT. SSF is currently inop for all three units for seismic when the discharge line was cut.


Outside of Scope



outside  
of  
Scope

Information in this record was deleted in accordance with the Freedom of Information Act Exemptions Outside of Scope FOIA/PA 2011-0421

Outside of Scope



Outside  
of  
Scope