

McCarver, Sammy

From: Gray, Mel - R1
Sent: Tuesday, November 30, 2010 8:12 AM
To: Bickett, Brice; McCarver, Sammy
Subject: mels draft of briefing paper if needed
Attachments: Briefing Sheet to Support ORA Stakeholder Outreach Meeting with G.docx

Information in this record was deleted in
accordance with the Freedom of Information Act.
Exemptions Outside of Scope
FOIA/PA 2011-0045

B/7

OUT-OF-SCOPE

Outside of Scope

IP2 automatic reactor trip occurred on November 7, 2010 due to automatic turbine trip as a result of 21 main transformer failure and explosion. Entergy declared "alert" per their EP plan. Entergy personnel replaced the 21 main transformer and determined the 22 main transformer was not damaged. Entergy operators re-started Unit 2 after completing replacement and testing of the 21 main transformer and inspection of other similar transformers. NRC inspectors continue to closely follow Entergy's causal evaluations of transformer failure and associated corrective actions and to review Entergy plant response and Entergy staff implementation and critique of their EP Plan.

Outside of Scope

outside of scope

outside of scope

Outside of Scope

(1 Page)