

# UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 612 EAST LAMAR BLVD, SUITE 400 ARLINGTON, TEXAS 76011-4125

January 21, 2011

Mr. Rick L. Tripp Plant Managing Director PacifiCorp Energy Dave Johnston Steam Electric Plant 1591 Tank Farm Road Glenrock, WY 82637

SUBJECT: RESPONSE TO NRC INSPECTION REPORT 030-36612/2010-001 AND

NOTICE OF VIOLATION

Dear Mr. Tripp:

Thank you for your letter dated January 7, 2011, in response to the violation identified in our letter and Notice of Violation (Notice) dated December 28, 2010. We have reviewed your letter and find your response and corrective actions to be responsive to our concerns.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a>.

If you have any questions about this letter, please contact Martha Poston-Brown at 817-860-8181 or the undersigned at 817-860-8287.

Singerely,

Vivian H, Campbell, Chief

Nuclear Materials Safety Branch A

Docket: 030-36612 License: 49-27781-01

cc w/enclosure:

Copy of licensee's response

Scott W. Ramsey, Radiological Services Supervisor Wyoming Office of Homeland Security 2421 East 7<sup>th</sup> Street Cheyenne, WY 82001

cc w/enclosure:

E. Collins, RA

R. Caniano, D:DNMS

C. Cain, DD:DNMS

J. Whitten, C:NMSB-B

R4DNMS\_MS-A

Hard copy: RIV Materials Docket File

S:\DNMS\!NMIE	3\!Poston\Wy N	ov 2010\PacifiCor	o 10-001 .	Ack Ltr.docx ML	110210584	
ADAMS	X Yes □ No	X SUNSI Rev C	omplete	Reviewer Initials:	MRP .	
Publicly Avail	X Yes □ No	Sensitive Value:	n/a			
RIV:C:NMSB-A			C:NMSB-A			
MRPoston-Brown;dlf			VHCampbell			
( NK			1,110			
1/19/11	Ner		1/1/11			

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax



JAN 1 0 REC'D

DNMS

#### DAVE JOHNSTON STEAM ELECTRIC PLANT

1591 TANK FARM ROAD • GLENROCK, WYOMING 82637 • PHONE (307) 995-5000 • FAX (307) 995-5020

January 7, 2011

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Re: Reply to a Notice of Violation

NRC INSPECTION REPORT 030-36612/2010-001 AND NOTICE OF VIOLATION

#### Dear Sir or Madam:

In connection with the inspection conducted at PacifiCorp's Dave Johnston power plant by Ms. Marta Poston-Brown and Ms. Vivian H. Campbell on November 17, 2010, and in response to the subsequent notice of violation dated December 28, 2010, please find the following explanation which includes corrective measures taken by PacifiCorp to achieve compliance.

#### **BACKGROUND**:

In October 2009, the Dave Johnston Plant's Safety and Security Coordinator, Tom Miller, was terminated. In addition to Mr. Miller's safety and security duties, he was also the plant's Radiation Safety Officer.

In addition to Mr. Miller's termination, PacifiCorp's contract with ThermoFisher Scientific expired in April of 2009, and was not renewed until November 2009. ThermoFisher Scientific is the supplier of the radioactive source and is contracted to perform the shutter checks, leak tests, and assist with the inventory. Although a contract with ThermoFisher was in place in late 2009, the necessary work release was not initiated to conduct these tasks because the plant did not identify anyone to pick up those responsibilities after Mr. Miller's termination.

#### **CORRECTIVE ACTIONS:**

After the inspection on November 17, 2010, PacifiCorp initiated the following corrective actions:

A. In response to violation D, on December 2, 2010, Mr. Anderson conducted the periodic (annual) review of the radiation protection program content and implementation in accordance with 10 CFR 20.1101(c). See Attachment 1.

- B. In response to violations A, B and C, on December 12-14, 2010, Mr. Rob Belnap of ThermoFisher Scientific conducted the leak test in accordance with Condition 13 of NRC materials license 49-27781-01. In addition, Mr. Belnap completed the test of the on-off mechanism (shutter) as required by Condition 16 of NRC materials license 49-27781-01, and Mr. Belnap completed the physical inventory of the sealed sources required by Condition 15 of NRC materials license 49-27781-01. See Attachment 2.
- C. Upon completion of Mr. Belnap's leak test certification, the Sealed Source Leak Test and Inventory Record was filled out by the Dave Johnston Plant's Compliance Manager, Alan Dugan. See Attachment 3.

#### STEPS TO PREVENT FUTURE OCCURRENCE:

PacifiCorp has taken the following steps to prevent future occurrence:

- A. The Dave Johnston Plant recognizes the need for a Radiation Safety Office on site and has named Mr. Alan Dugan to fulfill that requirement. Mr. Dugan will be attending Radiation Safety Officer training in Las Vegas, Nevada, January 10 14, 2011. Upon completion of Mr. Dugan's training, PacifiCorp will submit an amendment to NRC material license 49-27781-01 naming him as Radiation Safety Officer.
- B. PacifiCorp utilizes an electronic compliance management system for other regulatory requirements. The compliance management system generates task assignments with due dates and has a robust reminder system to a variety of personnel to ensure all required actions are completed. All of the requirements of NRC materials license 49-27781-01 have been added to the system to ensure continued compliance.

Should you have questions or need clarification, please feel free to contact Mr. Alan Dugan at (307) 995-5046 or myself at (307) 995-5001.

Sincerely,

Ricky L. Tripp

Plant Managing Director

Olily 2. Trol

Attachments

Reply to a Notice of Violation January 7, 2011 Page | 3

cc: Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
612 East Lamar Blvd, Suite 400
Arlington, TX 76011-4125

Scott W. Ramsay Wyoming Radiation Control Program Director Radiological Services Supervisor Wyoming Office of Homeland Security 2421 E. 7<sup>th</sup> Street Cheyenne, Wyoming 82001

Dana Ralston - NTO
Derald Anderson - NTO
Alan Dugan - Dave Johnston Plant

# Attachment 1

Fixed Gauge Audit Checklist 12-01-2010

#### Suggested Fixed Gauge Audit Checklist

**Note:** All areas indicated in audit notes may not be applicable to every license and may not need to be addressed during each audit. For example, licensees do not need to address areas which do not apply to their activities and activities which have not occurred since the last audit need not be reviewed at the next audit.

Licensee's name Dave Janston Plant	License No. 49 - 2778/ - 0
Date of This Audit 12-2-10	Date of Last Audit <u>9-17-08</u>
Durke	Date 12-2-10
(Auditor Signature)	
	Date
(Management Signature)	

#### **Audit History**

- A. Last audit of this location conducted on (date) 9-17-08
- B. Were previous audits conducted at intervals not to exceed 12 months? [10 CFR 20.1101]  $\mathcal{W}_{\mathcal{O}}$
- C. Were records of previous audits maintained? [10 CFR 20.2102] Yes
- D. Were any deficiencies identified during last two audits or two years, whichever is longer?
- E. Were corrective actions taken? (Look for repeated deficiencies). W/4

#### Organization and Scope of Program

- A. If the mailing address or places of use changed, was the license amended? M/A
- B. If ownership changed or bankruptcy filed, was NRC prior consent obtained or was NRC notified? M/4
- C. Radiation Safety Officer
  - 1. If the RSO was changed, was license amended? 412
  - 2. Does new RSO meet NRC training requirements? Los
  - 3. Is RSO fulfilling his/her duties? Yn
  - 4. To whom does RSO report? Tun Davis

#### APPENDIX H

- D. If the designated contact person for NRC changed, was NRC notified? Yuz
- E. Sealed Sources and Devices
  - 1. Does the license authorize all of the NRC regulated radionuclides contained in gauges? 42
  - 2. Are the gauges as described in the Sealed Source and Device (SSD) Registration you Certificate?
  - 3. Have copies of (or access to) SSD Certificates? Yes
  - 4. Have manufacturers' or distributor's manuals for operation and maintenance? Yes [10 CFR 32.210]
  - 5. Are the actual uses of gauges consistent with the authorized uses listed on the license?
  - 6. Are the location of the gauges compatible with the "Conditions of Normal Use" and "Limitations and/or Other Considerations of Use" on the SSD Registration Certificates?

#### Training and Instructions to Workers

- A. Were all workers who are likely to exceed 1 mSv (100 mrem) in a year instructed per [10 CFR 19.12]? Refresher training provided, as needed [10 CFR 19.12]? Records maintained? Triving fracted by Mannfecture
- B. Did each AU receive training and instruction given at the time of gauge installation or equivalent training and instruction before using gauges?
- C. Are training records maintained for each AU? Yes
- D. Did individuals who perform non-routine operations receive training before performing these operations?
- E. Did interviews with AUs reveal that they know the emergency procedures? Yes
- F. Did this audit include observations of AUs using the gauge? No
- G. Did this audit include observations of workers performing routine cleaning and lubrication on the gauge?  $\mathcal{N}_6$
- H. HAZMAT training provided, if required? [49 CFR 172.700, 172.701, 172.702, 172.703, 172.704] Yes on 514e team

# Radiation Survey Instruments W/A

- A. If the licensee is required to possess a survey meter, does it meet the NRC's criteria? [10 CFR 20.1501]
- B. Are calibration records maintained [10 CFR 20.2103(a)]?

#### **Gauge Inventory**

- A. Is a record kept showing the receipt of each gauge? [10 CFR 30.51(a)(1)] Yes
- B. Are all gauges physically inventoried every six months? Yes
- C. Are records of inventory results with appropriate information maintained? Yes

#### **Personnel Radiation Protection**

- A. Are ALARA considerations incorporated into the radiation protection program? [10 CFR 20.1101(b)] Yes
- B. Were prospective evaluations performed showing that unmonitored individuals receive ≤ 10% of limit? [10 CFR 20.1502(a)] 412
- C. Did unmonitored individuals' activities change during the year which could put them over 10% of limit?
- D. If yes to C. above, was a new evaluation performed? M/A
- E. Is external dosimetry required (individuals likely to receive >10% of limit,)? And is dosimetry provided to these individuals? Not Regard
  - 1. Is the dosimetry supplier NVLAP approved? [10 CFR 20.1501(c)]
  - 2. Are the dosimeters exchanged monthly for film badges and quarterly for TLD's?
  - 3. Are dosimetry reports reviewed by the RSO when they are received?
  - 4. Are the records NRC Forms or equivalent? [10 CFR 20.2104(d), 20.2106(c)]
    - a. NRC-Form 4 "Cumulative Occupational Exposure History" completed?
    - b. NRC-Form 5 "Occupational Exposure Record for a Monitoring Period" completed?
  - 5. Declared pregnant worker/embryo/fetus
    - a. If a worker declared her pregnancy, did licensee comply with [10 CFR 20.1208]? Nane
    - b. Were records kept of embryo/fetus dose per [10 CFR 20.2106(e)]? N/4
- F. Are records of exposures, surveys, monitoring, and evaluations maintained [10 CFR 20.2102, 20.2103, 20.2106]

#### APPENDIX H

#### **Public Dose**

- A. Is public access to gauges controlled in a manner to keep doses below 1 mSv (100 mrem) in a year? 10 CFR 20.1301(a)(1)] 442
- B. Has a survey or evaluation been performed per 10 CFR 20.1501(a)? Have there been any additions or changes to the storage, security, or use of surrounding areas that would necessitate a new survey or evaluation? Yes - No
- C. Do unrestricted area radiation levels exceed 0.02 mSv (2 mrem) in any one hour? [10 CFR 20.1301(a)(2)] No
- D. Is gauge access controlled in a manner that would prevent unauthorized use or removal? [10 CFR 20.1801]
- E. Records maintained? [10 CFR 20.2103, 20.2107] Yes

#### **Operating and Emergency Procedures**

- A. Have operating and emergency procedures been developed? Yes
- B. Do they contain the required elements?
- C. Does each individual working with the gauges have a current copy of the operating and emergency procedures (including lock-out procedures and emergency telephone numbers)?
- D. Is a lock-out warning sign posted at each entryway to an area where it is possible to be exposed to the beam? 211
- E. Did any emergencies occur? No
  - 1. If so, were they handled properly? MA
  - 2. Were appropriate corrective actions taken? MIT
  - 3. Was NRC notification or reporting required? [10 CFR 20.2201, 20.2202, 20.2203] W/M

#### **Leak Tests**

- A. Was each sealed source leak tested every 6 months or at other prescribed intervals? No, Was each sealed source leak tested every 6 months or at other prescribed intervals? No, Was each sealed source leak tested every 6 months or at other prescribed intervals? No, Was each sealed source leak tested every 6 months or at other prescribed intervals? No, Was each sealed source leak tested every 6 months or at other prescribed intervals? No, Was each sealed source leak tested every 6 months or at other prescribed intervals? No, Was each sealed source leak tested every 6 months or at other prescribed intervals? No, Was each sealed source leak tested every 6 months or at other prescribed intervals?
- C. Are records of results retained with the appropriate information included?
- D. Were any sources found leaking and if yes, was NRC notified? No

#### **Maintenance of Gauges**

- A. Are manufacturer's or distributor's procedures followed for routine cleaning and lubrication of gauge? Yes, but 2010 missel. Will be Completed Dec. 2010
- B. Was each on-off mechanism tested for proper operation every 6 months or at other prescribed intervals? No
- C. Are repair and maintenance of components related to the radiological safety of the gauge performed by the manufacturer, distributor or person specifically authorized by the NRC or an Agreement State and according to license requirements (e.g., extent of work, procedures, dosimetry, survey instrument, compliance with 10 CFR 20.1301 limits)?
- D. Are labels, signs, and postings identifying gauges containing radioactive material, radiation areas, and lock-out procedures/warnings clean and legible?

# Transportation NA

(Note: This section will not apply if you have not transported gauges during the period covered by this audit.)

- A. DOT-7A or other authorized packages used? [49 CFR 173.415, 173.416(b)]
- B. Package performance test records on file?
- C. Special form sources documentation? [49 CFR 173.476(a)]
- D. Package has two labels (ex. Yellow-II) with TI, Nuclide, Activity, and Hazard Class? [49 CFR 172.403, 173.441]
- E. Package properly marked? [49 CFR 172.301, 172.304, 172.310, 172.324]
- F. Package closed and sealed during transport? [49 CFR 173.475(f)]
- G. Shipping papers prepared and used? [49 CFR 172.200(a)]
- H. Shipping papers contain proper entries? {Shipping name, Hazard Class, Identification Number (UN Number), Total Quantity, Package Type, Nuclide, RQ, Radioactive Material, Physical and Chemical Form, Activity (SI units required), category of label, TI, Shipper's Name, Certification and Signature, Emergency Response Phone Number, Cargo Aircraft Only (if applicable)} [49 CFR 172.200, 172.201, 172.202, 172.203, 172.204, 172.604]
- I. Shipping papers within drivers reach and readily accessible during transport? [49 CFR 177.817(e)].
- J. Package secured against movement? [49 CFR 177.834]
- K. Placards on vehicle, if needed? [49 CFR 172.504]

#### APPENDIX H

- L. Proper overpacks, if used? [49 CFR 173.25]
- M. Any incidents reported to DOT? [49 CFR 171.15, 171.16]

#### Auditor's Independent Survey Measurements (If Made)

A. Describe the type, location, and results of measurements. Does any radiation level exceed regulatory limits? [10 CFR 20.1501(a) & 20.1502(a)]

#### **Notification and Reports**

- A. Was any radioactive material lost or stolen? Were reports made? [10 CFR 20.2201, 30.50]
- B. Did any reportable incidents occur? Were reports made? [10 CFR 20.2202, 21.21, 30.34, 30.36, 30.50]
- C. Did any overexposures and high radiation levels occur? Reported? [10 CFR 20.2203, 30.50]
- D. If any events (as described in items a through c above) did occur, what was root cause? Were corrective actions appropriate?
- E. Is the management/RSO/shift foreman licensee aware of telephone number for NRC Statement [(301) 816-5100]

#### Posting and Labeling

- A. NRC-Form 3 "Notice to Workers" posted? [10 CFR 19.11] 422
- B. NRC regulations, license documents posted or a notice posted? [10 CFR 19.11, 21.6] Yes
- C. Other posting and labeling? [10 CFR 20.1902, 20.1904] MA

#### Record Keeping for Decommissioning N/A

- A. Records kept of information important to decommissioning? [10 CFR 30.35(g)]
- B. Records include all information outlined in [10 CFR 30.35(g)]?

#### **Bulletins and Information Notices**

- A. NRC Bulletins, NRC Information Notices, NMSS Newsletters, received?
- B. Appropriate training and action taken in response? Yes

#### **Special License Conditions or Issues**

A. Did auditor review special license conditions or other issues (e.g., non-routine operations)? No

**Deficiencies Identified in Audit; Corrective Actions** 

Missel heads tests + maintaining

A. Summarize problems/deficiencies identified during audit.

B. If problems/deficiencies identified in this audit, describe corrective actions planned or taken. Are corrective actions planned or taken at ALL licensed locations (not just location audited)? Include date(s) when corrective actions are implemented. Leals test a muster will be complated by Dec. 17, 2010

C. Provide any other recommendations for improvement.

#### **Evaluation of Other Factors**

- A. Senior licensee management is appropriately involved with the radiation protection program and/or RSO oversight? Yes
- B. RSO has sufficient time to perform his/her radiation safety duties? Yes
- C. Licensee has sufficient staff to support the radiation protection program? Yes

# Attachment 2

ThermoFisher Scientific Leak Test Certification and Field Service Activity Report

12-14-2010

# Thermofisher scientific

Thermo Gamma Metrics, LLC 10010 Mesa Rim Road San Diego, CA 92121

Tel: +1-800-488-4399 Fax: +1-858-546-1734 www.thermo.com

#### LEAK TEST CERTIFICATE

CUSTOMER	Pacificorp	TES	ST DATE	=   .	12/14/2010	1
SITE NAME	Dave Johnson	RSC	Der	ald A	nderson	
SITE ADDRESS	1591 Tank Farm Rd, Coal Co. Rte					
SITE ADDRESS	Glenrock, WY 82637		LICENS	E#	49-27781-01	
DEVICE TYPE	CB-HI (CQM)		DEVICE	S/N	840021	
TEST REASON	Source Replenishment		······································			.:

ļ	TEST					
1	PERFORMED			Parza		Ì
	BY:	Rob G. Belnap	SIGNATURE	Total Dallary	DATE	12/14/2010

#### **TEST EQUIPMENT**

MODEL	Eberline 600	S/N	2228	CALIBRATION DUE DATE	12/30/2010
MODEL	Eberline SHP-270	S/N	609	CALIBRATION DUE DATE	12/30/2010
MODEL	Eberline SHP-360	S/N	653	CALIBRATION DUE DATE	12/30/2010

#### **CERTIFICATIONS**

Special Form:	Californium 252 (Cf-252) Cf-Pd cermet or Cf-Pd alloy Cessum 137 (Cs-137) Cessum Chloride Americium 241 (Am-241) Americium Chloride Colher Type:
Leak Test:	The sources listed below have passed the ANSI N5.10-1268, Appendix B, section B2.1 Wipe (Smear) Test with removable Alpha and Beta/Gamma surface contamination less than, or equal to, 0.005 μCi.  Nate: A scaled source may be leaking if it has removable contamination that is found to be equal to or greater than 0.003 μCi. (185 Becquerel)
Inventory:	The sources listed below were verified to be in above device.
	Reference Data: 0.005 pm=1558q 18q=27 pm

#### **SOURCE DATA**

Serial Number	Isotope	Amount (µgm)	Amount (mCi)	Manufacture	Status	Contamination
FTC-CF-Z2303	CALIFORNIUM 252	4.67	2.51	Frontier Technology	Installed	0
FTC-CF-Z3144	CALIFORNIUM 252	4.42	2.37	Frontier Technology	Installed	0
V-954	CESIUM-137	14.21	7.63	E&Z Isotope Products	Installed	0
FTC-CF-4057	CALIFORNIUM 252	9.43	5.06	Frontier Technology	Installed	0

# 

# Radiation Device Survey

Date: 12/14/2010 Company: PacifiCorp

Site: Dave Johnston Power Plant

Site RSO: Deraid Anderson Device Mod: CB-HI (CQM) Device S/N: 840021

Radíation L	Detection	Radiation Detection Equipment
Model	N/S	Cal Due Date
Eberline E800	2228	12/30/10
Eberline SHP270	609	12/30/10
Eberline SHP360	653	12/30/10
NRD	717148	12/30/10

·			·	····		 	
Source Info	N/S	FTC-CF-Z2303	FTC-CF-Z3144	FTC-CF-4057	V-954		
Ø	Isotope	Cf-252	Cf-252	Cf-252	Cs-137		


KONNERNONTERIŠČENA	No Materi	terial On Balt	ļ				Stano	lard or M	Standard or Material On Belt	ו Belt	
30cm	10(	100cm	TOT	TOTALS	Location	30cm	im:	100	100cm	TOTALS	ALS
Neutron	л Оатта	Neutron	30 cm	100 cm		Gamma	Neutron	Gamma	Neutron	30 cm	100 cm
1.09	0,80	0.62	2.08	1.42	1					0.00	00'0
0.81	0.83	0.32	1.92	0.95	2					0,00	0.00
0.31	0.04	0,15	0.87	0.19	က					0.00	0.00
0.49	0.21	0.25	1.39	0.46	4					00'0	0.00
0.80	0.78	0.02	1,95	0.78	သ					0.00	0.00
0.07	0,31	0.14	0.84	0.45	9					00'0	0.00
0.51	0.19	0.08	1,20	0.24	7					0.00	0.00
0.20	0.31	0,12	1.03	0.43	œ					00'0	00'0
0.88	06.0	0.82	2.78	1.72	8					0.00	00'0
1.18	0.92	0.65	2.39	1.57	10					0.00	0.00

NOTE: Use Device Map for survey point locations. Data results in mRem/Hr.

Conversion: 1 mSv = 100 mRem

Signature: Broke Gr. Francoure Rob G. Belnap Surveyed By:

12/14/2010 Date:





# **Radioactive Materials Shipping Notification**

RECEIVER	R INFORMATI	<u>ON:</u>			
Company:	PacifiCorp				
Site:	Dave Johns	ton Power Plant		**************************************	
Address:	1591 Tank F	arm Road, Coal C	o, Rie		
	Glenrock, W	Y 82637			
RSO Cont	act: Derald A	nderson			
Telephone	: 801-220-	4155			
Email: _	derald.an	derson@pacificor	p.com		
TECHNICA	AL INFORMAT	TON			
Source	<u>Isotope</u>	Quantity	- Activity (ug)		
Cf-252		1	10	-	
		-		_	
				_	
	has been noti o customer si		oactive sources ar	e ready for shipment an	d approves shipment of
Requested	d ship date: (	)8/06/2010			
		of will be made to the case with th		shìp date, due to extern	al factors there are no
Thermo Fis	sher Scientific:				
By: Rob G	. Belnap	Т	itle: FSE	Date	e: 8/2/2010



#### STRAIGHT BILL OF LADING

150-9001 & 14001

# DRIVER PLEASE NOTE

IF SINGLE SHIPMENT CHECK BOX BELOW

RKED COLLECT

# SHIPPER PLEASE NOTE

# FREIGHT CHARGES ARE PREPAID UNLESS MARKED COLLECT

**ORIGINAL - NOT MEGOTIABLE** 

	Charter - Mai Medaletber					
Conway-853-737883	DATE P.O. NO. SHPPER NO. A50642 AUGUST 2010 3000069801 50220 s/n 1279 CUSTOMER'S SPECIAL REFERENCE NUMBER					
Superproducts (Contract Contract Contra	Attn: Rom Miller					
SKIPPER (FROM) Frontier Technology Corporation	CONSIGNEE (TO)   PacifiCoxp - Dave Johnston Plant					
STREET 1641 Burnett Drive	STREET					
CITY, STATE/PROVINCE, ZPIPOSTAL CODE (TELEPHONE)	1591 Tank Faun Road, Coal Co Rte CHY, STATEPROVINCE, ZIEPOSTAL CODE (TELEPHONE)					
Xenia, OH 45385 937-376-5691	Glenrock, WY 82637 307.436.2119					
Themso Gamma Metrics, IIC						
10010 Mesa Rim Road	STREET					
CITY, STATEPROVINCE, ZIP/POSTAL CODE (TELEPHONE) San Disgo, CA 92121 858.450.9811	CITY, STATE-PROVINCE, ZIPIPOSTAL CODE (TELEPHOME)					
ACCOUNT CODE	Greage					
NUBBEH SARYMU HU DAYS S	REGISTO EXCEPTIONS PROJECT OF THE STATE OF T					
1 X Radioactive Material, Type A Package, Special						
Class 7, UN3332 Californium-252 solid CfRd a	164000					
	2 100 2/3					
1 Type A Package X 0.2GBq. TI: 2.1						
Labeled "RADICACTIVE YELLOW III". Radioactive placards required -1- offered.						
PRINCIPLE 1800-424-9300						
COD AMOUNT: \$ COD ☐ Prepaid						
LI U.S. LI Canadian  NOTE: Onseigner's congainy check made psyable to the Shipper will be accepted by  Onseigner's congainy check made psyable to the Shipper will be accepted by						
Con-way and forwarded to shipper unless officerwise directed to do so by the shipper.						
Notice: Unless the Stigger completes the requirements as provided telen; Canter's liability shall shall in no event be Eadle for loss of prolif, iscome, interest anomey tees, or any special, indications are required to state executionly in which gradered value of the property. For this paragraph remains a on the resease nide of the life of Lening.	l be thrived as stated herein and in Teriff CNWY-189, which may be obtained by request. Cambar ented or conscipential damages. Where the rate or MAPC classification is dependent on value, mapson the inclased veloce of the property is bestly specifically stated by the Shipper to be not g suits final released value termin and combines.					
Conster Hability with estigament oxiginating within the United States: Unless the Supper de- abilitional change, Center's mechanic Rabidy is \$25.00 per pound per individual test or demograd of buther that Candon's Rabidy on esticles other from near esticles, individual but not funded to used, the other of the control of the stigates of the from near esticles, individual but not funded to used, the other of the control of the stigates of the proposal the deciment value of the property is increby s	issus excess value on the 280 of Lading below, enquests excess liability coverage and pags an son within the stigment, subject to \$150,000.00 maximum total liability per stigment, and provided encountational or subjects that in the sense of an orang \$1,00 per sevent, and provided subject on the sense effects stell not exceed ten cents (\$,10) per pound per individual lost or permany stated by the Stigger to be \$ and Shipper agrees to pay an additional lest.					
change for excess salviny coverage. Total declared value may not excess 5650,010.00 per shipir Canting Balanny with ethipirish originaling within Canadar Unique the Shipper speec to a Soc	ieni. Del Agresmont, declares the valua in the DOX boldry and agrepa to sey the excess liability charge.					
Cantin Babilly with elignment originaling within Ceneda: Unless the Shipper agrees to a Special Agreement, declares the value in the tox below and agrees to pay the excess fieldly of by billialing, where indicated, Center's moving Residues is CANSACAD per powerful (CANSACAD per Biogram) per individual local or demanded piece within the stigment, subject to a maximum biblioper of CANSACAD per powerful fieldly per shipment of CANSACAD CO, and provided feature that Canter's Subject on earlies other new winders, including but not limited to cent. Examinational or individual loci or descent entires that canter is subject or individual loci or descent entire that occurs (S.10) (CANS) per powerful per individual loci or descent piece within the adoption.						
SPECIAL AGREEMENT: Declared Value: CANSper pound. (Declared value may not exceed CAN \$100,000.00 per shipment						
Shipper agrees to pay excess Rability charge:(Shipper's initials)  bipper Certification: I hereby deciate that the contents of this consignment are fully and accurately deciated above by the proper shipping name, and are properly classified, pauliaged, market						
and labelediplacearded, and are in all respects in proper condition for transport according to applications. Highwent Received: The shipment is received subject to Tariff CNV/Y-199, Canter's pricing some	chies, terms, conditions and rules maintained at Carrier's general diffices in effect on the date of					
some of this 1610 of Leding, as well as the Mational Motor Freight Classifications (MAFC), the Hazz I-C), and the Household Goods Masage Guide (MHSB 105 Series), for shipments originating in the Goods Act, and the regulations in force in the provincial jurisdiction at the time and place of the	e United States: and the Canadian Motor Vehicle Transport Act. the Transportation of Democrars					
program good oxier, but only to the extent that it is unconceated and visible without further inspec he word Carrier is defined throughout this contract as meaning any person or corporation in pos	fion and except as noted or marked. The property is consigned and destined as indicated above, session of the property under this contract. Carter screes to carry the property to its destination.					
ion its mute, otherwise to deliver to another Camier on the route to said destination. In the event r COL, all stipppearts will be hilled as PPD. It is mutually agreed as to each Comier of all or any any time interested in all or any off said property, that every service to be performed hereumder sin activing, but not limited to, the "Terms and Conditions" listed on the back side of this Bill of Land	t non mentitings are involvated om the 1811 of Lading stating that the shipment is to be bailed as PPD of said property, over all or any portion of said route to the destination and as to each party at all be subject to all of this 1818 of Lading's terms and conditions in effect on the date of shipment.					
SWPPER	CARRER ID CON-WAY FREIGHT INC.					
Frontier Technology Corporation  *UTHORIZED SIGNATURE	AUTHORIZED SIGNATURE DATE () P()					
Freeze S. Cantow Treva L. Janzon	mindeny covay DV 1654					
	AND MISCO COLLANGE DEFENSION A					

Thermo Gamma Metrics, LLC./PacifiCorp DJ Johnston, WY 16 August 2010

PACKING LIST-DECLARATION OF CONFORMITY

FRONTIER TECHNOLOGY CORPORATION 1641 Burnett Drive, Xenia Ohio 45385 Tel: 937/376-5691 Fax: 937/376-5692

CONSIGNEE: PacifiCorp - Dave Johnston Plant

1591 Tank Farm Road,

Coal Co Rte

Glenrock, WY 82637

Attn: Tom Miller Tel: 307-436-2119

License: NRC 49-27781-01 REFERENCES: A50642 3000069801

16 August 2010 SOURCE DATA: as of

Content (activity) Output (n/s) Contamination/100 cm<sup>2</sup> 10.3 ug. (0.2 GBq.) 2.4 x 10 alpha<9 x 10 6 uCi Model Serial No.

FTC-CF-4057 100

beta/gamma<45 x 10<sup>-6</sup>uCi

Documents Review

SHIPPING CONTAINER: US-DOT 7A Type A

Serial # 1279 Weight 275 lbs.(125 K.) Seal #FTC Model #50220

surface at one meter Radiation level (wrem/hr): 10.0 0.6 qamma 15.0 1.5 neutron 2.1 (TI) 25.0 TOTAL

Gamma RO2 1522 Neutron PNR4 1004 Survey Instruments Used: Contamination level: alpha<9 x 10-6uCi/100cm2 beta/gamma<45  $\times 10^{-6}$ uCi/100cm<sup>2</sup>

A radiation safety specialist should be present when this container is opened.

#### CERTIFICATIONS

SPECIAL FORM: At the time of shipment the source in this shipment met the requirements for special form.

LEAK TEST: The source in this shipment passed the helium bubble pressure leak test.

CERTIFICATE OF ORIGIN: The Cf-252 neutron source, Frontier Technology Corporation Model 100, serial number FTC-CF-4057 and the Type A shipping package, Model 50220, serial number 1279 are the product of the United States of America.

CERTIFICATE OF CONFORMANCE: The products covered by this document are certified to meet the requirements of the contract.

SHIPMENT APPROYALS: 16 August 2010

Treva L. Janzow

Projects Manager

Thermo Gamma Metrics, LLC. / PacifiCorp DJ Johnston, WY 16 August 2010

#### FRONTIER TECHNOLOGY CORPORATION RADIOACTIVE SOURCE SHIPMENT SURVEY RECORD

- A. Source Data
  - Type of source: Cf-252 1.
  - Quantity of source: 1 2.
  - Type of radiation emitted: neutron, gamma 3.
  - Source identification: FTC-CF-4057 4.

- B. Shipping Package Data
  - 1. Type A
  - 2. Model No. 50220
  - 3. Serial No. 1279
  - Approximate weight 275 lbs. (125 K.)
- C. Radiological Control
  - Container Survey contamination, microcuries/100 cm<sup>2</sup> 1. Outer Surface: alpha <9 X 10<sup>-6</sup> beta/gamma <45 x 10<sup>-6</sup>
  - Container Survey radiation, wrew/hr 1 meter from surface Surface 0.6 Gamma 10.0 Neutron 15.0 1.5

2.1 \* Total 25.0

- \*=transport index when rounded to next higher tenth, 49CFR173.389(i) Survey instruments used: Gamma: RO2 1522 Neutron: PNR4 1004
- FRONTIER TECHNOLOGY CORPORATION D. Name and address of shipper:

1641 Burnett Drive

Xenia, Ohio 45385 U.S.A.

Tel: 937/376-5691 Fax: 937/376-5692

Name and title of person generating form: Treva L. Janzow E.

Projects Manager

Thermo Gamma Metrics, LLC. /PacifiCorp DJ Johnston, WY 16 August 2010

#### FRONTIER TECHNOLOGY CORPORATION RADIOACTIVE SOURCES LEAK TEST CERTIFICATE

CURRENTLY, STATE AND FEDERALLY ISSUED RADIOACTIVE MATERIALS LICENSES DEFINE A SEALED RADIATION SOURCE AS LEAKING IF REMOVABLE CONTAMINATION IS FOUND ON THE SOURCE IN EXCESS OF 0.005 MICROCURIES.

THIS IS TO CERTIFY THAT THE FOLLOWING LISTED SOURCE HAS BEEN TESTED FOR REMOVABLE SURFACE CONTAMINATION WITH THE LEVEL OF REMOVABLE CONTAMINATION OBSERVED ON THE SOURCE SURFACE BEING AS LISTED BELOW.

#### METHOD OF TEST:

[X] DRY WIPE TEST PER PARAGRAPH A2.1.2 OF AMERICAN NATIONAL STANDARD N542; SEALED RADIOACTIVE SOURCES, CLASSIFICATION (ANSI STANDARD N542-1977, NBS HANDBOOK 126).

[ ] OTHER (DESCRIBE):

SOURCE DESCRIPTION - ISOTOPE - CONTENT as of 16 August 2010 10.3 uq. Cf-252 FTC-CF-4057

ALPHA, BETA/GAMMA TEST FOR: REMOVABLE SURFACE CONTAMINATION (MICROCURIES):

alpha <9  $\times$  10<sup>-6</sup>uCi/100 cm<sup>2</sup> beta/gamma <45  $\times$  10<sup>-6</sup>uCi/100 cm<sup>2</sup>

FROM THE RECORDED RESULTS THERE IS NO INDICATION OF LEAK IN THE SOURCE.

SIGNED BY:

TREVA L. JANZOW PRINTED NAME:

TITLE: PROJECTS MANAGER

FRONTIER TECHNOLOGY CORPORATION 1641 BURNETT DRIVE XENIA, OHIO 45385 U.S.A.

TEL: 937/376-5691 FAX: 937/376-5692



Thermo Gamma Metrics, LLC 10010 Mesa Rim Road San Diego, CA 92121 Tel: +1-800-488-4399 Fax: +1-858-546-1734 www.thermo.com

#### Field Service Activity Report (FSAR)

CUSTOMER	Pacificorp	SITE NAME Dave Johnson
SITE ADDRESS	1591 Tank Farm Rd, Coal Co. Rte	
CITY / STATE	Glenrock, WY	ZIP CODE 82637 COUNTRY USA
SITE CONTACT	Derald Anderson	TITLE Safety Manager
CONTACT TEL	(801) 220-4155	EMAIL derald.anderson@pacificorp.com
SITE ALIAS		

#### **Equipment Detail**

MODEL	CQM	SERIAL	840021 WO# 31533
PRIMARY FSE	Robin Belnap		

#### Case Detail

CASE NUMBER	00021341	ORIGINAL REQUEST DATE	12/12/2010 3:0	)1:00 PM
CASE ASSIGNED FSE	Robin Belnap		TOTAL HRS	16
SUBJECT Radia	ation Leak Test and Source Rep	olenishment		

#### Service Detail

Date	Subject	Component	Hours	
12/13/2010	Travel		7.00	
Description				
Depart Home office to customers' area				

Date	Subject	Component	Hours
12/14/2010	Travel		0.50
Description			
Depart hotel to c	ustomer's site.		

Date	Subject	Component	Hours
12/14/2010	Radiation Work		3.50
Description			

Once onsite met with key personal, Jim Ritter- Alan Dugan-Sam Evans. We discussed what was to be accomplished during visit, it was determined first and foremost that Dave Johnston stays current with their "Radiation Work" due to the fact they were out of compliance regarding leak testing.

Tasks performed during this visit were Source Replenishment, Leak Testing and Schedule PM.

# Thermo Fisher

Thermo Gamma Metrics, LLC 10010 Mesa Rim Road San Diego, CA 92121 Tel: +1-800-488-4399 Fax: +1-858-546-1734 www.thermo.com

#### SOURCE REPLENISHMENT:

- Preformed source barrel survey/leak test on new source Documentation verification: All Passed
- Run the 3 CRS for 30 minutes each, before installing the new source due to the fact we did not have any FAT files and needed to achieve a baseline.
- · Installed new source, performed leak test and radiation survey of device.
- Ran the 3 CRS 15 minutes each.
- Collect factory spectra from CRS run before new source. Collect field spectra from CRS after new source.
   LEAK TEST

Radiation Source Wipe/Contamination Leak Test

- · Radiation Source Wipe was performed during visit.
- · Performed a radiation source contamination test according to U.S. NRC guidelines.
- · Forwarded LTC to Site RSO via email

Date	Subject	Component	Hours
12/14/2010	Semi Annual PM		3.50
Description			

#### Semi-Annual PM

Hard disk diagnostics were used to determine the condition of the hard disk(s), indicating fragmentation and bad sectors

Inspection of Major Sub-System Operation and Parameters

- · Temperature set points were checked.
- Diagnostics, parameters that indicate the health and proper operation of the main detector and associated subsystem(s) were viewed and recorded.
- Data is collected to establish performance baselines and historical trends.

System Software Back-up for Restoration

· The system configuration and database were backed up

Inspect and Check Systems

- · Inspection of Basic Maintenance performed by Site
- Inspection of Mechanical and Electrical Components
- · Identification of Preventive/Planned Replacement Components
- Entire system is inspected for physical damage.
- · All filters were cleaned or replaced, as necessary.
- · Liners were inspected for wear.
- All electronics were thoroughly checked. Power supplies were checked and adjusted if necessary; cables and connections were inspected; fans were checked; all boards were inspected visually for dust buildup and heat damage; and all controls, sensors and indicators were checked. Modems, keyboards, and monitors were tested.
   Support
- Complete and maintain radiation source records and provide unlimited support regarding record keeping, documentation management, and compliance.

Date	Subject	Component	Hours
12/14/2010	travel		0.50
Description			
Depart site to Cas	•		

Date	Subject	Component	Hours
12/13/2010	Document Prep		1.00
Description			
Prepare docume	nts for visit.		

# Thermo Fisher SCIENTIFIC

Thermo Gamma Metrics, LLC 10010 Mesa Rim Road San Diego, CA 92121 Parts Required Tel: +1-800-488-4399 Fax: +1-858-546-1734 www.thermo.com

#### Customer \*

I have reviewed this report and agree with its content:

CUSTOMER SIGNATURE	DATE	CUSTOMER NAME (Please print)

<sup>\*</sup> Note: In a continual effort to provide excellent customer service we periodically survey our customers through an independent firm. If you receive a survey we appreciate the time spent to complete as your feedback is important to us.

# Attachment 3

Date of Inventory: 12-14-2010 Location: COAL YARD SOURCE LOCATION
NRC License Number: 49-27781-01 Type of Source: DENSITY
Source Model/Serial Number: Z2303 Gauge Model/Serial Number: 84002/
Manufacturer: THERMOFISHER SCIEWTIFIC.
Isotope and Initial Activity: CALIFORNIUM -252 24.3 ug
Current Isotope Activity: 4.67 yg
Status: Active X Inactive Leak Test Results**: <0.005 wCi
Samples Analyzed Using: LSC Gamma Counter Other EBERLINE 600, SHP-270, sHP-360
Leak Test Performed By: ROB BELNAP - THERMOFISHER SCIENTIFIC
**See Leak Test Certificate for additional information.
Inventory Performed By: ALAN L. Dugan Signature: Alan L. Dugan

Date of Inventory: 12-14-2010	Location: COALYARD SOURCE LOCATION
NRC License Number: <u>49-27781-01</u>	Type of Source: DENSITY
Source Model/Serial Number: <u>Z3144</u> (	Gauge Model/Serial Number: 840021
Manufacturer: THERMOFISHER Sc	IENTIFIC
Isotope and Initial Activity: CALIFORN	cum-252 10.29 ug
Current Isotope Activity: 4.42	vg .
Status: Active X Inactive	Leak Test Results**: <0.005 mCi
Samples Analyzed Using: LSC Gamm	a Counter Other <u>FBERLINE</u> 600, SHP-270, SHP-360
Leak Test Performed By: Rob Belnap	
**See Leak Test Certificate for additional info	ormation.
	,
ROB BELWAP	
Inventory Performed By: ALDL Duck	Signature: Alla Ly

Date of Inventory: 12-14-2010 Location: COAL YARD Source LOCATION		
NRC License Number: 49-27781-01 Type of Source: Dewsity		
Source Model/Serial Number: <u>V-954</u> Gauge Model/Serial Number: <u>84002</u>		
Manufacturer: THERMOFISHER SCIENTIFIC		
Isotope and Initial Activity: <u>CESIUM -137</u> IOMCi		
Current Isotope Activity: 7.63 mCi		
Status: Active X Inactive Leak Test Results**: <a href="#">XO.COSuCS</a>		
Samples Analyzed Using: LSC Gamma Counter Other EBERLINE 600, SHP-270		
Leak Test Performed By: ROB BELNAP - THERMOFISHER SCIENTIFIC		
**See Leak Test Certificate for additional information.		
Inventory Performed By: A and A Nacons Signature: Alas II		

Date of Inventory: <u>IZ-I4-ID</u> Locat	ion: COAL YARD Source LOCATION
NRC License Number: 49-27781-01 Type	of Source: Dews174
Source Model/Serial Number: 4057 Gauge	Model/Serial Number: 840021
Manufacturer: Thormofisher Sciow77	Fic
Isotope and Initial Activity: CALIFORNIUM	252 9.43
Current Isotope Activity: 9,43	
Status: Active Inactive	Leak Test Results**:
Samples Analyzed Using: LSC Gamma Co	unter Other EBERLINE 600, SHP-270
Leak Test Performed By: Rob Belnap -	
**See Leak Test Certificate for additional informa	tion.
ROB BELNAP \$	
Inventory Performed By: ALAN L. DUGAN	Signature: Man Tough