



January 11, 2011

Craig Z. Gordon
United States Nuclear Regulatory Commission
Division of Nuclear Materials Safety
Region 1
475 Allendale Road
King of Prussia, PA 19406

03038262/2010001

**RE: WATER SPRAY TESTING OF TROXLER BOXES
License No. 06-31405-01**

Dear Mr. Gordon;

Based on our discussion concerning the transport boxes containing the Troxler nuclear gauges, we have taken the follow action to correct any possible deficiencies. All four boxes were water spray tested to ensure that the epoxy sealant maintained the integrity of the boxes as far as being waterproof. A spray of water from a garden hose was directed at the sealed holes at full pressure for approximately five minutes. The boxes were then opened to reveal that no moisture had intruded the cases and the contents were dry. We will keep this test information on file for at least one year as directed. We hope that this will satisfy your requirements and as always we look forward to any suggestions that you may have. Thank you.

Respectfully submitted,

Neil T. Russo, RSO
HAKS Engineers, P.C.
36 River St.
Bridgeport, CT 06604
203-362-1552

JAN 21 2011

REC'D IN LAT _____

NMSS/RONI MATERIALS-004