

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE

NEW YORK, N. Y. 10019

(212) 397-6200

CENTRAL FILES

8004300 041

TRUSTEES

JOHN S. DYSON
CHAIRMAN

GEORGE L. INGALLS
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

FREDERICK R. CLARK



April 9, 1980
IPN-80-37

GEORGE T. BERRY
PRESIDENT & CHIEF
OPERATING OFFICER

JOHN W. BOSTON
EXECUTIVE VICE
PRESIDENT & DIRECTOR
OF POWER OPERATIONS

JOSEPH R. SCHMIEDER
EXECUTIVE VICE
PRESIDENT & CHIEF
ENGINEER

LEROY W. SINCLAIR
SENIOR VICE PRESIDENT
& CHIEF FINANCIAL
OFFICER

THOMAS R. FREY
SENIOR VICE PRESIDENT
& GENERAL COUNSEL

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
I. E. Bulletin 79-14

Dear Sir:

This letter provides the final report of the results of the Authority's field verification program required by I. E. Bulletin 79-14 for both dynamically and static span table analyzed lines in normally inaccessible areas in accordance with our December 11, 1979 letter (IPN-79-91).

The field verification program for inaccessible areas was conducted in accordance with IP3 Plant Procedures 3PT-V14, Rev. 2 (previously transmitted by IPN-79-56, dated August 7, 1979) and 3PT-V14, Rev. 3 (attached).

A complete listing of the dynamically and static span table analyzed lines in normally accessible and inaccessible areas has been transmitted to you via our May 22, 1979 (IPN-79-26) and February 25, 1980 (IPN-80-20) letter respectively.

Field inspection in inaccessible areas of all of the 130 lines and 1463 supports required has been completed. As a result of this inspection only one (1) modification was required due to the field verification effort (79-14). The modification is described in Table 1 along with the completion date.

Very truly yours,

George M. Wilbriding

for Paul J. Early
Assistant Chief Engineer-Projects

cc: Mr. T. Rebelowski, Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

TABLE 1

FIELD MODIFICATION IN
INACCESSIBLE AREAS DUE TO FIELD VERIFICATION EFFORT (79-14)

<u>LINE NO./SUPPORT NO.</u>	<u>PROBLEM</u>	<u>CORRECTIVE ACTION</u>	<u>DATE COMPLETED</u>
1. 361/SI-H-361-2-S	1 1/2" eccentricity on W 4x13	Stiffener plate installed to counterbalance eccentricity	1/11/80