

Continental Cement Company

10107 HIGHWAY 79
Hannibal, MO 63401
573/221-1740
Fax: 573/221-1689

FAX TRANSMISSION COVER SHEET

Date: 01/31/2011

FAX#: 1-630-515-1259

To: Mr. Ed. Kulzer

Re: 30 day follow-up.

Sender: Bill Sherman

YOU SHOULD RECEIVE 2 PAGE(S) INCLUDING THIS COVER SHEET.
IF YOU DO NOT RECEIVE ALL THE PAGES, PLEASE CALL (573) 221-1740

The first copy I sent had the wrong date.

**Continental Cement Co., L.L.C.**

10107 Hwy 79 So
Hannibal, MO 63401
Phone 573-221-1740
Fax 573-221-1689

January 31, 2011
Attn: Edward L. Kulzer CIH, CSP
Health Physicist
United States Nuclear Regulatory Commission Region III
2443 Warrenville Road, Suite 210
Lisle, Illinois 60532-4352

30 Day Corrective Action Follow-up Report

Dear Mr. Kulzer,

This is a follow-up letter to confirm the corrective actions that were taken in response to the "stuck shutter" incident on December 8, 2010 at Continental Cement Company L.L.C. The following actions have been taken:

Short Term: General maintenance (cleaning of clinker dust) was performed on the Berthold Technologies Model PB100 weigh belt on January 11, 2011 to ensure that the shutter will now fully open and close.


Long Term: The Continental Cement LLC Nuclear Safety Program was modified to include:

- Changes to the procurement section to include a review of license possession limits prior to ordering of any new materials and.
- Sending a copy of the current Specific License Amendment to the material provider prior to purchasing.

In addition, a memo outlining these changes has been sent to all management personnel. A copy of this report has been placed in the annual safety program audit file, and. The annual safety audit will be changed to ensure a memo of the same nature is sent to management personnel each year during the audit.

Please contact me if any of these changes are not to your approval or if additional changes are needed.

Sincerely,


William E. Sherman Jr., BSO