

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Advex Corporation 121 Floyd Thompson Drive Hampton, Virginia 23666-1307 REPORT Nos. 2011001	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415
---	--

3. DOCKET NUMBER(S) 03011069	4. LICENSE NUMBER(S) 45-16452-01	5. DATE(S) OF INSPECTION February 3, 2011
--	--	---

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Title 10 CFR 20.2206 (a) requires, in part, licensees who possess or use byproduct material for purposes of radiography, shall submit a report of individual monitoring for each individual for whom monitoring was required by 10 CFR 20.1502 during that year, and in accordance with 10 CFR 20.2206 (c), to file the report covering the preceding year, on or before April 30 of each year, to the REIRS Project Manager by an appropriate method listed in 10 CFR 20.1007, or via the REIRS website at <http://www.reirs.com>.
 Contrary to the above, ADVEX Corporation failed to submit a report of individual monitoring for the year 2009, on or before April 30, 2010. In response to this finding, the Advex Corporation agreed to submit the required report for the 2009 monitoring year, and to include the requirement in their annual program assessment and in their Outlook calendar.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	George C. Hill Jr.		2/10/2011
	ROBERT BARNETT.		2/10/2011
NRC INSPECTOR	Randolph C. Ragland, Jr.		2/10/2011
BRANCH CHIEF	Marie T. Miller		2/10/2011

SUNSI Review Completed By: / RA / R. C. Ragland Public Non-Sensitive

NRC-002