WBN2Public Resource

From: Poole, Justin

Sent: Wednesday, February 09, 2011 4:47 PM

To: Garg, Hukam; Singh, Gursharan; Darbali, Samir; Carte, Norbert

Cc: WBN2HearingFile Resource

Subject: FW: 20110204 Open Item List Master TVA Update 02-08-11.docx Attachments: 20110204 Open Item List Master TVA Update 02-08-11.docx

Justin C. Poole Project Manager NRR/DORL/LPWB U.S. Nuclear Regulatory Commission (301)415-2048

email: <u>Justin.Poole@nrc.gov</u>

From: Clark, Mark Steven [mailto:msclark0@tva.gov]
Sent: Wednesday, February 09, 2011 4:11 PM
To: Crouch, William D; Hilmes, Steven A

Cc: Poole, Justin

Subject: 20110204 Open Item List Master TVA Update 02-08-11.docx

Bill:

Please forward the attached update to Justin Poole.

Regards,

Steve

Steve Clark Bechtel Power Corp. Control Systems Watts Bar 2 Completion Project

Phone: 423.365.3007 e-mail: msclark0@tva.gov **Hearing Identifier:** Watts_Bar_2_Operating_LA_Public

Email Number: 257

Mail Envelope Properties (19D990B45D535548840D1118C451C74D7EFF544597)

Subject: FW: 20110204 Open Item List Master TVA Update 02-08-11.docx

Sent Date: 2/9/2011 4:47:02 PM **Received Date:** 2/9/2011 4:47:08 PM

From: Poole, Justin

Created By: Justin.Poole@nrc.gov

Recipients:

"WBN2HearingFile Resource" < WBN2HearingFile.Resource@nrc.gov>

Tracking Status: None

"Garg, Hukam" < Hukam. Garg@nrc.gov>

Tracking Status: None

"Singh, Gursharan" < Gursharan. Singh@nrc.gov>

Tracking Status: None

"Darbali, Samir" <Samir.Darbali@nrc.gov>

Tracking Status: None

"Carte, Norbert" < Norbert. Carte@nrc.gov>

Tracking Status: None

Post Office: HQCLSTR02.nrc.gov

Files Size Date & Time

MESSAGE 677 2/9/2011 4:47:08 PM

20110204 Open Item List Master TVA Update 02-08-11.docx 451198

Options

Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal

Expiration Date: Recipients Received:

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
001	All	All) ·	The Watts Bar Nuclear Plant FSAR red-line for Unit 2 (Agency	12/15/2009 Presentation Slides	1. Y	Closed	Closed	EICB RAI	3/12/2010	NNC 11/19/09: The FSAR contains
002	All	All) .	Are there I&C components and systems that have changed to a	12/15/2009 Presentation Slides	2. Y	Closed	Closed	EICB RAI	3/12/2010	NNC 11/19/09: The FSAR contains
003	All	All) .	Because a digital I&C platform can be configured and programmed	12/15/2009 Presentation Slides	3. Y	Closed	Closed	EICB RAI	3/12/2010	NNC 11/19/09: The FSAR contains
004	All	All) .	Please identify the information that will be submitted for each	Responder: Webb 1/13/10 Public Meeting	4. Y	Closed	Closed	EICB RAI	January 13, 2010	NNC 11/19/09: LIC-110 Rev. 1 Section
005	7.1.3.1		٣	By letter date February 28, 2008 (Agencywide Documents Access	Responder: Craig/Webb	5. Y	Closed	Closed	EICB RAI	TVA Letter dated	
006			ان پ	Amendment 95 of the FSAR, Chapter 7.3, shows that change 7.3-	By letter dated February 5, 2010: TVA provided the Unit 2	6. Y	Closed	Closed	EICB RAI	TVA Letter dated	NNC: WCAP-12096 Rev. 7
007	7.1.3.1			The setpoint methodology has been reviewed and approved by the	TVA Letter Dated March 12, 2010 (Enclosure 1, Item No. 7	7. Y	Closed	Closed	EICB RAI	TVA Letter dated	TVA to provide Rev. 8 of the Unit 1
800	7.3		٥	There are several staff positions that provide guidance on setpoint	TVA Letter Dated March 12, 2010 (Enclosure 1, Item No. 8	8. Y	Closed	Closed	EICB RAI	TVA Letter dated	
009	7.3.2	5.6,	a	Change 7.3-2, identified in Watts Bar Nuclear Plant FSAR red-line	TVA Letter Dated March 12, 2010 (Enclosure 1, Item No. 9	9. Y	Closed	Closed	EICB RAI	3/12/10,	
010	7.3	7.3	a	The original SER on Watts Bar (NUREG-0847) documents that the	TVA Letter Dated March 12, 2010 (Enclosure 1, Item No. 10	10. Y	Closed	Closed	EICB RAI	3/12/10,	
011	7.3.2	5.6,	a	NUREG-0847 Supplement No. 2 Section 7.3.2 includes an	TVA Letter Dated March 12, 2010 (Enclosure 1, Item No. 11	11. Y	Closed	Closed	EICB RAI	ML101680598,	
012	7.4	7.4	a D		TVA Letter Dated March 12, 2010 (Enclosure 1, Item No. 12	12. Y	Closed	Closed	EICB RAI	TVA Letter dated	
013	7.1.3.1		٥	Chapter 7 and Chapter 16 of Amendment 95 to the FSAR do not	TVA Letter Dated March 12, 2010 (Enclosure 1, Item No. 13	13. Y	Closed	Closed	EICB RAI	TVA Letter dated	TS have been docketed.
014	All	All			Date: 4/27/10	14. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
015					Date: 4/27/10		Closed	Closed	NRC Meeting	TVA Letter dated	
016			_O	Identify the precedents in license amendment requests (LARs), if	Date: 4/27/10	16. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
017	7.3.1	7.3.1,	a	Identify precedents in LARs, if any, for the solid state protection	Date: 4/27/10	17. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
018					Date: 4/27/10	18. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
019			٥	Verify that the containment purge isolation radiation monitor is the	Date: 4/27/10	19. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
020			٥	Provide environmental qualification information pursuant to Section	Date: 4/27/10	20. Y	Closed	Closed	NRC Meeting	TVA Letter dated	NNC 4/30/10: SRP Section 7.0 states:
021		7.3	ا پ	For the Foxboro Spec 200 platform, identify any changes in	Date: 5/25/10	21. Y	Closed	Closed	NRC Meeting	TVA Letter dated	The resolution of this item will be
022	7.3.2	5.6,	a	·	Dato: I/EI/10	22. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
023			٥	Provide environmental qualification (10 CFR 50.49) information for	Date: 4/27/10	23. Y	Closed	Closed	NRC Meeting	TVA Letter dated	NNC 4/30/10: SRP Section 7.0 states:
024			_O	Provide a schedule by the January 13, 2010, meeting for providing	During the January 13, 2010 meeting, TVA presented a	24. Y	Closed	Closed	NRC Meeting	N/A – Request for	NNC 4/30/10: Carte to address
025	7.5.2	7.5.1		For the containment radiation high radiation monitor, verify that the	Date. 1/21/10	25. Y	Closed	Closed	NRC Meeting	ML101230248,	
026			رن پ	Provide environmental qualification (10 CFR 50.49) information for	Date: 4/27/10	26. Y	Closed	Closed	NRC Meeting	TVA Letter dated	NNC 4/30/10: SRP Section 7.0 states:
027	7.7.1.4				Date: 4/27/10	27. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
028			ا پ	For the turbine control AEH system, verify that the refurbishment	Responder: Mark Scansen	28. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
029				For the rod control system, verify that the refurbishment results in a	Date: 4/27/10	29. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
030			رن پ	Regarding the refurbishment of I&C equipment, identify any	Responder: Clark	30. Y	Closed	Closed	NRC Meeting	TVA Letter dated	
031			_O	For the rod position indication system (CERPI), provide information	Date: 4/27/10	31. Y	Closed	Closed	NRC Meeting	TVA Letter dated	CERPI is non-safety related.
032			UU	For the process computer, need to consider cyber security issues	Date: 4/27/10	32. Y	Closed	Closed	NRC Meeting	TVA Letter dated	EICB will no longer consider cyber
033					Date: 4/27/10	33. Y	Closed	Closed	NRC Meeting	TVA Letter dated	The loose parts monitoring system is
034			٥	2/4/2010	Responder: TVA	34. Y	Closed	Closed	N/A	TVA Letter dated	
034.1			a - D	Chapter 7.1 – Introduction		35. Y	Closed	Closed	N/A	N/A	
034.2			٥	Chapter 7.2 - Reactor Trip System		36. Y	Closed	Closed	N/A	N/A	
034.3	7.3	7.3	a	Chapter 7.3 – ESFAS		37. Y	Closed	Closed	N/A	N/A	
034.4	7.5.1.1	7.5.2	<u></u> ≥ ø	Chapter 7.5 - Instrumentation Systems Important to Safety		38. Y	Closed	Closed	N/A	N/A	Closed
034.5	7.5.1.1	7.5.2	r o b	Chapter 7.6 - All Other Systems Required for Safety		39. Y	Closed	Closed	N/A	N/A	Closed
034.6			. p.c	Chapter 7.7 Control Systems		40. Y	Closed	Closed	N/A	N/A	
035			<u> </u>	2/18/2010	Responder: Clark	41. Y	Closed	Closed	RAI No. 1	TVA Letter dated	LIC-110 Section 6.2.2 states: "Design
036	7.5.2	7.5.1		3 ,	Date: 5/25/10	42. Y	Closed	Closed	NRC Meeting		NNC: Unit 2 FSAR Section 7.5.1, "Post
037	7.5.1.1	7.5.2	<u> ≥ </u>	2/18/2010	Responder: Clark Date: 5/25/10	43. Y	Closed	Closed	N/A	TVA Letter dated	FSAR Amendment 100 provides

No.	SE Sec.	FSAR Sec.	NRC Issue	TVA Res	ponse(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
038	7.5.1.1	7.5.2	→ ≥ [®] 2/18/2010	Responder: Clark Da	ate: 5/25/10	44. Y	Closed	Closed	EICB RAI	TVA Letter dated	The slides presented at the December
039			January 13, 2010	Responder: Clark	Date: 5/25/10	45. Y	Closed	Closed	EICB RAI	FSAR amendment	The equation for the calculation of the
040			January 13, 2010	Responder: Clark	Date: 5/25/10	46. Y	Closed	Closed	EICB RAI EICB RAI	FSAR amendment	The equation for the calculation of the
042	All	All	February 25, 2010: Telecom	Date: 5/25/10		47. Y	Closed	Closed	EICB RAI	TVA Letter dated	The drawing provided did not have the
044	7.5.2	7.5.1	February 25, 2010	Date: 5/25/10		48. Y	Closed	Closed	EICB RAI	TVA Letter dated	
045			February 25, 2010	Date: 5/25/10		49. Y	Closed	Closed	EICB RAI	TVA Letter dated	
046			February 25, 2010	Date: 5/25/10		50. Y	Closed	Closed	N/A – Request for	N/A	
047	7.5.2	7.5.1	U 4/8/2010	Responder: WEC/Hilmes	Date: 5/25/10	51. Y	Closed	Closed	EICB RAI	TVA Letter dated	
048	7.5.2	7.5.1	April 8, 2010	Date: 5/25/10		52. Y	Closed	Closed	EICB RAI	TVA Letter dated	
049	7.5.2	7.5.1	<u>4/8/2010</u>	Responder: WEC Dat	e: 5/25/10	53. Y	Closed	Closed	EICB RAI	TVA Letter dated	
050	7.5.2	7.5.1		Responder: WEC	Date: 5/25/10	54. N	Closed	Closed	EICB RAI	TVA Letter dated	NNC 11/18/10: SysRS Rev. 2 contains
051			— [©] April 15, 2010	Date: 5/25/10		55. Y	Closed	Closed	N/A	N/A	Review addressed by another Open
052	7.5.2	7.5.1	April 19, 2010	Date: 5/25/10		56. Y	Closed	Closed	RAI No. 12		
053	7.5.2	7.5.1	April 19, 2010	Date: 5/25/10		57. Y	Closed	Closed	RAI No. 13		
054	7.5.2	7.5.1	<u></u>	Responder: Slifer/Clark	Date: 5/25/10	58. Y	Closed	Closed	RAI No. 14	TVA Letter dated	
055	7.5.2	7.5.1	〜∽ · 4/19/2010	Responder: Slifer/Clark	Date: 5/25/10	59. Y	Closed	Closed	RAI No. 15	TVA Letter dated	
056			April 19, 2010	Date: 5/25/10		60. Y	Closed	Closed	RAI No. 16	TVA Letter dated	Sorrento Radiation Monitoring
057	7.5.2	7.5.1		Responder: TVA I&C Staff	Date: 5/25/10	61. Y	Closed	Closed	RAI No. 17	TVA Letter dated	
058	7.5.0	7.5	_ o . April 19, 2010	Date: 5/25/10		62. Y	Closed	Closed	RAI No. 18	TVA Letter dated	
059	7.5.2	7.5.1	April 19, 2010	Date:		63. Y	Closed	Closed	RAI No. 19	TVA Letter dated	
060	7.5.2	7.5.1	April 19, 2010	Date: 5/25/10		64. Y	Closed	Closed	N/A	N/A	Addressed by Open Item No. 47
061	7.5.2	7.5.1	April 19, 2010	Date: 5/25/10		65. Y	Closed	Closed	N/A	N/A	Addressed by Open Item No. 48
062	7.5.2	7.5.1	April 19, 2010	Date: 5/25/10		66. Y	Closed	Closed	N/A	N/A	Addressed by Open Item No. 49
063	7.5.2	7.5.1	April 19, 2010	Date: 5/25/10		67. Y	Closed	Closed	N/A	N/A	Addressed by Open Item No. 50
064	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal		72010		Closed			TVA Letter dated	
065	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal		te: 5/25/10	69. Y	Closed	Closed	N/A - No question	TVA Letter dated	
066	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal	Responder: WEC	Date: 5/25/10	70. Y	Closed	Closed	N/A - No question	TVA Letter dated	
070	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal	Responder: WEC	Bato: 0/20/10		Closed	Closed	N/A - No question	TVA Letter dated	NNC 11/23/10: The dues date in this
071	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal	•	7. G/2G/10		Closed		-	N/A	NNC 11/23/10: The dues date in this
072	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal		Date: 5/25/10	73. Y	Closed	Closed	N/A - No question	N/A	
073	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal	Responder: WEC	Date: 5/25/10	74. N	Closed	Closed	N/A - No question	N/A	
075	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal		Pate: 5/25/10	75. N	Closed	Closed	N/A - No question	N/A	
076	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal		Date: 5/25/10	76. Y	Closed	Closed	N/A - No question	N/A	
077	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal	Responder: WEC	20.00.07207.0		Closed	Closed	N/A - No question	TVA Letter dated	
078			⁻ ⁻ 4/26/2010	Responder: Clark	Date: 5/25/10	78. Y	Closed	Closed	EICB RAI	TVA Letter dated	
079				Responder: Clark	Date: 5/25/10	79. Y	Closed	Closed	EICB RAI	TVA Letter dated	Reviewed under Item 154
080				Responder: WEC		80. Y	Closed	Closed	RAI No. 2	TVA Letter dated	
083	7.5.2	7.5.1	<u></u> Мау 6, 2010	Date: 6/18/10			Closed	Closed	EICB RAI	TVA Letter dated	
084	7.5.2	7.5.1	<u></u> May 6, 2010	Date: 6/18/10		82. Y	Closed	Closed	EICB RAI	TVA Letter dated	
085	7.5.2	7.5.1	5/6/2010	Responder: WEC		83. N	Closed	Closed	EICB RAI		
087	7.5.2	7.5.1	_ ∽ · May 6, 2010	Date: 5/24/10			Closed	Closed	RAI No. 20	TVA Letter dated	
088	7.5.2	7.5.1	_ ∽ ⋅ May 6, 2010	Date: 5/24/10		85. Y	Closed	Closed	RAI No. 21	TVA Letter dated	
089			5/6/2010	Responder: Clark		86. Y	Closed	Closed	EICB RAI	TVA Letter dated	NNC: Docketed response states that

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
090			_0	5/6/2010	Responder: Clark Date: 5/25/10	87. Y	Closed	Closed	EICB RAI	TVA Letter dated	
091	7.4	7.4	- D &	May 20, 2010	Date: 5/25/10	88. Y	Closed	Closed	EICB RAI No.1	TVA Letter dated	
093			ں ت	May 20, 2010	Date: 5/25/10	89. Y	Closed	Closed	N/A	N/A	Will be reviewed under item 154
094			٥٥		Responder: Clark Date: 5/25/10	90. Y	Closed	Closed	N/A	N/A	Information was found in FSAR
095	7.8.1,	XX	a	May 20, 2010	Date:	91. Y	Closed	Closed	EICB RAI No. 2	TVA Letter dated	
096	7.7.5	XX	a	5/20/2010	Responder:	92. Y	Closed	Closed	EICB RAI No.3	TVA Letter dated	
097	7.4.2	7.4	a	May 20, 2010	Date:	93. Y	Closed	Closed	EICB RAI No.4	TVA Letter dated	
098	7.4.2	7.4	a	May 25, 2010	Date:	94. Y	Closed	Closed	EICB RAI No.5	TVA Letter dated	
099			a B	April 12, 2010	Date:	95. Y	Closed	Closed			Closed to Item 129
100				5/20/2010	Responder: WEC	96. Y	Closed	Closed	N/A - No question	N/A	
102					Date: 5/24/10	97. Y	Closed	Closed	N/A	TVA Letter dated	Request for schedule not information.
103	7.4	7.4	a D-	5/27/2010	Responder: Ayala Date: 5/27/10	98. Y	Closed	Closed	EICB RAI No.1	TVA Letter dated	Submittal date is based on current
104	7.4	7.4		5/27/2010	Responder: Merten Date: 5/27/10	99. Y	Closed	Closed	EICB RAI No.1	TVA Letter dated	Submittal date is based on current
105				April 29, 2010	240.		Closed	Closed	N/A	N/A	Will be reviewed under item 154.
106				May 6, 2010	Date: 5/25/10	101. Y	Closed	Closed	RAI No. 9	TVA Letter dated	
107				May 6, 2010	Date: 5/28/10	102. Y	Closed	Closed	RAI No. 22	TVA Letter dated	
108			۳	May 6, 2010	Date: 5/25/10	103. Y	Closed	Closed	N/A	N/A	Will be reviewed under Ol#154
109.b					Responder: N/A	104. Y	Closed	Closed	N/A	N/A	Duplicate of another open Item.
109.a	7.8	XX			Responder: N/A	105. Y	Closed	Closed	N/A	N/A	
110				May 6, 2010	Date:		Closed	Closed	N/A	N/A	Information was found.
111				May 6, 2010	Date: 5/28/10	107. Y	Closed	Closed	N/A	TVA Letter dated	Request to help find, not a request for
112				June 1, 2010	Date:	108. Y	Closed	Closed	N/A	N/A	Information was received
113				6/1/2010	Responder: Clark	109. Y	Closed	Closed	EICB RAI	TVA Letter dated	
114	7.2	7.2		6/1/2010	Responder: WEC	110. Y	Close	Closed	EICB RAI	TVA Letter dated	
115			_O		Responder: Clark		Closed	Closed	EICB RAI	TVA Letter dated	
116					Responder: WEC	112. Y	Closed	Closed	EICB RAI	TVA Letter dated	Letter sent to Westinghouse requesting
117	7.1	7.1		6/3/2010	Responder: Hilmes	113. Y	Closed	Closed	EICB RAI	TVA Letter dated	
118	7.4	7.4			Responder: Merten	114. Y	Closed	Closed	EICB RAI No.1	TVA Letter dated	Submittal date is based on current
119				June 10, 2010	Date:	115. Y	Closed	Closed	RAI No. 23	TVA Letter dated	
120				5/6/2010	Responder: Hilmes/Merten/Costley	116. Y	Closed	Closed	EICB RAI	TVA Letter dated	
121			_O	5/6/2010	Responder: Webb/Webber	117. Y	Closed	Closed	EICB RAI	TVA Letter dated	
122				June 14, 2010	Date:	118. Y	Closed	Closed	N/A - Request for	N/A	
123	7.7.3	7.4.1,		6/14/2010	Responder:	119. Y	Closed	Closed	ML101720589,	TVA Letter dated	
124	7.7.5			6/14/2010	Responder:	120. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	
125	7.7.8				Responder:	121. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	
126	7.8	7.8		June 14, 2010	2.1.0.		Closed	Closed	ML101720589, Item	TVA Letter dated	
127	7.2	7.2		6/16/2010	Responder: WEC/Clark	123. Y	Closed	Closed	EICB RAI	TVA Letter dated	
128	7.2	7.2			Responder: WEC Drake /TVA Craig	124. Y	Closed	Closed	EICB RAI	TVA Letter dated	Track through SE open item
129			<u> </u>	6/12/2010	Responder: WEC		Closed	Closed	N/A	TVA Letter dated	
130				6/28/2010	Responder: Clark	126. Y	Closed	Closed	N/A	TVA Letter dated	
131				6/28/2010	Responder: Clark	127. Y	Closed	Closed	N/A	TVA Letter dated	
132			<u></u>	6/28/2010	Responder: Clark	128. Y	Closed	Closed	N/A	TVA Letter dated	
133				6/28/2010	Responder: Clark	129. Y	Closed	Closed		TVA Letter dated	

			Tologon With TV/T(100 onaptor 7 only)		1		1		•	- The second of
No.	SE Sec.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
134			<u> </u>	Responder: Clark	130. Y	Closed	Closed		TVA Letter dated	
135	7.3.1	7.3.1	^{СС 05} 6/30/2010	Responder: Clark	131. Y	Closed	Closed	RAI not necessary	TVA Letter dated	
136	7.3.2,	7.4, 5.6,	^{СС 05} 6/30/2010	Responder: Clark	132. Y	Closed	Closed	RAI not necessary	TVA Letter dated	
137			Several WBN2 PAMS documents contain a table titled, "Document	Responder: WEC	133. Y	Closed	Closed	ML101650255, Item	TVA Letter dated	
139			The WBN2 PAMS System Requirements Specification (WBN2	Responder: WEC	134. Y	Closed	Closed	ML101650255, Item	TVA Letter dated	WBN2 PAMS System Requirements
140			The first requirement in the WBN2 PAMS SysRS (i.e., R2.2-1)	Responder: Clark	135. N	Closed	Closed	ML101650255, Item	TVA Letter dated	WBN2 PAMS System Requirements
141			Deleted by DORL	Date:	136. Y	Closed	Closed	ML101650255, Item		WBN2 PAMS System Requirements
146			6/17/2010	Responder:	137. Y	Closed	Closed	ML101650255, Item		PAMS System Requirements
147			6/17/2010	Responder:	138. Y	Closed	Closed	ML101650255, Item		PAMS System Requirements
148			6/17/2010	Responder:	139. Y	Closed	Closed	ML101650255, Item		PAMS System Requirements
149	7.2	7.2	FSAR Section 7.1.1.2(2), Overtemperature delta T and	Responder: Tindell	140. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
150	7.2	7.2	col	Responder: Clark	141. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
151	7.2	7.2	Provide the EDCR 52378 and 54504 which discusses the basis for	Responder: Clark	142. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
152	7.2	7.2	Deleted portion of FSAR section 7.2.3.3.4 and moved to FSAR	Responder: Merten/Clark	143. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
153	7.2	7.2	FSAR section 7.2.1.1.7 added the reference to FSAR section	Responder: Craig/Webb	144. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
154	7.2	7.2	FSAR section 7.2.1.1.10, setpoints: NRC staff has issued RIS	Responder: Craig/Webb	145. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	EICB RAI ML102861885 sent to DORL
155	7.2	7.2	Summary of FSAR change document section 7.2 states that	Date:	146. Y	Closed	Closed	ML101720589, Item		
156	7.2	7.2	FSAR section 7.2.2.1.1 states that dashed lines in Figure 15.1-	Responder: WEC	147. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	Response on hold pending
157	7.2	7.2	FSAR section 7.2.2.1.1, fifth paragraph was deleted except for the	Responder: Tindell	148. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
158	7.2	7.2	FSAR section 7.2.2.1.1, paragraph six was changed to state that	Responder: Tindell	149. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	
159	7.2	7.2	FSAR section 7.2.2.1.2 discusses reactor coolant flow	Responder: Craig	150. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
160	7.2	7.2	FSAR section 7.2.2.2(7) deleted text which has references 12 and	Responder: Tindell	151. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
161	7.2	7.2	FSAR section 7.2.2.3 states that changes to the control function	Responder: Clark	152. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	
162	7.2	7.2	FSAR section 7.2.2.2(14) states that bypass of a protection	Responder: Tindell	153. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	
163	7.2	7.2	Deleted by DORL	Date:	154. Y	Closed	Closed	ML101720589, Item		
164	7.2	7.2	FSAR section 7.2.2.2(20) has been revised to include the plant	Responder: Perkins	155. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	Item No. 8 sent to DORL
165	7.2	7.2	,	Responder: Clark	156. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	
166	7.2	7.2	Changes to FSAR section 7.2.2.2(20) are justified based on the	Responder: Clark	157. Y	Closed	Closed	ML101720589, Item	TVA Letter dated	
167	7.2	7.2	FSAR section 7.2.2.4, provide an analysis or reference to chapter	Responder: Clark	158. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
168	7.2	7.2		Responder: Clark	159. Y	Close	Closed	ML101720589, Item	TVA Letter dated	
169				Responder: Clark	160. Y	Closed	Closed			
170			⁶ /17/2010	Responder: Clark	161. Y	Closed	Closed			
171	7.2	7.2		Responder: Craig	162. Y	Closed	Closed	EICB RAI	TVA Letter dated	Closed to SE Open Item
172				Responder: Craig	163. Y	Closed	Closed	EICB RAI		
173	7.1	7.1		Responder: Craig/Webb/Powers	164. Y	Closed	Closed	EICB RAI		
174				Responder: Hilmes/Craig	165. Y	Closed	Closed	EICB RAI		
175				Responder:	166. Y	Closed	Closed	EICB RAI		
176	7.1	7.1		Responder: Craig/Webb	167. Y	Closed	Closed	EICB RAI		
177	7.5.2.1	7.5.1		Responder: Clark	168. Y	Closed	Closed	N/A	TVA Letter dated	RAI not required
	7.5.2.1	7.5.1		Responder: Clark	169. Y	Closed	Closed	N/A	TVA Letter dated	RAI not required
179				Responder: WEC	170. Y	Closed	Closed	N/A – Closed to	NA	
180				Responder: WEC	171. Y	Closed	Closed		NA	
181			An emphasis is placed on traceability in System Requirements	Responder: WEC	172. Y	Closed	Closed	N/A – Closed to	NA	

No.	SE Sec.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
182			Characteristics that the SRP states that a Software Requirements	Responder: WEC	173. Y	Closed	Closed	N/A – Closed to	NA	
184			7/15/2010	Responder: WEC	174. Y	Closed	Closed	N/A – Closed to	N/A	
186	7.7.8	7.7.1.12	7/15/2010	Responder: Perkins/Clark	175. Y	Closed	Closed	EICB RAI No.6	TVA Letter dated	
187				Responder: Merten	176. N	Closed	Closed	ML101970033, Item	TVA Letter dated	Are these connections already
188			By letter dated June 30, 2010, TVA docketed, "Tennessee Valley	Responder: Clark	177. Y	Closed	Closed	ML101970033, Item	TVA Letter dated	
189		7.6.7	~ · 7/20/2010	Responder: Clark	178. Y	Closed	Closed	RAI No. 3	TVA Letter dated	
190	7.9		FSAR Table 7.1-1 states: "Regulatory Guide 1.133, May 1981	Responder: Clark	179. Y	Closed	Closed	RAI No. 4	TVA Letter dated	Closed to OI-331.
191	7.9		NUREG-0800 Chapter 7, Section 7.9, "Data Communication	Responder: Jimmie Perkins	180. Y	Closed	Closed	ML10197016, Item	TVA Letter dated	
192	7.5.1.1	7.5.2	The NRC Staff is using SRP (NUREG-0800) Chapter 7 Section	Responder: Clark	181. Y	Closed	Closed	Item No. 1 sent to	TVA Letter dated	EICB RAI ML1028618855 sent to
193	7.5.1.1	7.5.2	The WBU2 FSAR, Section 7.5.2, "Plant Computer System,"	Responder: Clark	182. Y	Closed	Closed	Item No. 2 sent to	TVA Letter dated	EICB RAI ML1028618855 sent to
194	7.5.1.1	7.5.2.1	→ [™] The WBU2 FSAR Section 7.5.2.1, "Safety Parameter Display	Responder: Costley/Norman	183. Y	Closed	Closed	Item No. 3 sent to	TVA Letter dated	EICB RAI ML1028618855 sent to
195	7.5.1.1	7.5.2.2	→ ≥ rd Bypassed and Inoperable Status Indication (BISI)	Responder: Costley/Norman	184. Y	Closed	Closed	Item No. 4 sent to	TVA Letter dated	EICB RAI ML1028618855 sent to
196	7.5.1.1	7.5.2.2	→ ≥ rd Bypassed and Inoperable Status Indication (BISI)	Responder: Costley/Norman	185. Y	Closed	Closed	Item No. 5 sent to	TVA Letter dated	EICB RAI ML1028618855 sent to
197			Open Item 197 was never issued.		186. Y	Closed	Closed			
198	7.5.1.1	7.5.2.2	SRP Section 7.5, Subsection III, "Review Procedures" states:	Responder: Costley/Norman	187. Y	Closed	Closed	Item No. 6 sent to	TVA Letter dated	EICB RAI ML1028618855 sent to
199	7.5.1.1	7.5.2.3	The WBU2 FSAR Section 7.5.2.3, "Technical Support Center and	Responder: Costley/Norman	188. Y	Closed	Closed	Item No. 7 sent to	TVA Letter dated	Related SE Section 7.5.5.3 EICB RAI
200	7.2		7/21/2010	Responder: Clark	189. Y	Closed	Closed	EICB RAI	TVA Letter dated	
201	7.7.1.1	7.7.11	7/21/2010	Responder: Webb	190. Y	Closed	Closed	EICB RAI	TVA Letter dated	
203	7.5.1.1	7.5.2	~≥ [®] 7/26/2010	Responder: Clark	191. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
204	7.5.1.1	7.5.2	~≥ [®] 7/26/2010	Responder: Costley/Norman	192. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
205				Responder: Clark	193. Y	Closed	Closed	EICB RAI	TVA Letter dated	Question B related to prior NRC
206	7.5.1.1	7.5.2	~ ≥ [®] 7/27/2010	Responder: Clark	194. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
207			July 27, 2010	Date:	195. Y	Closed	Closed			
208	7.5.2.1	7.5.1		Responder: Clark	196. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
	7.5.2.1			Responder: Clark	197. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
210	7.5.2.1			Responder: Clark	198. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
211	7.5.1.1			Responder: Clark	199. Y	Closed	Closed	EICB RAI	TVA Letter dated	Relates to SE Sections:
214			7/27/2010	Responder: WEC	200. Y	Closed	Closed	EICB RAI	TVA Letter dated	
215				Responder: WEC	201. Y	Closed	Closed			
216	7.5.1.1	7.5.2		Responder: Clark	202. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
217			^で 7/6/2010	Responder: Clark	203. Y	Close	Closed	EICB RAI	TVA Letter dated	
218				Responder: Clark	204. Y	Closed	Closed	EICB RAI	TVA Letter dated	
219				Responder: TVA Licensing	205. Y	Closed	Closed	EICB RAI		
220				Responder: Ayala	206. Y	Closed	Closed	EICB RAI	TVA Letter dated	
221	7.7.1.2	7.7.1.3		Responder: Trelease	207. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
222			⁻ 8/4/2010	Responder: Clark	208. Y	Close	Closed	EICB RAI	TVA Letter dated	
223			⁻ 8/4/2010	Responder: Clark	209. Y	Closed	Closed	EICB RAI		
224	7.5.1.1	7.5.2	∠≥ [®] 8/4/2010	Responder: Norman (TVA CEG)	210. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
225			⁻ 8/4/2010	Responder: Scansen	211. Y	Close	Closed	EICB RAI	TVA Letter dated	
226				Responder: TVA Licensing	212. Y	Closed	Closed	N/A – Information	TVA Letter dated	See also Open Item Nos. 41 & 270.
227			^{- 0} 8/4/2010	Responder: Clark	213. Y	Close	Closed	EICB RAI	TVA Letter dated	
228			~ ^O 8/4/2010	Responder: Clark	214. Y	Closed	Closed	EICB RAI	TVA Letter dated	
229			8/4/2010	Responder: Clark	215. Y	Closed	Closed	EICB RAI	TVA Letter dated	

No.	SE Sec.	FSAR Sec.	POC	ssue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
230			○ ^O 8/4/2010		Responder: Webb	216. Y	Closed	Closed	EICB RAI	TVA Letter dated	
231			^{ت ن} 8/4/2010		Responder: Clark	217. Y	Closed	Closed	EICB RAI	TVA Letter dated	
232			<i>∽</i> · 8/4/2010		Responder: Clark	218. Y	Closed	Closed	RAI No. 5	TVA Letter dated	
233			○ ^O 8/4/2010		Responder: Clark	219. Y	Closed	Closed	EICB RAI	TVA Letter dated	
234			○ ^O 8/4/2010		Responder:	220. Y	Closed	Closed	N/A – Duplicate	N/A	
235			8/4/2010		Responder: TVA Licensing	221. Y	Closed	Closed	N/A	N/A	
236			8/4/2010		Responder: Clark	222. Y	Close	Closed	EICB RAI	TVA Letter dated	
237			○ ^O 8/4/2010		Responder: Clark	223. Y	Closed	Closed	EICB RAI	TVA Letter dated	
238			O 8/4/2010		Responder: Webb/Hilmes	224. Y	Closed	Closed	N/A – Duplicate	N/A	
239			8/4/2010		Responder: Hilmes	225. Y	Closed	Closed	N/A – Meeting	N/A	
240			^O 8/4/2010		Responder: Clark	226. Y	Close	Closed	MI102910008	TVA Letter dated	
241			<i>∽</i> · 8/4/2010		Responder: Davies	227. Y	Closed	Closed	RAI No. 10	TVA Letter dated	
242			^{— ©} 8/4/2010		Responder: Hilmes	228. Y	Close	Closed	EICB RAI	TVA Letter dated	
243			8/3/2010		Responder: WEC	229. Y	Closed	Closed	N/A – Closed to	N/A	
247			○ ^O 8/8/2010		Responder: WEC	230. Y	Closed	Closed	EICB RAI	Response is	LIC-101 Rev. 3 Appendix B Section 4,
248			○ ^O 8/8/2010		Responder: WEC	231. Y	Closed	Closed		Response is	LIC-101 Rev. 3 Appendix B Section 4,
249			8/8/2010		Responder: WEC	232. Y	Closed	Closed			LIC-101 Rev. 3 Appendix B Section 4,
253			8/8/2010		Responder: Clark	233. Y	Closed	Closed		TVA Letter dated	Related to Open Item no. 83.
254			O 8/10/2010		Responder: WEC	234. Y	Closed	Closed	N/A - Request to	TVA Letter dated	
255			O 8/10/2010		Responder: WEC	235. Y	Closed	Closed	N/A - Request to	TVA Letter dated	
256			8/10/2010		Responder: WEC	236. Y	Closed	Closed	N/A - Request to	TVA Letter dated	
257			8/10/2010		Responder: WEC	237. Y	Closed	Closed	N/A - Request to	N/A	
258			○ ^O 8/10/2010		Responder: WEC	238. Y	Closed	Closed	N/A - Request to	N/A	
259			8/10/2010		Responder: WEC	239. Y	Closed	Closed	N/A - Request to	TVA Letter dated	
260			O 8/10/2010				Closed	Closed	N/A - Request to	N/A	
261			8/10/2010		Responder: WEC	241. Y	Closed	Closed	N/A – Closed to	TVA Letter dated	LIC-110 Rev. 1 Section 6.2.2 states:
262			○ ^O 8/10/2010		Responder: WEC	242. Y	Closed	Closed	N/A - Request to	N/A	
263			O 8/11/2010		Responder: WEC	243. Y	Closed	Closed	ML101650255, Item		
264			8/11/2010		Responder: WEC	244. Y	Closed	Closed	ML101650255, Item		
265			O 8/11/2010		Responder: WEC	245. Y	Closed	Closed	ML101650255, Item		
266			○ ^O 8/11/2010		Responder: Webb/Webber	246. Y	Closed	Closed		TVA Letter dated	
267			8/11/2010		Responder: WEC	247. Y	Closed	Closed			
268			8/19/2010		Responder: WEC	248. N	Closed	Closed			
269			<u> </u>		Responder: NRC	249. Y	Closed	Closed	N/A	N/A	
270			○ ^C 8/23/2010		Responder: Clark	250. Y	Closed	Closed			See also Open Item Nod. 41 & 245.
271			© 8/23/2010		Responder: WEC	251. Y	Closed	Closed	N/A – Closed to	NA	
272	7.5.2.1	7.5.1	_ ≥ ¹⁰ 8/26/2010		Responder: Clark	252. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
273	7.5.2.1		_ ≥ ¹⁰ 8/26/2010		Responder: Clark	253. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
274.a	7.5.2.1	7.5.1	_ ≥ ¹⁰ 8/26/2010		Responder: Clark	254. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
274.b			<i>∽</i>		Responder: Stockton	255. Y	Closed	Closed	RAI No. 6	TVA Letter dated	
275			~ · 8/27/2010		Responder: Clark	256. Y	Closed	Closed	Not Required	N/A	
276	7.6	7.6	ー ^で 8/27/2010		Responder: Webb	257. Y	Closed	Closed	EICB RAI	TVA Letter dated	
277	7.6	7.6.3	^{— ©} 8/27/2010		Responder: Clark	258. Y	Close	Closed	EICB RAI	TVA Letter dated	

		T			Response		1			
No.	SE Sec.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
278	7.6	7.6.6	8/27/2010	Responder: Trelease	259. Y	Close	Closed	EICB RAI	TVA Letter dated	
279	7.6	7.6.6		Responder: Mather	260. Y	Close	Closed	EICB RAI	TVA Letter dated	
280	7.6	7.6.6		Responder: Trelease	261. Y	Closed	Closed	EICB RAI	TVA Letter dated	
282	7.6	7.6.9	8/27/2010	Responder: Trelease	262. Y	Close	Closed	EICB RAI	TVA Letter dated	
283	7.7.5	XX	8/27/2010	Responder: Clark	263. Y	Closed	Closed	EICB RAI No.13	TVA Letter dated	This item is a follow-up question to item
284	7.7.3	7.4.1	8/27/2010	Responder: Webber	264. Y	Closed	Closed	EICB RAI No.14	TVA Letter dated	This item is a follow-up question to item
285	7.3.3	7.3	8/27/2010	Responder: McNeil	265. Y	Closed	Closed	EICB RAI No.15	TVA Letter dated	This item is a follow-up question to item
286	7.7.3	9.3.4.2.	[□] [©] 8/27/2010	Responder: Webber	266. Y	Closed	Closed	EICB RAI No.16	TVA Letter dated	
287	7.3	7.3-1		Responder: Elton	267. Y	Closed	Closed	ML102390538, Item	Response	
288	7.3			Responder: McNeil	268. Y	Closed	Closed	EICB RAI		
289			<i>∽</i> · 9/2/2010	Responder: Faulkner	269. Y	Closed	Closed	RAI No. 24	TVA Letter dated	
290		7.7	9/7/2010	Responder: Clark	270. Y	Closed	Closed	N/A	N/A	This item is a duplicate of item 291.
291		7.7	9/7/2010	Responder: Clark	271. Y	Closed	Closed		TVA Letter dated	
292	7.2.5	7.2	9/7/2010	Responder: Craig	272. Y	Closed	Closed	EICB RAI	TVA Letter dated	
293	7.7.4	7.2.2.3.	→ ≥ [∞] 9/8/2010	Responder: Craig	273. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
294	7.3	7.3.1.1.	9/9/2010	Responder: Elton	274. Y	Closed	Closed	ML102390538, Item	Response	
295	7.3	7.3.1.1.	P ™ 9/9/2010	Responder: Elton	275. Y	Closed	Closed	ML102390538, Item	Response	
296	7.3	7.3.1.2.	P ™ 9/9/2010	Responder: Elton	276. Y	Closed	Closed	ML102390538, Item	Response	
297	7.3	7.3.1.2.	□ [®] 9/9/2010	Responder: Elton	277. Y	Closed	Closed	ML102390538, Item	Response	
298	7.3		[□] [©] 9/9/2010	Responder: Clark	278. Y	Closed	Closed	ML102390538, Item	Response	
299			Provide Common Q Software Requirements Specification Post	Attachment 41 of the 10/5 letter contains the Common Q	279. Y	Closed	Closed		TVA Letter dated	
300			Need Radiation Monitoring System Description/Design Criteria	Responder: Temples/Mather	280. Y	Closed	Closed	RAI No. 25	TVA Letter	
301			1.TVA is requested to address the consequences of software	Responder: WEC/Davies/Clark	281. Y	Closed	Closed	RAI No. 11	TVA Letter dated	Note 1:
302	7.5.2.1	7.5.1	~ ≥ ® 09/17/2010	Responder: Tindell	282. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
303	7.5.2.1	7.5.1	~ ≥ ® 09/17/2010	Responder: Tindell	283. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
304	7.5.2.1	7.5.1		Responder: Tindell	284. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
305	7.5.2.1	7.5.1	~ ≥ ® 09/17/2010	Responder: Tindell	285. Y	Closed	Closed	EICB RAI	TVA Letter dated	EICB RAI ML102861885 sent to DORL
306	7.1	7.1	FSAR amendment 100, page 7.1-12 provides the definition of	Responder: Hilmes	286. Y	Closed	Closed	EICB RAI	TVA Letter dated	
307	7.1	7.1	(1)	Responder: Hilmes	287. Y	Closed	Closed	EICB RAI	TVA Letter dated	
308	7.1	7.1	(1) FSAR Amendment 100, Section 7.1, page 7.1-13, definition of	Responder: Hilmes	288. Y	Closed	Closed	EICB RAI	TVA Letter dated	
309	7.1	7.1.2.1.	(1) FSAR amendment 100, Page 7.1-14, Westinghouse setpoint	Responder: Hilmes	289. Y	Closed	Closed	EICB RAI	TVA Letter dated	
310	7.1	7.1.2.1.		Responder: Hilmes	290. Y	Closed	Closed	EICB RAI	TVA Letter dated	
311	7.1	7.1		Responder: Hilmes	291. Y	Closed	Closed	EICB RAI	TVA Letter dated	
312		7.0	6.0	Responder: Stockton	292. Y	Close	Closed	EICB RAI	TVA Letter dated	
313	7.7.8	7.7.1.12		Responder: Ayala	293. Y	Closed	Closed	EICB RAI No.18	TVA Letter dated	
314	7.3	7.3		Responder: Stockton	294. Y	Closed	Closed	EICB RAI No. 19	TVA Letter dated	Related to OI 10
315	7.5.3	7.5.3		Responder: S. Smith (TVA Operations)	295. Y	Close	Closed		TVA Letter dated	
	7.5.2.3	7.5		Responder: Temples/Mather		Closed	Closed	RAI No. 26		
	7.5.2.3	7.5		Responder: Temples	297. Y	Closed	Closed		TVA Letter dated	
	7.5.2.3	7.5		Responder: Temples	298. Y	Closed	Closed		TVA Letter dated	
320				Responder: Clark		Closed	Closed		N/A	Duplicate of item 156
321				Responder: Clark		Closed	Closed		N/A	Duplicate of OI# 157
322		7.7.1.11				Closed	Closed			
7==			Section 1 of the provide				000			

324 325		Sec.	POC Issue	TVA Response(s)	Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
			→ ≥ ® Per the NRC reviewer, the BISI calculation is not required to be		302. Y	Closed	Closed			
000			The Unit 2 loops in service for Unit 1 that are scheduled to be	Responder: TVA Startup Olson	303. Y	Closed	Closed			Closed to open item ?
326			TVA uses double-sided methodology for as-found and as-left	Responder: Webb	304. Y	Closed	Closed		TVA Letter dated	
328 7.	7.5.2.3	7.5	Provide the model number for the four containment high range	Responder: Temples	305. Y	Closed	Closed	RAI No. 30	TVA Letter dated	
329	7.6.1	7.6.7	Section 7.6.7 of the FSAR (Amendment 100) states that, "The	Responder: Clark	306. Y	Closed	Closed	RAI No. 1	TVA Letter dated	
330	7.3	7.3	Related to Item 298	Responder: Hilmes/Faulkner	307. Y	Closed	Closed	EICB RAI No.20	Item 7, TVA letter	
331	7.6.1	7.6.7	As a follow up of OI 190, Staff has reviewed the proprietary version	Responder: WEC/Harless/Clark	308. Y	Closed	Closed	RAI No. 8	TVA Letter dated	Follow-up of OI-190.
332 7.	7.5.2.1	7.5.1	~≥ [®] 10/26/2010		309. Y	Closed	Closed	ML103000105 Item	TBD	EICB RAI ML103000105 sent to DORL
333 7.	7.5.2.1	7.5.1	~ ≥ [®] 10/27/2010		310. Y	Closed	Closed	ML103000105 Item	TBD	EICB RAI ML103000105 sent to DORL
336 7.	7.5.2.3	7.5	で · Re: RM-1000 Report 04508905-QR	Responder: GA	311. Y	Closed	Closed			
337 7.	7.5.2.3	7.5	ー Re: RM-1000 Report 04508905-QR	Responder: GA	312. Y	Closed	Closed			
342 7.	7.5.2.3	7.5	Please confirm that RM-1000 monitors and the associated	The RM-1000 containment high range radiation monitors are	313. Y	Closed	Closed			
343 7.	7.5.2.3	7.5	Seismic RRS in the 04508905-QR report Figures 3-2 and 3-3	(1) The cause of the difference between the RRS and TRS	314. Y	Closed	Closed			
068	7.5.2	7.5.1		Responder: WEC Date: 5/25/10 The following status is from the revised WB2 Common Q PAMS ISG-6 Compliance Matrix submitted in response to Item 43: a. Al687, Al688 – Scheduled for September 28, 2010 b. Upgraded PC node box – Per Westinghouse letter WBT-D-2024 (Reference 7), this item is available for audit at the Westinghouse Rockville office. c. Flat panel displays – Per Westinghouse letter WBT-D-2024 (Reference 7), this item is available for audit at the Westinghouse Rockville office. d. Power supplies – Per Westinghouse letter WBT-D-2035 (Reference 12), these items are available for audit at the Westinghouse Rockville office. To be addressed during 9/20-9/21 audit TVA Response to Follow-up NRC Request: For the commercial grade dedication process, please see the response to Request for Additional Information (RAI) item 3 in this letter, NRC Matrix Item 067. The component level EQ/Seismic summary reports for the hardware listed above are available for NRC review/audit as described below: (1) Al687 and Al688, the following documents were submitted in TVA Letter to NRC dated October 26, 2010, "Watts Bar Nuclear Plant (WBN) Unit 2 – Instrumentation and Controls Staff Information Requests," (Reference 5): a. EQ-EV-62-WBT, Revision 0, "Common Q PAMS Comparison of Tested Conditions for the Al687 and Al688 Common Q Modules and Supporting	1. N	Response included in letter dated 12/22/10. This item is addressed in Rev. 2 of the Licensing Technical Report	NNC 2/2/11: Commercial grade dedication will be addressed at the next	N/A - No question was asked. Item was opened to track comm8ittment made by applicant.	TVA Letter dated 6/18/10	

		Tologon with 1 V/ Clas onaptor 1 only						•	70 110001104 101 0211 11pp1014
	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
	Sec.	POC	Requirements," dated September 10, 2010 b. EQLR-171, Revision 0, "Environmental and Seismic Test Report, Analog Input (AI)687 & AI688 Modules for use in Common Q PAMS," dated September 10, 2010 c. CN-EQT-10-44, Revision 0, "Dynamic Similarity Analysis for the Watts Bar Unit 2 Post Accident Monitoring System (PAMS)," dated September 28, 2010 (2) Upgraded PC Node Box – As stated in Westinghouse letter WBT-D-2024, dated June 9, 2010 "NRC Access to Common Q Documents at the Westinghouse Rockville Office," (Reference 6), the following documents are available for NRC audit at the Westinghouse Rockville office: a. CDI-3722, Revision 7, "Next Generation PC Node Box Commercial Dedication Instruction" b. LTR-EQ-10-50 "PC Node Box/Flat Panel Display System Components Qualification Summary" (3) Flat Panel Displays – As stated in Westinghouse letter WBT-D-2024, dated June 9, 2010 "NRC Access to Common Q Documents at the Westinghouse Rockville Office," (Reference 6), the following documents are available for NRC audit at the Westinghouse Rockville Office: a. CDI-3803, Revision 8, "Next Generation Flat Panel Display (FPD) Commercial Dedication		Status/ Culterit Actions	Tresolution I atti	TVALINO. & Date	Trainesp. Date	Comments
			Instruction" b. LTR-EQ-10-50 "PC Node Box/Flat Panel Display System Components Qualification Summary" (4) Power supplies – As stated in Westinghouse letter WBT-D-2035 dated June 11, 2010 "NRC Access to Common Q Documents at the Westinghouse Rockville Office" (Reference 7), the following documents are available for NRC audit at the Westinghouse Rockville office: a. CDI- 4057, Revision 4, "Commercial Dedication Instruction" b. EQ-TP-1 05-GEN, Revision 0, "Electromagnetic Compatibility Test Plan and Procedure for Quint Power Supplies and Safety System Line Filter" c. Breakers," EQ-TP-114-GEN, Revision 0, "Seismic Qualification Test Procedure For Common Q Power Supplies, Quint Power Supplies, Line Filter Assemblies, and South Texas Units 3 & 4 Circuit" d. EQ-TP-117-GEN, Revision 0, "Environmental Qualification Test Procedure For Common Q Powe Supplies, Quint Power Supplies, and Line Filter						
082 7.5.2	7.5.1	(a) 5/6/2010	Assemblies" Responder: WEC Date: 6/18/10	2. N (Open	Open-NRC Review	EICB RAI	TVA Letter dated	NNC 11/18/10: See also Open Item No.
		The PAMS Licensing Technical Report (WNA-LI-00058-WBT Rev. 0, Dated April 2010), in Section 2.3, lists hardware/software changes to the Common Q PAMS previously reviewed by the NRC. However the Common Q ISG-6 Compliance Matrix does not	These components can be found in the Summary Qualification Report Of Hardware Testing For Common Q Applications, 00000-ICE-37764, Rev 3 and TWICE Qualification Status Report, WNAQR-00011-SSP Per Westinghouse letter WBT-D-2024, (Reference) dated	- F	Revised response included in etter dated 12/22/10 Regulations require that the NRC review be based on	NNC 2/2/11: Qualification of changes will be addressed at the next audit. The description	ML102910002 Item No. 10	7/30/10	41, Item No. 3.

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				specifically: 2.c - CI527 AF100 Peripheral Component Interconnect (PCI) interface card 3 Common Q TC514 AF100 Fiber Optic Modems (Evolutionary Product Maintenance/Improvements) 4.a - PM646A Processor Module 4.b - CI631 AF100 Communication Interface Module 4.e - DO620 Digital Output Card Please provide sufficient detail regarding the changes for the NRC to independently evaluate the acceptability of the changes.	June 9, 2010, these documents are available for audit at the Westinghouse Rockville Office. TVA provided information by letter dated July 30, 2010 (ML102160349) - See Enclosure 1 Item No. 7. Revision 1 of the Licensing Technical Report provides additional detail on the platform specific to WBN2 and references to the evaluation documentation. TVA Response to Follow-up NRC Request: Please see the response to Request for Additional Information (RAI) item 3 in letter dated 12/22/10, NRC Matrix Item 067.		docketed material. Awaiting for document to be docketed by TVA. NNC 8/9/10: per telephone conversation on 8/5/10, it is not clear how Westinghouse Commercial Grade Dedication Plans and Reports for Digital I&C. Westinghouse agree to present to the NRC in a public meeting on August 17, 2010, and explanation of how their system addresses regulatory criteria for both commercial grade dedication and equipment qualification. NNC 8/25/10: In the August 17, 2010 public meeting Westinghouse stated that the CDI were the plans. The NRC requested that the plans and associated reports be docketed. NNC 11/18/10: During the September 20-21, 2010 audit, TVA agreed to put a description of the commercial grade dedication program and implementation in Rev. 2 of the CQ PAMS LTR.	grade dedication process in the CQ PAMS LTR Rev. 2 should be updated to include a non-proprietary description and to include a software example.			
101			DORL (Poole)	4/12/2010 The non-proprietary versions of the following RM-1000, Containment High Range Post Accident Radiation Monitor documents will be provided by June 30, 2010. 1. V&V Report 04508006A 2. System Description 04508100-1TM 3. Qualification Reports 04508905-QR, 04508905-1 SP, 04508905-2SP, 04508905-3SP 4. Functional Testing Report 04507007-1TR	Responder: Slifer The documents, and affidavits for withholding for the listed documents were submitted to the NRC on TVA letter to the NRC dated July 15, 2010.	3. Y	Open Documents provided in letter dated 07/15/10	Open-NRC Review Due 10/14/10 Confirm receipt.	N/A		TVA is working with the vendor to meet the 6/30 date, however there is the potential this will slip to 7/14.
138			EICB (Carte)	By letter dated February 3, 2010, Westinghouse informed TVA that certain PAMS documentation has been completed. (a) The draft ISG6 states that a commercial grade dedication plan should be provided with an application for a Tier 2 review. By letter dated February 5, 2010, TVA stated that the commercial grade dedication plan was included in the Common Q Topical Report Section 11, "Commercial Grade Dedication Program." Section 11 includes a description of the Common Q Commercial Grade Dedication Program, and states: "A detailed review plan is developed for each Common Q hardware or software component that requires commercial grade dedication." Please provide the commercial grade dedication plans for each Common Q hardware or software component that has not been	This item is used to track all Commercial Grade Dedication issues. a. WNA-LI-00058-WT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report' submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1) contains the following changes to address the NRC request: Section 7, "Commercial Grade Dedication Process" has been revised to describe the general commercial grade dedication process for both hardware and software and uses a description of the Al687 dedication process as an example of how the process is applied.		Open Revised response included in letter dated 12/22/10 TVA agreed to include a description of the generic Westinghouse hardware commercial grade dedication process in the PAMS licensing technical report. (see ML102920031 Item No 1) TVA agreed to include (in the PAMS licensing technical report) an evaluation of WBN2 critical	Open-NRC Review NNC 2/2/11: Commercial grade dedication will be addressed at the next audit.	ML101650255, Item No. 2		

No. SE FSA Sec. Se	SAR ec.	NRC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
		previously reviewed and approved by the NRC. (b) The draft ISG6 states that a commercial grade dedication report should be provided within 12 months of requested approval for a Tier 2 review. (i) Please provide 00000-ICE-37722 Rev. 0, "Commercial Grade Dedication Report for the QNX Operating System for Common Q Applications." (ii) Please provide WNA-CD-00018-GEN Rev. 3, "Commercial Dedication Report for QNX 4.25G for Common Q Applications."	As listed in Table 6-3. "Westinghouse Watts Bar 2 Common Q PAMS Documents at Westinghouse Rockville Office, the following commercial grade dedication documents are available for NRC audit at the Westinghouse Rockville office: (list included in letter) b. It is TVA's understanding that the submittal of the documents listed in (b.i) and (b.ii) is no longer required. Rather, it was agreed, that the inclusion of a description of the commercial grade dedication process in revision 2 of the Post-Accident Monitoring System (PAMS) Licensing Technical Report, WNA-LI-00058-WT-P, would be sufficient to address this request.		characteristics for commercial Westinghouse hardware components against the generic critical characteristics. (see ML102920031 Item No 2) TVA agreed to include a description of the generic Westinghouse software commercial grade dedication process in the PAMS licensing technical report. (see ML102920031 Item No 3) TVA agreed to include (in the PAMS licensing technical report) an evaluation of WBN2 critical characteristics for commercial software components against the generic critical characteristics. (see ML102920031 Item No 4)				
185		Software Requirements Specifications in the SRP, in the unmodified IEEE std 830-1993, and even more so given the modifications to the standard listed in Regulatory Guide 1.172, which breaks with typical NRC use of the word "should" to say	Responder: WEC Steve Clark to look at how to combine traceability items. Was addressed to during the 9/15 meeting and 9/20 - 9/21 audit. TVA Response to Follow-up NRC Request: (1) See NRC Matrix Item 144 (2) There is no RTM for development of the individual reusable software elements. As listed in item 15 of Table 6-1 "Document Requirements" of WNA-LI-00058-WT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC, dated December 3, 2010, a RTM for implementation of the RSEDs (WNA-VR-00280-WBT) for the WBN Unit 2 Common Q PAMS has been developed. This document is available for NRC audit at the Westinghouse Rockville office.	5. N	Open Response included in letter dated 12/22/10.	Open-NRC Review Due (1) 12/3/10 (2) 12/22/10 NNC 11/18/10: (1)The point behind this open item was that TVA must demonstrate that the origin of each requirement in the WEC requirements specification is known and documented. TVA stated that this information would be in CQ PAMS LTR Rev. 2. (2) TVA also said it would provide a RTM for the RSED NNC 2/3/11: To be addressed during next audit.	EICB RAI ML102980066 Item No. 17		

	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
212 7.5.2	EICB	By letter dated June 18, 2010 (ML101940236) TVA stated (Enclosure 1, Attachment 3, Item No. 3) that the PAMS system design specification and software requirements specification contain information to address the "Design Report on Computer Integrity, Test and Calibration" The staff has reviewed these documents, and it is not clear how this is the case. (1) Please describe how the information provided demonstrates compliance with IEEE 603-1991 Clauses 5.5, 5.7, 5.10, & 6.5. (2) Please describe how the information provided demonstrates conformance with IEEE 7-4.3.2-2003 Clauses 5.5 & 57.	Responder: WEC Application specific requirements for testing. This cannot be addressed in a topical report. Evaluation of how the hardware meets the regulatory requirements. WEC to provide the information and determine where the information will be located. IEEE-603 1991: 5.5 System Integrity. The safety systems shall be designed to accomplish their safety functions under the full range of applicable conditions enumerated in the design basis. TVA Response: The applicable conditions and Common Q PAMS system compliance are contained in WNA-LI-00058-WBT-P, Rev. 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, Section 11, "Contract Compliance Matrix" items: 87 and 88 Seismic 89, 90, 91, 92 and 185 EMI/RFI 300, 301 and 302 Environmental 5.7 Capability for Test and Calibration. Capability for testing and calibration of safety system equipment shall be provided while retaining the capability of the safety systems to accomplish their safety functions. The capability for testing and calibration of safety system equipment shall be provided during power operation and shall duplicate, as closely as practicable, performance of the safety function. Testing of Class 1E systems shall be in accordance with the requirements of IEEE Std 338-1987. Exceptions to testing and calibration during power operation are allowed where this capability cannot be provided without adversely affecting the safety or operability of the generating station. In this case: (1) appropriate justification shall be provided (for example, demonstration that no practical design exists), (2) acceptable reliability of equipment operation shall be otherwise demonstrated, and (3) the capability shall be provided while the generating station in Shut down. TVA Response: The requirements for test and calibration and Common Q PAMS system compliance, are contained in WNA-LI-00058-WBT-P, Rev. 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" Section 11, "TVA		Open Response included in letter dated 12/22/10.		EICB RAI ML102980066 Item No. 10		

o. SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				Verification402, 403 and 404, 3.7.3 Channel Bypass or Removal from Operation						
				5.10 Repair. The safety systems shall be designed facilitate timely recognition, location, replacement, repair, and adjustment of malfunctioning equipment.	О					
				TVA Response: The requirements for repair and Common Q PAMS system compliance are contained WNA-LI-00058-WBT-P, Rev. 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" Section 11, "TVA Contract Compliance Matritems: 179 Mean time to repair 202 self test 398 3.7 Maintenance 399 3.7.1 Troubleshooting						
				6.5 Capability for Testing and Calibration						
				 6.5.1 Means shall be provided for checking, with a h degree of confidence, the operational availability of each sense and command feature input sensor required for a safety function during reactor operation. This may be accomplished in various ways; for example: by perturbing the monitored variable, within the constraints of 6.6, by introducing and varying, as appropriate, a substitute input to the sensor of the same nature as the measured variable, or by cross-checking between channels that bear known relationship to each other and that have readouts available. 	n.					
				 6.5.2 One of the following means shall be provided f assuring the operational availability of each sense a command feature required during the post-accident period: (1) Checking the operational availability of sensors use of the methods described in 6.5.1. (2) Specifying equipment that is stable and retains calibration during the post-accident time period 	by its					
				TVA Response: The requirements for sense and command feature testing and Common Q PAMS system compliance are contained in WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring Syste (PAMS) Licensing Technical Report" Section 11 "TV Contract Compliance Matrix" items: 10, display of sensor diagnostic information 202 self test	m					
				 205 self diagnostics and watchdog timer 264 through 271, system self checks 311 system status displays, 341 alarms, 344 on-line diagnostics 						

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
					5.5 System integrity In addition to the system integrity criteria provided by IEEE Std 603-1998, the following are necessary to achieve system integrity in digital equipment for use in safety systems: — Design for computer integrity — Design for test and calibration — Fault detection and self-diagnostics						
					5.5.1 Design for computer integrity The computer shall be designed to perform its safety function when subjected to conditions, external or internal, that have significant potential for defeating the safety function. For example, input and output processing failures, precision or round off problems, improper recovery actions, electrical input voltage and frequency fluctuations, and maximum credible number of coincident signal changes.						
					If the system requirements identify a safety system preferred failure mode, failures of the computer shall not preclude the safety system from being placed in that mode. Performance of computer system restart operations shall not result in the safety system being inhibited from performing its function.						
					 TVA Response: Common Q PAMS system reliability and failure modes are described in: WNA-AR-00180-WBT, Revision 0, "Failure Modes and Effects Analysis (FMEA) for the Post Acciden Monitoring System" WNA-AR-00189-WBT, Revision 0 "Post Accident Monitoring System Reliability Analysis" 						
					The requirements for mean time between failure and Common Q PAMS system compliance are contained in WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report," Section 11 "TVA Contract Compliance Matrix" item 178.						
					5.5.2 Design for test and calibration Test and calibration functions shall not adversely affect the ability of the computer to perform its safety function. Appropriate bypass of one redundant channel is not considered an adverse effect in this context. It shall be verified that the test and calibration functions do not affect computer functions that are not included in a calibration change (e.g., setpoint change).						
					V&V, configuration management, and QA shall be required for test and calibration functions on separate computers (e.g., test and calibration computer) that provide the sole verification of test and calibration data V&V, configuration management, and QA shall be						

No.	SE Sec.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				required when the test and calibration function is inherent to the computer that is part of the safety system.						
				V&V, configuration management, and QA are not required when the test and calibration function is resident on a separate computer and does not provide the sole verification of test and calibration data for the computer that is part of the safety system.						
				 TVA Response: The requirements for test and calibration and Common Q PAMS system compliance are contained in WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" Section 11 "TVA Contract Compliance Matrix" items: 202 self test 350 Maintenance Bypass 351 Loop Tuning Parameters, 400 and 401 3.7.2 Testing, Calibration, and Verification 402, 403 and 404, 3.7.3 Channel Bypass or Removal from Operation 						
				5.5.3 Fault detection and self-diagnostics Computer systems can experience partial failures that can degrade the capabilities of the computer system, but may not be immediately detectable by the system. Self-diagnostics are one means that can be used to assist in detecting these failures. Fault detection and self-diagnostics requirements are addressed in this sub-clause.						
				The reliability requirements of the safety system shall be used to establish the need for self-diagnostics. Self diagnostics are not required for systems in which failures can be detected by alternate means in a timely manner. If self-diagnostics are incorporated into the system requirements, these functions shall be subject to the same V&V processes as the safety system functions.						
				If reliability requirements warrant self-diagnostics, then computer programs shall incorporate functions to detect and report computer system faults and failures in a timely manner. Conversely, self-diagnostic functions shall not adversely affect the ability of the computer system to perform its safety function, or cause spurious actuations of the safety function. A typical set of self-diagnostic functions includes the following:						
				 Memory functionality and integrity tests (e.g., PROM checksum and RAM tests) Computer system instruction set (e.g., calculation tests) Computer peripheral hardware tests (e.g., watchdog timers and keyboards) Computer architecture support hardware (e.g., 						

No.	SE Sec.	FSAR Sec.	NRC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				address lines and shared memory interfaces) Communication link diagnostics (e.g., CRC checks) Infrequent communication link failures that do not result in a system failure or a lack of system functionality do not require reporting. When self-diagnostics are applied, the following self-diagnostic features shall be incorporated into the system design: a) Self-diagnostics during computer system startup b) Periodic self-diagnostics while the computer system is operating c) Self-diagnostic test failure reporting TVA Response: The requirements for fault detection and self diagnostics and Common Q PAMS system compliance are contained in WNA-LI-00058-WBT-P, Rev. 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" Section 11 "TVA Contract Compliance Matrix" items: 107 error free download 202 self test 205 self diagnostics and watchdog timer 263 primary and backup communication 264 through 271, continuous on-line self checks 311 system status displays, 341 alarms, 344 on-line diagnostics 5.7 Capability for test and calibration No requirements beyond IEEE Std 603-1998 are necessary. TVA Response: No response required. Concurrence: E-mail from Westinghouse (Andrew P. Drake) to Bechtel (Mark S. Clark), RE: RAI 212 Response - Errors in the Contract Compliance Matrix, dated December 17, 2010						
250			The SPM describes the software and documents that will be created and placed under configuration control. The SCMP (e.g., SPM Section 6, "Software Configuration Management Plan") describes the implementation tasks that are to be carried out. The acceptance criterion for software CM implementation is that the tasks in the SCMP have been carried out in their entirety. Documentation should exist that shows that the configuration management tasks for that activity group have been successfully accomplished. Please provide information that shows that the CM tasks have been successfully accomplished for each life cycle	Responder: WEC Westinghouse develops Software Release Reports/Records and a Configuration Management Release Report. Describe the documents and when they will be produced. Summarize guidance on how to produce these records, focus on project specific requirements in SPM etc. TVA Response to Follow-up NRC Request: The following documentation shows that the configuration management tasks for that activity group have been successfully accomplished. 1. WNA-LI-00058-WT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1) contains the following changes to	F G	Open Revised response included in etter dated 12/22/10 Response included in letter lated 10/25/10.	Open-NRC Review Due 12/22/10 10/25/10 is a partial response. Still waiting on Software Test Plan and all other testing documentation. NNC 2/2/11: To be addressed during the next audit.			LIC-101 Rev. 3 Appendix B Section 4, "Safety Evaluation" states: "the information relied upon in the SE must be docketed correspondence." LIC-101 Rev. 3 states: "The safety analysis that supports the change requested should include technical information in sufficient detail to enable the NRC staff to make an independent assessment regarding the acceptability of the proposal in terms of regulatory requirements and the protection of public health and safety."

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
					 address the NRC requests: a. Section 2.2.1 Hardware/Software Change Process has been added to describe the process of how changes are evaluated. b. Section 2.2.2, "Software" has been expanded to include a table detailing evolutionary software changes that have occurred since the initial submittal and the change evaluation of the life cycle. 						
					 WNA-PT-00138-WBT, Revision 0, "Nuclear Automation Watts Bar 2 NSSS Completion Program I&C Projects, Post Accident Monitoring System Test Plan," (Proprietary), dated November 2010 submitted in TVA Letter to NRC, dated December 3, 2010 (Reference 1). 						
327			<u>e</u>	SC-2001 sheets 1 through 6. An affidavit for withholding and non-	Responder: Webber In accordance with correspondence from Foxboro, there is no proprietary information contained in the 08F802403-SC-2001 drawings. Based on this, no affidavit for withholding is required. Attachment 1 contains versions of the drawings with the proprietary information block removed.		Open Response Included in letter dated 11/24/10	Open-NRC Review Due 11/24/10			
281	7.6	7.6.8	EICE	For FSAR Section 7.6.8 in amendment 96, redline version has completely rewritten this section of the FSAR, however, the staff is not able to determine any changes made to the section. Explain what changes have been made to this FSAR Section.	Attachment 5 contains the WBN Unit 2 FSAR markup for Section 7.6.8, "Interlocks for RCS Pressure Control During Low Temperature Operation," showing what was changed between Amendments 95 and 96. TVA Response to Follow-up NRC Request: The interlock for the RCS Pressure Control for Unit 2 is implemented differently than Unit 1 implementation. There are no differences between Unit 1 and Unit 2 interlocks, operation of interlocks and operator interface for operation of the RCS Pressure Control. Primary sensing elements and final control elements are identical and operations of these devices are identical. For Unit 2, once signals are processed by the Eagle 21 system, interlock implementation is by software modules in the Foxboro I/A Distributed Control System (DCS). Hardware outputs, generated in the DCS, operate the PORVs. The Unit 2 DCS is implemented via EDCRs 52378 and 54504. Section 7.6.8 in Amendment 101 of the WBN Unit 2 FSAR reflects the Unit 2 changes associated with implementation of the DCS. TVA Response to Second Follow-up NRC Request: The underlined text from FSAR Amendment 101 Section 7.6.8 reflects the installation of the Foxboro DCS. 7.6.8 Text from FSAR Amendment 101 The wide range temperature signals, as inputs to the Protection Sets I and II, continuously monitor RCS temperature conditions. In Protection Set I, the existing RCS temperature conditions. In Protection Set I, the existing RCS		Response provided in letter dated 10/29/10 FSAR Amendment 101 did not reflect the changes in 7.6.8 associated with implementation of the DCS. Provide the basis for acceptance to use Foxboro I/A DCS inplace of analog instrumentation and relays. Additional clarification provided during 1/20 telecom. Question is how does the system conform to IEEE 279 as described in 7.6.8.1.	Open-TVA/Bechtel Due 11/24/10 Provide the basis for the changes. Look at Foxboro I/A impact.	EICB RAI ML102910008 Item#65	TVA Letter dated 10/29/10 Enclosure 1 Item No. 16	

No.	SE Sec.	FSAR Sec.	NRC POC Issue		Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				wide range temperature channels on RCS loops 1 and 2 provide inputs to the Eagle 21 digital process protection system. Eagle 21 provides isolated analog signals to the digital process control system. An auctioneer function selects the lowest temperature signal which is then used to calculate an acceptable reference pressure limit (PORV setpoint) considering the plant's allowable pressure and temperature Protection Set III. The calculated reference pressure is compared to the actual RCS pressure monitored by the wide range pressure channel. The auctioneered temperature signal will annunciate a main control room (MCR) alarm whenever the measured temperature approaches, within a predetermined amount, the reference temperature for arming the system. Similarly, whenever the measured pressure approaches within a predetermined amount of the programmed setpoint, another MCR alarm will be generated. When the measured RCS pressure is equal to or above the programmed setpoint (nominal values), a PORV open signal is initiated and a MCR alarm is actuated. A manually armed permissive allows this actuation signal to control the Train A PORV (PCV-68-340A). The manually armed permissive also serves to block a spurious PORV opening due to potential instrument failure whenever the RCS temperature is above the arming reference temperature. The monitored generating station variables that generate the actuation signal for the Train B PORV (PCV-68-334) are processed in a similar manner. The RCS loops 3 and 4 wide range temperature signals and the RCS pressure signal are provided from Protection Set II. Therefore, the generating station variables used for the Train B PORV are derived from a protection set that is independent of the sets from which generating station variables used for the Train A PORV are derived. The wide range temperature auctioneer function and the programmed pressure setpoint calculation for the Train B PORV are performed in a different group of the digital process control system than those for the Train A PORV.						
318	7.5.2.3	7.5	TVA has provided the following documents for RM-1000 equipment qualification: (i) Qualification Test Report for RM-1000 Processor Module and Current-To-Frequency Converter 04508905-QR (January 2001) (ii) Qualification Test Report Supplement, RM-1000 Upgrades 04508905-1SP (June 2006) (iii) Qualification Test Report Supplement, RM-1000 Upgrades	(i) Applicable to WBN Unit 2. 04508905-1QR is applicable only in regards to the RM-1000, with the exception of re-qualification of certain RM-1000 equipment differences covered in the -1SP report. The Current-to-Frequency (I-F) converter module		Revised response is included in letter dated 12/22/10. Note check 04508905-1QR or QR. Staff version is QR only.	<u>'</u>	RAI No. 28 ML102980005 10/26/2010	TVA Letter dated 10/29/10, Encl 1 Item 34, and TVA letter 11/24/10, Att. 2.	

No. SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
			04508905-2SP (June 2008) (iv) Qualification Test Report Supplement, RM-1000 Upgrades 04508905-3SP (May 2008) Please clarify whether all of these are fully applicable to WBN2 or are they applicable with exceptions? If with exceptions, then please clarify what those are. Supplement 3 was issued one month prior to supplement 2. Please explain the reason for the same.	qualifications in the base report and the -1SP report are not applicable to the RM-1000s, and will be used later as references in the WBN Unit 2 specific qualification reports. (iii) Applicable to WBN Unit 2. (iii) Not applicable to WBN Unit 2. (iii) Not applicable to WBN Unit 2. (iv) Not applicable to WBN Unit 2. The 04508905-3SP report was prepared for another TVA plant, as a monitor system-level report, where the system included equipment mostly based on the base report equipment items. These two -2SP and -3SP supplement reports were essentially worked concurrently, but the -2SP document review/release process resulted in the release time difference. TVA Response to Follow-up NRC Request: NOTE: The response for the current to frequency (I to F) converter in item 1 below is a reversal of the response previously provided in TVA to NRC letter dated October 29, 2010 (Reference 22). General Atomics Electronic Systems Inc. (GA-ESI) notified TVA of this change on December 8, 2010 (Reference 20). (1) The applicability of the qualification reports from GA-ESI e-mail dated December 10, 2010 (Reference 19) is as follows: a. 04508905-QR "Qualification Test Report for RM-1000 Processor Module and Current-to-Frequency Converter" is applicable to the WBN Unit 2 RM-1000 and I to F converter modules. b. 04508905-1SP "Supplement to Qualification Test Report for RM-1000 Processor Module and Current-to-Frequency Converter" is applicable to the WBN Unit 2 RM-1000 module. c. 04508905-1SP is not applicable to the WBN Unit 2 To F converter module. d. 04508905-2SP "Qualification Test Report Supplement, I-F Converter Upgrades" is applicable to the WBN Unit 2 To F converter module. d. 04508905-2SP "Qualification Test Report Supplement, I-F Converter Upgrades" is applicable to the WBN Unit 2 To F converter module. GA-ESI provided two other reports required to support qualification of the containment high range radiation monitors. The report descriptions are from GA-ESI e-mail on December 8, 2010 (Reference 20). The report		dated 10/29/10	applicability of 04508905-QR and - 1SP to RM-1000 and IF converter is not clear. Check page numbers of Appendix F (missing/duplicate pages). Check applicability of Appendix C to RM1000 instead of RM2300? See items 336 and 337. All equipment qualification reports including supplements 2SP and 3SP have been reviewed as vendor drawings for WBN-2. Please explain the reason for applicability of one report and not the other. Further all TVA/Bechtel reviews seems to be dispositioned as Code 4, "Review not required. Work may proceed." The applicable reports should have been reviewed prior to dispositioning them. Please explain the apparent lack of review of WBN-2 applicable documents. Was appropriate review of WBN-2 applicable documents. Was appropriate review guidance used? Further update required Provide model number/part number for the RM-1000 and I/F converter used for WBN-2. This information is needed to verify that the model or part number used is the equipment that has been qualified for WBN-2. Provide qualification reports 04038903-QSR and 04038903-TSP by			

No. SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
		POC	Issue	the principle report and the starting point for all the radiation monitors provided as part of the replacement contract. The report describes each monitor; referenced to the technical manual for the physical and functional description and lists the major components of the monitor system. Report section 3 identifies the TVA Watts Bar Unit 2 Environmental, Seismic, Electromagnetic Compatibility (EMC), and software requirements for each monitor. In section 4 a brief description of GA-ESI generic qualification programs for all radiation monitoring equipment in each of the four above areas is provided. The qualification basis for each monitor is provided in a separate supplement to the principle report and is identified in section 5. f. GA-ESI report 04038903-7SP, "Qualification Basis for 04034101-001 (2-RE-90-271, -272, -273, & -274) [TVA Note: These are the containment post accident high range radiation monitors.]:" GA-ESI report 04038903-7SP is divided into subsections to address the		Status/ Current Actions	the dues date of 1/22/11. Submit a copy of any other relevant reviewed versions of the qualification reports. Submit copies of the reviewed reports for 04508905-QR, 04508905-1SP, 04508905-2SP. Clarification of applicability of existing reports is acceptable.	KAI No. & Date	KAI Kesp. Date	Comments
				Environmental, Seismic, EMC, and Software qualification basis for the High Range Area Monitors. Within each subsection, the HRAM is compared to a tested or analyzed article to demonstrate similarity and/or evaluate differences, the tests that were performed, and evaluation to demonstrate qualification. In most cases, the qualification basis references other documents. In addition to qualification, a section is provided that lists the life of those replaceable components that have life expectancy less than 40 years.						
				(2) This is addressed by response to RAI Question 336 in TVA to NRC letter dated November 24, 2010 (Reference 8)						
				(3) This is addressed by response to RAI Question 337 in TVA to NRC letter dated November 24, 2010 (Reference 8)						
				(4) The 04508905-3SP Qualification Test Report Supplement, RM-1000 Upgrades" is not applicable to WBN Unit 2 (Reference 19).						
				Please see Item 1, above, for applicability of the other reports.						
				(5) TVA provided the proprietary versions of the reports by letter dated March 12, 2010 (Reference 10). By letter dated July 15, 2010 (Reference 23), TVA provided the non-proprietary version of the reports and included a copy of the proprietary report which had been erroneously marked as having not been reviewed. 04508905-QR report has been reviewed by TVA. The						

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
					review of the remaining reports is ongoing. (6) See item 5.						
338	7.5.2.3	7.5		In page 3-15 and appendix B of Qualification Test Report 04508905-QR, licensee described the selection of seismic required response spectra (RRS) and indicated Figure 3-2 (page 3-17), Figure 3-3 (page 3-18) are the RRSs used. The RRS curves used for actual testing are lower than the RRS curves that are shown on Figures 3-2 and 3-3. The RRS curves used for testing are shown in Figure 4-5, 4-6, 4-7, 4-8, 4-11, 4-12, 4-13, and 4-14 (pages 4-25, 4-26, 4-28, 4-29, 4-37, 4-38, 4-40, 4-41). Please clarify and justify why the RRS curves used in actual tests are lower than the RRS curves determined in Figures 3-2 and 3-3. In addition please justify that the RRS used for testing envelopes the RRS required for WBN-2 application specific seismic conditions.	Responder: Civil EQB Get date from Bob Brown	3. N	Open	Open-TVA/Bechtel Due: 2/25/11			
339	7.5.2.3	7.5	EICB (Singh)	In the Qualification Test Report 04508905-QR, the licensee provided only eight Safe Shutdown Earthquake (SSE) Test Response Spectra (TRS) as mentioned in the previous open item (OI-338). Please provide all SSE and Operating Basis Earthquake (OBE) TRS plots for NRC review.	Responder: Bob Brown	4. N	Open	Open-TVA/Bechtel Due: 2/25/11			
340	7.5.2.3	7.5	EICB (Singh)	Provide test result curves for all EMI/RFI tests listed in Table 3.2.3 (page 3-8) of the Qualification Test Report 04508905-QR. In addition, please provide the standards or the guidance documents used as the source for ENV 50140, ENV 55011 Class A, and EN 55022 Class B.	·		Open Response included in letter dated 12/22/10.	Open-TVA/Bechtel Provide the qual reports by 1/28/11 per TVA letter of 12/22/10. Due: 2/25/11			

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
					c. EN 55022 - Information technology equipment - Radio disturbance characteristics - Limits and methods of measurement						
341	7.5.2.3	7.5		these tables do not list the containment high range radiation monitors. Please add them to the appropriate FSAR table(s) or justify why they should not be included in the FSAR 3.10 series of tables.	A review of WBN Unit 2 FSAR amendment 102 chapters 3.10, 11 and 12 was performed. The reviewer was unable to locate seismic qualification information for the radiation monitoring system in those chapters. A review of chapter 3.11 confirmed that radiation monitoring is included in the environmentally qualified systems. It appears that seismic qualification of the radiation monitoring equipment was unintentionally omitted from FSAR chapter 3.10. FSAR chapter 3.10 will be updated to include the qualified radiation monitoring equipment in a future FSAR amendment.	6. Y	·	Open-TVA/Bechtel Will be closed on update of FSAR 3.10 series tables.			
344	7.6.6	?	5 0 0	There is no section in FSAR which provides discussion on this subject. SE section discusses compliance with PSB-18. Provide a discussion which can be used by the staff to determine similar conclusion as Unit 1 and if the design is similar to Unit 1 then make a statement to that effect. Also provide the list of the valves where power lockout during normal reactor operation is utilized for valves whose inadvertent operation could affect plant safety.	The requested information is contained in FSAR Amendment 102 as follows: 7.6.2.1 Description 5th paragraph: "The motor-operated bypass valves are located in bypass lines paralleling the normal RHR suction isolation valves FCV 74-1 and FCV 74-2 which are in series in the flowpath. Valves FCV 74-8 and FCV 74-9 are normally closed and remain closed with power locked out unless one of the two main isolation valves (FCV 74-1 or FCV 74-2) cannot be opened and the plant must be cooled down." And: 7.6.6 Spurious Actuation Protection for Motor Operated Valves To the best of TVA's knowledge, the information contained in the FSAR is complete and accurate as of February, 2, 2011.		Open ICSB-18 provides guidance on application of the single failure criterion to manually controlled electrically operated valves According to this BTP, electrically operated valves includes MOV, SOV and those valves operated indirectly by an electrical device, e.g.an air operatd valves whose air supply is controlled by an electrical solenoid valves. FSAR Section 7.6.6 addresses only MOVs. If TVA has done an analysis to demonstrate compliance with the guidance of this BTP for Unit 1 and this analysis does not change for Unit 2 for other valves than TVA shouls make a statement to that effect. If there are changes to the analysis then justify those changes based on this BTP.	Open-TVA/Bechtel			
345	7.5.2.3	7.5	EICB (Singh)	temperature excursions to assess aging requirements. TVA to further clarify if 86°F for 40 years was used as the qualification requirement for aging tests. This has been stated in some of the subsections under section 4.2 of the 04508905-QR report but the rationale for using 86°F (includes an internal temperature rise of 18°F) for 40 years has not been justified in the 04508905-QR report or the supplement reports. TVA to provide the rationale for this acceptance criteria for WBN-2.	RM-1000 in a NIM Bin was Tested at 39°F for 72 Hrs and Tested at 131°F for 72 Hrs per Section 4.2.6 of 04508905-QR. This is stated in document 04038903-7SP, Section 2.1. The ambient temperature used for aging was 86°F(30°C). The NIM Bin has perforated holes in top and bottom covers and has an average internal temperate rise of approximately 18 °F due to natural air convection. So the average internal temperature used for aging was 104°F (40°C). Response is incomplete. Awaiting further input from GA.	8. N	Open	Open-TVA/Bechtel Due: 2/25/11			
346	7.5.2.3	7.5	(Singh)	1000 System Verification Test Results report, 04507007-1TR is not applicable to WBN-2. However, TVA has not provided a WBN-2 specific test results report. Please identify and provide the appropriate test results reports to complete the review.	Document 04507007-1TR is only the RM-1000 System Verification Test Results. Additional test results are summarized in the following documents: 04508905-QR, 04508905-1SP, and 04508905-2SP. Response is incomplete. Awaiting further input from GA.	9. N	Open	Open-TVA/Bechtel Due: 2/25/11 The proposed response appears to be conflicting with the			

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
								proposed response for OI-351 regarding not submitting the 04508905-QR report. TVA to re-assess proposed response for both OIs.			
347	7.5.2.3	7.5	EICB (Singh)	qualification for the new RM-1000 modules. TVA to provide the updated qualification or explain the basis for not addressing the EMI/RFI qualification.	Qualification report 04038903-7SP, Qualification Basis for 04034101-001 (2-RE-90-271, -272, -273, & -274), addresses the EMI/RFI qualifications for the entire loop including the RM-1000 & I/F converter. This report references 04038800, RM-1000 EMC Test Report, TVA, and the results are summarized in 04038903-7SP.		Open	Open-TVA/Bechtel Due: 2/25/11			
348	7.5.2.3	7.5	EICB (Singh)	qualification for the new I/F converters. TVA to provide the updated qualification or explain the basis for not addressing the EMI/RFI qualification.	Qualification report 04038903-7SP, Qualification Basis for 04034101-001 (2-RE-90-271, -272, -273, & -274), addresses the EMI/RFI qualifications for the entire loop including the RM-1000 & I/F converter. This report references 04038800, RM-1000 EMC Test Report, TVA, and the results are summarized in 04038903-7SP.		Open	Open-TVA/Bechtel Due: 2/25/11			
349	7.5.2.3	7.5	EICB (Singh)	all the equipment has been assumed to be located in nuclear power plant areas with mild environments and radiation dosages	In response to a question about Common Q PAMS equipment qualification, TVA re-evaluated the Control and Aux Instrument Room TID and concluded it to be less than 1x10³ RAD.	12. N	Open	Open-TVA/Bechtel Due: 2/25/11 TVA to provide the assessment document or a suumary of the document with the reference to the appropriate document/documents.			
350	7.5.2.3	7.5	읦	3-1 of 04508905-1SP and Figure 3-1 of 0458905-2SP report. The actual test response spectra are shown in Figures 4-5 and 4-6 of 04508905-QR report. The actual test response spectra does not seem to fully envelope the RRS. However, this statement is based on visual reading of unidentified numbers. TVA to provide	RM-1000 in a NIM Bin was Seismically Tested and the actual test response spectra fully envelopes the RRS of CEB-SS-5.10 Rev. 3, Figure 3-1 as shown in Figures 3-4 and 3-5 of 04038903-7SP. Response is incomplete. Awaiting further input from GA.	13. N	Open	Open-TVA/Bechtel Due: 2/25/11			
351	7.5.2.3	7.5	EICB (Sin	qualified life of less than 40 years is noted in Table 6-1 of the supplemental qualification report 04508905-1SP. It is not clear if the components identified for replacement in this report are the only components or if the components which are in addition to the components previously identified in qualification report 04508905-QR.	After further review, it was determined that 04508905-QR is a historical document and should not have been submitted as part of the WBN Unit 2 licensing documents. The replacement schedules stated in 04508905-1SP and 04508905-2SP should be used. 04508905-2SP states in Section 6: "None of the Current-to-Frequency converter modules qualified by this supplement contain parts that have significant age related failure mechanisms."		Open	Open-TVA/Bechtel Due: 2/25/11 Reports 04508905-1SP and -2SP both refer to 04508905-QR as the parent document in section 4.1. Also see staff comment on OI-			

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				sensitive components that require replacement during the qualified life).				<mark>346.</mark>			
352	7.5.2.3	7.5	EICB (Singh)	MRA-HARA-00002, R4 under Item 1.6 indicates that the quantity is	The total number of RM-1000 units procured under MR 25402-011-MRA-HARA-00002 is four. The MR on line item 1.6 is stating the purchase of 2 sets of 2 RM-1000s & I/F Converters making a total of 4 for each type of component. Each monitor utilizes a single channel display for the 2-RM-90-271 – 274 monitors.	15. Y	Open	Open-TVA/Bechtel Due: 2/25/11 Will close on receipt of formal response.			
334	7	7	EICB (Darbali)	FSAR Figure 7A-3 "Mechanical Flow and Control Diagram Symbols" doesn't show the symbols for the first column of valves. Please correct this in a future FSAR amendment. Update: Please fix symbols for Gate Valve, Globe Valve and Float operated valve.	Responder: Stockton	1. Y	Open Figure will be corrected in FSAR Amendment 103.	Open-TVA/Licensing	RAI not required.	N/A	RAI not required because the figure is not part of any SE section.
092			DORL (Poole)	5/20/2010	Responder: Hilmes	1. Y	Open	Open-TVA/Oversight			Continuous review as items are added
			<u> </u>	TVA to review Licensee Open Item list and determine which items are proprietary.	This item will close when we are no longer using this document as a communications tool.			Due: SER Issue			
323			EICB(Garg)	1 SER SSER 13 (Reference 8). Unit 2 references revision 2. An	Responder: Hilmes/Unit 1 Attachment 12 contains the WCAP 13869 Revision 1 to Revision 2 Change Analysis.	2. Y	Open Response is included in letter dated 10/29/10 The staff is confused with the response since both units have reference leg not insulated Rev 2 should apply to Unit 1 also and there should be no difference between Unit 1 and 2			TVA Letter dated 10/29/10 Enclosure 1 Item No. 36	
041	7.5.2	7.5.1	EICB (Carte)	(1) WNA-DS-01617-WBT Rev. 1, "PAMS System Requirements Specification" (2) WNA-DS-01667-WBT Rev. 0, "PAMS System Design Specification" (3) WNA-CD-00018-GEN Rev. 3, "CGD for QNX version 4.5g" Please provide the following Westinghouse documents or pointers to where the material was reviewed and approved in the CQ TR or SPM: (4) WNA-PT-00058-GEN Rev. 0, "Testing Process for Common Q Safety systems"	WBN2 Specific Test Plan to compensate for the fact that the NRC disapproved WNA-PT-00058-GEN during the original		Final Response included in letter dated 12/3/10 Partial Response is included in letter dated 10/5/10. The SysRS and SRS incorporate requirements from many other documents by reference. NNC 8/25/10: (3) An earlier version of this report was docketed for the Common Q topical report; therefore, there should be no problem to docket this version. (4) Per ML091560352, the testing process document does not address the test plan requirements of the SPM. Please provide a test plan that implements the requirements of the SPM.	Open-TVA/WEC NNC 1/27/11: Issues with the STP were discussed in the weekly public meetings. Westinghouse to: (1) perfrom STP self assessment., and (2) Augment Test Summary report to provide missing test plan information NNC 2/3/11: At next audit compare & discuss: (1) WNA-PT-00058-GEN Rev. 0 (2) WNA-PT-00138-WBT Rev. 0 (3) AP1000 STP	NRC Meeting Summary NRC Meeting Summary ML093560019, Item No. 11	TVA Letter dated 6/18/10 TVA Letter dated 10/5/10	See also Open Item Nos. 226 & 270.

denda	for Weekly	Telecom w	ith T\/Δ	(I&C	Chanter 7	7 only)
ruenua	IOI VVEEKIV	I EIECOIII W	IIII I VA	ιιαυ	Chaptel 1	OHIV

rad	Ε.	7Ω	ᄄ	2 ~	-
เดน		ıo) . U	ш,

No.	SE Sec.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
043	7.5.2	7.5.1	0140/0040	For Item 4, Attachment 9 contains the Westinghouse document "Nuclear Automation Watts Bar 2 NSSS Completion Program I&C Projects, Post Accident Monitoring System Test Plan," WNA-PT-00138-WBT, Revision 0, dated November 2010. Attachment 10 contains the Westinghouse Application for Withholding for the WNA-PT-00138-WBT, Revision 0 "Nuclear Automation Watts Bar 2 NSSS Completion Program I&C Projects, Post Accident Monitoring System Test Plan," WNA-PT-00138-WBT, Revision 0, dated November 17, 2010.		•		EICB RAI ML102910002	TVA Letter dated 2/5/10	NNC 8/25/10: A CQ PAMS ISG6 compliance matrix was docketed on: (1)
			TVA letter dated February 5, 2010 is a first draft of the information needed. The shortcomings of the first three lines in the matrix are: Line 1: Section 11 of the Common Q topical report did include a commercial grade dedication program, but this program was not approved in the associated SE. Westinghouse stated that this was the program and it could now be reviewed. The NRC stated that TVA should identified what they believe was previously reviewed and approved. Line 2: TVA stated the D3 analysis was not applicable to PAMS, but provided no justification. The NRC asked for justification since SRP Chapter 7.5 identified SRM to SECV-93-087 Item II.Q as being SRP acceptance criteria for PAMS. Line 3: TVA identified that the Design report for computer integrity was completed as part of the common Q topical report. The NRC noted that this report is applicable for a system in a plant, and the CQ topical report did no specifically address this PAMS system at Watts Bar Unit 2. NRC then concluded that TVA should go through and provide a more complete and thorough compliance matrix.	The PAMS ISG6 compliance matrix supplied as Enclosure 1 to TVA letter dated February 5, 2010 is a first draft of the information needed. By letter dated April 8, 2010 TVA provided the PAMS Licensing Technical Report provided additional information. Attachment 3 contains the revised Common Q PAMS ISG-6 Compliance Matrix, dated June 11, 2010, that addresses these items (Reference 13). By letter Dated June 18, 2010 (see Attachment 3) TVA provided a table, "Watts Bar 2 - Common Q PAMS ISG-6 Compliance Matrix." It is TVA's understanding that this comment is focused on the fact that there are documents that NRC has requested that are currently listed as being available for audit at the Westinghouse offices. For those Common Q PAMS documents that are TVA deliverable documents from Westinghouse, TVA has agreed to provide those to NRC. Westinghouse documents that are not deliverable to TVA will be available for audit as stated above. Requirements Traceability Matrix issues will be tracked under NRC RAI Matrix Items 142 (Software Requirements Specification) and 145 (System Design Specification). Commercial Item Dedication issues will be tracked under NRC RAI Matrix Item 138. This item is considered closed. TVA Response to Follow-up NRC Request: WNA-LI-00058-WT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1) contains the following changes to address the NRC requests: (1) While RSEDs are not specifically mentioned, Section 7 has been revised to be applicable to both hardware and software which includes the RSEDs. (2) Table 6-1 item 15 reference added for WNA-VR-00280-		Revised compliance matrix is	with Common Q TR & SPM compliance were discussed in the weekly public meetings. Westinghouse to perform Common Q TR & SPM compliance self assessment; his will be discussed in detail on the next audit.	Item No. 2	TVA Letter dated 5/12/10 TVA Letter dated 6/18/10 TVA Letter dated 10/5/10	February, 5 12010, (2) March 12, 2010, & (3) June 18, 2010. The staff has expressed issued with all of these compliance evaluations. The staff is still waiting for a good compliance evaluation. NNC 11/23/10: WNA-LI-00058-WT-P Rev. 1 Section 7 does not include the RSED documents, and it should. Table 6-1 Item No. 15 should also include the RSED RTMs.
067	7.5.2	7.5.1	By letter dated March 12, 2010 TVA stated that the target submittal date for the "Commercial Grade Dedication Instructions for Al687, Al688, Upgraded PC node box and flat panels." was September	WBT (RESD) Responder: WEC Date: 5/25/10 The following status is from the revised WB2 Common Q		Open Response included in letter	Open-TVA/WEC Due: 2/25/11	N/A - No question was asked. Item was opened to track	TVA Letter dated 6/18/10	

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				28, 2010.	PAMS ISG-6 Compliance Matrix submitted in response to Item 43: a. Al687, Al688 – Scheduled for September 28, 2010 b. Upgraded PC node box and flat panel displays – Per Westinghouse letter WBT-D-2024 (Reference 7), these items are available for audit at the Westinghouse Rockville office. c. Power supplies – Per Westinghouse letter WBT-D-2035 (Reference 12), these items are available for audit at the Westinghouse Rockville office. To be addressed during 9/20-9/21 audit TVA Response to Follow-up NRC Request: WNA-LI-00058-WT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1) contains the following change to address the NRC request: Section 7, "Commercial Grade Dedication Process," has been revised to describe the general commercial grade dedication process for both hardware and software and uses a description of the Al687 dedication process as an example of how the process is applied.		dated 12/22/10. This item is addressed in Rev. 2 of the Licensing Technical Report	NNC 2/2/11: Section 7 of the WBN2 PAMS LTR should be updated to include: (1) non-proprietary description of commercial grade dedication, and (2) Software example Commercial grade dedication will also be addressed at the next audit.	comm8ittment made by applicant.		
069	7.5.2	7.5.1	EICB (Carte)	By letter dated March 12, 2010 TVA stated that the target submittadate for the "Watts Bar 2 PAMS Specific FAT Report" was October 2010. As agreed, the Watts Bar 2 PAMS Specific FAT Report will not be submitted. Instead a non-proprietary PAMS Test Summary Report will be submitted.		4. N	'	Open-TVA/WEC Due 3/31/11 NNC 2/3/11: The current due dated above is 4 months later than planned.	N/A - No question was asked. Item was opened to track comm8ittment made by applicant.	N/A	
074	7.5.2	7.5.1	EICB (Carte)	By letter dated March 12, 2010 TVA stated that the target submitta date for the Post FAT IV&V Phase Summary Report was November 30, 2010.	Responder: WEC Date: 5/25/10	5. N	Open TVA to provide due date.	Open-TVA/WEC Due 4/15/11 NNC 2/3/11: The current due date above is 3 months later than planned.	N/A - No question was asked. Item was opened to track commitment made by applicant.		Rev. 4 will be available for the NRC audit on 2/28/11. This document will not be submitted. Rev. 5 will be submitted after resolution of the datastorm display issue.
081	7.5.2	7.5.1	EICB (Carte)	5/6/2010 The PAMS Licensing Technical Report (WNA-LI-00058-WBT Rev. 0, Dated April 2010), in Section 7, lists codes and standards applicable to the Common Q PAMS. This list contains references to old revisions of several regulatory documents, for example: (1) RG 1.29 - September 1978 vs. March 2007 (2) RG 1.53 - June 1973 vs. November 2003 (a) IEEE 379-1994 vs2000 (3) RG 1.75 - September 1975 vs. February 2005 (a) IEEE 384-1992 vs1992 (4) RG 1.100 - June 1988 vs. September 2009 (a) IEEE 344-1987 vs2004 (5) RG 1.152 - January 1996 vs. January 2006	Responder: Merten/WEC The codes and standards documents listed in Section 7 of the Common Q PAMS Licensing Technical Report are the documents that the Common Q platform was licensed to when the NRC approved the original topical report and issued the approved SER. The WBN Unit 2 Common Q PAMS is designed in accordance with the approved Common Q topical report and approved SER and the codes and standards on which the SER was based. Since the current versions referenced are not applicable to WBN Unit 2, there is no basis for a comparison review. Bechtel to develop a matrix and work with Westinghouse to	6. N	ML101600092 Item No.1: There are three sets of regulatory criteria that relate to a Common Q application (e.g. WBN2 PAMS): (a) Common Q platform components – Common Q TR (b) Application Development Processes – Common Q SPM (c) Application Specific – current	TVA to provide requested information. NNC 2/3/11: The above due date has been missed by at least 2 months.	EICB RAI ML102910002 Item No. 9	TVA Letter dated 6/18/10	NNC 1/5/11: See Also Open Item No. 86 and 202.

١	o. SE	Ē.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				(a) IEEE 7-4.33.2-1993 vs2003 (b) RG 1.168 - September 1997 vs. February 2004 (a) IEEE 1012-1986 vs1998 (b) IEEE 1028-1988 vs1997 (7) IEEE 279-1991 vs. 603-1991 (8) IEEE 323-1983 vs1974 (RG 1.89 Rev. 1 June 1984 endorses 323-1974) However, LIC-110, "Watts Bar Unit 2 License Application Review," states: "Design features and administrative programs that are unique to Unit 2 should then be reviewed in accordance with the current staff positions." Please identify all differences between the versions referenced and the current staff positions. Please provide a justification for the acceptability PAMS with respect to these differences.	provide justification.		and associated appendices primarily addressed (a) and (b). The Common Q SER states: 'Appendix 1, "Post Accident Monitoring Systems," provides the functional requirements and conceptual design approach for upgrading an existing PAMS based on Common Q components (page 58, Section 4.4.1.1, "Description")On the basis of the above review, the staff concludes that Appendix 1 does not contain sufficient information to establish the generic acceptability of the proposed PAMS design (page 56, Section 4.4.1.3, "PAMS Evaluation")' The NRC did not approve the proposed PAMS design. Section 6, "References," and Section 7, "Codes and Standards Applicable to the Common Q PAMS," of the PAMS Licensing Technical Report contain items that are not the current regulatory criteria. Please provide an explanation of how the WBN2 PAMS conforms with the application specific regulatory criteria applicable to the WBN2 PAMS design. For example IEEE Std. 603-1991 Clause 5.6.3, "Independence Between Safety Systems and Other Systems," and Clause 6.3, "Interaction Between the Sense and Command Features and Other Systems," contain application specific requirements that must				
							be addressed by a PAMS system.				
0	36 7.5.	.2	7.5.1		Responder: WEC Date: 5/24/10	7. N	Awaiting TVA Response. Open	Open-TVA/WEC	EICB RAI	TVA Letter dated	NNC 1/6/11: See Also Open Item No.81
				(1) DI&C-ISG04 - Rev. 0 (ML072540138) vs. Rev. 1	Licensing Technical Report are the documents that the	oved n	TVA to address with item OI 81.	Due 2/25/11 NNC 2/3/11: The above due date has been missed by at least 2 months.	ML102910002 Item No. 14	6/18/10	<u>& 202</u>

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				states: "Design features and administrative programs that are unique to Unit 2 should then be reviewed in accordance with the current staff positions." Please identify all differences between the versions referenced and the current staff positions. Please provide				Please provide new due date.			
142			EICB (Carte)	The applicable regulatory guidance for reviewing the WBN2 PAMS SysRS would be IEEE 830 as endorsed by Regulatory Guide 1.172 and BTP 7-14 Section B.3.3.1, Requirements Activities – Software Requirements Specifications." IEEE 830-1994 Section 4.3.8, "Traceable," states: "A [requirements specification] is traceable of the origin of each of its requirements is clear" 1. How did TVA ensure the traceability of each requirement in the WBN2 PAMS SysRS. 2. Explain the source(s) of the requirements present in the Post Accident Monitoring System's Software Requirements Specification. To clarify, many documents have requirements that are incorporated by reference into the SRS, but what served to direct the author to include those various documents in the SRS or, if the requirement is based on the System Requirements Specification, what directed the author to include the requirement there? 3. Clarify whether the unnumbered paragraphs in the Post Accident Monitoring System's Software Requirements Specification, such as in the section headings, or are all such sections simply considered to be informative? Does the same apply to documents referenced by the SRS? Such as WCAP-16096-NP-A, Rev. 1A, "Software Program Manual for Common Q Systems," which is incorporated by reference in requirement R2.3-2 in the SRS.	Responder: WEC This item is used to track all traceability issues with the Software Requirements Specification (SRS). TVA Response to 1: Traceability of requirements for the WBN Unit 2 Common Q PAMS is ensured by: a. Preparation of the TVA Contract Compliance Matrix contained in WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010 (Reference 1). b. Engineering review/comment/status of each revision of: i. WNA-DS-01617-WBT, "Post Accident Monitoring System - System Requirements Specification" ii. WNA-DS-01667-WBT, "Post Accident Monitoring System — System Design Specification" (hardware) iii. WNA-SD-00239-WBT, "Software Requirements Specification for the Post Accident Monitoring System" (software) TVA Response to 2: As documented in the RTM, some software requirements are taken from generic documents. The decision to include generic software requirements was to reduce the overall scope for Common Q features that are unchanged across projects. Westinghouse reviewed the generic PAMS requirements and included those requirements that were applicable to WBN Unit 2 PAMS. Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13) TVA Response to 3: Unnumbered paragraphs in the Post Accident Monitoring System's Software Requirements Specification, such as in the section headings, are informative and are not to be interpreted as requirements. All requirements are explicitly numbered. It depends on the document type. The statement would be true for requirements documents (such as the SysRS or	8. N	Open Response included in letter dated 12/22/10 TVA/Westinghouse agreed to include the V&V evaluation of their reusable software element development process in the V&V design phase summary report. This evaluation would include an evaluation against the development process requirements. This evaluation would also include an evaluation of how the WBN2 specific requirements were addressed by the reusable software elements. (see ML102920031 ltem No 5)	Due 2/25/11 (document submittals) NNC 2/2/11: Updated Specifications and RTMs to be provided by TVA Tracability to be addressed during the next audit.	ML101650255, Item No. 6		WBN2 PAMS System Requirements Specification TVA docketed WNA-DS-01617-WBT Rev. 1, "RRAS Watts Bar 2 NSSS Completion Program I&C Projects Post Accident Monitoring System-System Requirements Specification," dated December 2009.
				R2.3-2 [The PAMS software shall comply with the	SDS) if they were incorporated by reference. However, for the specific item cited, WCAP-16096-NP-A, Rev. 1A, it does						

		-		TWILL TVA (I&C Chapter 7 only)						Jen items to b	• •
No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				requirements and guidelines defined in WCAP-16096-NP-A, "Software Program Manual for Common Q Systems" (reference 5).]	not contain numbered requirements. The requirements contained in this document are contained within the text of the various sections.						
				If any requirements are expressed in such unnumbered paragraph form instead of individually identified requirements, please list them, describe why they satisfy the fundamental requirement of unambiguity, and describe how they were verified.	Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						
			4.	Are there any sources of requirements in parallel with the Post Accident Monitoring System's Software Requirements Specification? Meaning does the SRS contain, explicitly or by reference, all the requirements that were used in the design phase for the application specific software, or do	TVA Response to 4: The Westinghouse SRS, WNA-SD-00239-WBT, Revision 3 contains references to other Westinghouse software requirements documents. Specifically,						
				software design phase activities use requirements found in any other source or document? If so, what are these sources or documents?	00000-ICE-3238, Revision 5, "Software Requirements Specification Post Accident Monitoring System" 00000-ICE-3239, Revision 13, "Software Requirements						
					Specification for the Common Q Generic Flat Panel Display Software"						
					Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						
			5.	References 12, 27, 29, and 31-44 in the Post Accident Monitoring System's Software Requirements Specification are various types of "Reusable Software Element". These references are used in the body of the SRS, for example: "	TVA Response to 5: Requirements for the reusable software elements (RSEDs) are evaluated in WNA-VR-00283-WBT-P, Revision 3, "IV&V Summary Report for the Post Accident Monitoring System," dated December 2010 (Attachment 10).						
				R5.3.14-2 [The Addressable Constants CRC error signal shall be TRUE when any CAL CRC's respective ERROR terminal = TRUE (WNA-DS-00315-GEN, "Reusable Software Element Document CRC for Calibration Data" [Reference 12]).]	RSED traceability is contained in WNA-VR-00280-WBT, Revision 2, "Watts Bar 2 NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Reactor Vessel Level Indication System (RVLIS) Custom PC Elements." This document can be made available for audit at the Westinghouse Rockville office.						
				They are also included via tables such as found in requirement R7.1.2-1							
				[The Watts Bar 2 PAMS shall use the application-specific type circuits and custom PC elements listed in Table 7.1-1.]							
			red	to the referenced reusable software element documents include quirements not explicitly stated in the SRS? If so what is their igin?							
					At the September 15 public meeting in Rockville, the following actions were agreed to. These items address the traceability concerns with the Software Requirements Specification. 1. Westinghouse will perform a review of the Requirements Traceability Matrix(RTM), using the issues identified at the 9/15 public meeting as a guide						
					(documented below) and update the RTM as required. TVA Response: See response to letter Item 13 (NRC Matrix Item 145).						

No.	SE Sec.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				2. The next issue of the IV&V report will include the Requirements phase review of the RTM and a partial review for the Design phase.						
				TVA Response: See response to letter Item 13 (NRC Matrix Item 145).						
				3. Westinghouse will add a comments column in the Requirements Traceability Matrix (RTM) to address items not in the SRS or SysRS.						
				TVA Response: A comments column has been added to WNA-VR-00279-WBT, Revision 3, "Watts Bar 2 NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Post Accident Monitoring System."						
				Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						
				4. IEEE 830 says you shouldn't have planning information in the SRS. Westinghouse has agreed to remove this information.						
				TVA Response: Westinghouse has confirmed that process requirements have been removed from the SRS.						
				Source: E-mail from Westinghouse (Andrew P. Drake) to Bechtel (Mark S. Clark), RE: Common Q RAI concerns, dated December 8, 2010 (Reference 17)						
				5. IEEE 830 says you shouldn't have process requirements in the SRS. Westinghouse has agreed to remove these requirements.						
				TVA Response: Westinghouse confirmed that process requirements have been removed from the SRS.						
				Source: E-mail from Westinghouse (Andrew P. Drake) to Bechtel (Mark S. Clark), RE: Common Q RAI concerns, dated December 8, 2010 (Reference 17)						
				6. Westinghouse will perform and document an evaluation of the SRS to ensure compliance with Reg. Guide 1.172 and justify any deviations.						
				TVA Response: WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1):						
				Section 9, "Compliance Evaluation Of The Watts Bar 2 PAMS Software Requirements Specification To IEEE						

No.	SE Sec.	FSAR Sec.	NRC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				Standard 830-1998 And Regulatory Guide 1.172" has been added.						
				7. 25 issues identified by V&V where some requirements have not been included in the System Design Specification (SDS) (14) and SRS (11) at the revisions reviewed by V&V. Have these been addressed?						
				TVA Response: The twenty-five (25) issues are captured in Exception Reports (ERs): V&V-769 and V&V-770. These ERs have all been addressed and the ERs have been closed satisfactorily by Westinghouse IV&V.						
				Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						
				8. Some hardware requirements are contained in the SRS instead of the System Design Specification (SDS). These will be removed from the SRS and incorporated into the next revision of the SDS.						
				TVA Response: The hardware requirements in the Software Requirements Specification have been deleted and moved to System Design Specification.						
				Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 16, 2010 (Reference 15)						
				9. RTM item R4.2-2 protection class software set to 0. Needs to be fixed internally. Write CAPs to revise the application restrictions document on AC160.						
				TVA Response: Westinghouse CAPs IR# 10-259-M034 has been issued. This item will be addressed in revision 4 of the RTM.						
				Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						
				10. Westinghouse to improve the traceability of the tests that are performed with the function enable (FE) switch in the "ENABLE" position.						
				TVA Response: The tests that are performed with the FE keyswitch in the ENABLE position are defined in the SRS Sections: 6.2 "Manually Initiated Testing," 7.2.23 "Annunciator Test Display," 7.2.25 "Saturation Margin Test Display," and 7.2.26 "Analog Output Test Display."						
				 Westinghouse to revise documents to be consistent with referring to the FE switch in the "ENABLE" position. 						

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
					TVA Response: Westinghouse has elected to standardize on the terms "FE keyswitch" and "ENABLE." A review of recent documents for compliance with this comment and commitment was performed with the following results: a. Revision 3 of the SysRs, and SDS have been revised to use the terms "FE keyswitch." Revision 3 of the SDS is consistent in use of the term "ENABLE." b. SysRS Revision 3 is not consistent in use of the term "ENABLE." i. R2.5.2.1-2 uses the term "ENABLED" instead of "ENABLE" ii. R2.5.2.1.3-3, R2.6.3.3-1, R2.6.3.3-2, R2.6.3.3- 3, and R2.6.3.3-7, use the term "Enable" instead of "ENABLE" c. Revision 3 of the SRS is not consistent in use of the terms "FE keyswitch" and "ENABLE" as noted below: i. Tables 7.2-1 "Train A PAMS Data Transmitted to the Plant Computer" and 7.2-2 "Train B PAMS Data Transmitted to the Plant Computer" items 101 and 102 in the SRS refer to the FE switch. All other items in the SRS refer to the FE keyswitch. ii. Section 2.1, page 2-4, uses the term "Enable" instead of "ENABLE" iii. Requirements R7.2.14-6 and R7.2.16-7 use the term "active" instead of "ENABLE" iv. Requirements R7.2.23-2, R7.2.25-2, R7.2.26-2, R7.2.31-4, 7.2.56 FPDS Availability, and R7.2.57-4 use the term "enabled" instead of "ENABLE" d. WNA-AR-00180-WBT-P, Revision 0, "Failure Modes and Effects Analysis (FMEA) for the Post Accident Monitoring System," dated October 2010 submitted in TVA letter to NRC dated (Reference 12) is not consistent in use of the term "FE keyswitch" as noted below: i. Section 2.2 "System Description" and Table 3 1 "WB2 PAMS FMEA" refer to the FE switch. iii. Table 3-1 describes the switch as the "Functional Enable (FE) switch" and the "FE keyswitch" as noted below: i. Section 2.2 "System Description" and Table 3 1 "WB2 PAMS FMEA" refer to the FE switch. iii. Table 3-1 describes the switch as the "Functional Enable (FE) switch" and the "FE keyswitch" and "ENABLE" in the SysRS, SRS, FMEA and Licensing Technical Report is no consistent in use of the term "FE keyswitch" as noted below: i						

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
					documents are used. Describe in 1.1 of the SysRS. Need a good write up of how the process works.						
					TVA Response: See response to letter item 13 (NRC Matrix Item 145).						
					13. Westinghouse and TVA will develop a revised schedule for document submittals and provide it to the NRC no later than 9/30/10						
					TVA Response: The revised document submittal schedule was included as item 3 NRC Request (Matrix Item Number 142, TVA Commitments Nos. 10 and 17) in TVA letter to NRC dated October 26, 2010 (Reference 5).						
					14. TVA will update the Procurement Requisition Resolution Matrix and submit it to show how the Common Q PAMS design meets the contract requirements.						
					TVA Response: The Procurement Requisition Resolution Matrix has been updated and is included in WNA-LI-00058-WBT-P. Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1), as Section 11, "TVA Contract Compliance Matrix."						
					 Westinghouse to add the Software Design Descriptions to the RTM 						
					TVA Response: The Software Design Description documents were added to the RTM in WNA-VR-00279-WBT, Rev 2.						
					Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						
					 Westinghouse to clarify how requirements or documents are incorporated by reference into the Common Q PAMS requirements. 						
					TVA Response: When a Common Q PAMS requirements document references a section of another document, all requirements in that section are applicable.						
					Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						
					17. Westinghouse to review the use of "shall" outside of numbered paragraphs in requirements documents to ensure that all requirements are captured and clearly identified.						
					TVA Response:						

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
					See response in letter dated December 22, 2010, item 2 (NRC Matrix Item 050).						
					18. Westinghouse to resolve the following questions concerning Software Design Descriptions (SDDs)						
					a. Is the SDD a standalone document or will it incorporate the generic SDD by reference?						
					b. What are the SDDs?						
					c. PAMS is a delta document so how do we capture all the generic requirements for traceability.						
					TVA Response: a. There are three SDDs prepared specifically for the Watts Bar 2 PAMS project. These are listed below in Item b. These documents and superior requirements documents refer to other generic SDDs also listed in Item b.						
					 b. The SDDs developed for this project are: WNA-SD-00248-WBT, Revision 1, "Watts Bar 2 NSSS Completion Program I&C Projects Software Design Description for the Post Accident Monitoring System Flat Panel Display" WNA-SD-00250-WBT, Revision 1, "Watts Bar 2 NSSS Completion Program I&C Projects Software Design Description for the Post Accident Monitoring System AC160 Software" WNA-SD-00277-WBT, Revision 2, "Watts Bar 2 NSSS Completion Program I&C Projects Software Design Description for the Post Accident Monitoring System Flat Panel Display System Screen Design Details" 						
					 iv. Other generic SDDs referenced by the PAMS project are: (a) 00000-ICE-20157, Revision 18, "Software Design Description for the Common Q Generic Flat-Panel Software" 						
					(b) 00000-ICE-30152, Revision 5,"Software Design Description Post Accident Monitoring System AC160"						
					(c) 00000-ICE-30140, Revision 4, "Software Design Description for the Common Q Core Protection Calculator System Database and Utility Functions"						
					c. Refer to WNA-VR-00279-WBT, Revision 3. Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13)						

No	SE Sec.	FSAR Sec.	NRC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
14	Sec.		The WBN2 PAMS Software Requirements Specification (WBN2 PAMS SRS – ML101050202) contains a table (see page iii) titled, "Document Traceability & Compliance," which states that the WBN2 PAMS SRS was created to support the three documents identified (one of which is the WBN2 PAMS SysRS). Section 1.1, "Overview," of the WBN2 PAMS SRS states: "This document describes requirements for the major software components"	19. For Reusable Software Elements, Westinghouse to describe as qualified libraries by following the SPM and qualified using the Software Elements Test procedure under Appendix B program. Provide a summary of RSEDs generic WCAP. Westinghouse to determine if the WCAP was docketed under the AP1000. RSED concept is not in the SPM. WCAP-15927 AP-1000 does not discuss RCEDs. WCAP process was acceptable. RSEDs are listed in the SDD References. TVA Response: Section 3.2.4.1 of WCAP-15927 describes the RSED design process for custom PC elements and type circuits. The Glossary of Terms in the SPM defines custom PC elements and type circuits. The relationship between WCAP-15927 describing the RSED process as circuits, is defined in the SPM requirements for software module development. WCAP-15927 is on the AP1000 docket. Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13) Responder: WEC Addressed in the 9/15 public meeting and 9/20 - 9/21 audit. A detailed explanation will be provided. TVA Response: (a) and (b) The requested information is provided in the following documents: i. WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report," Table 6-1, "Document Requirements" which lists the software	9. N	Open Response included in letter dated 12/22/10	Open-TVA/WEC	ML101650255, Item No. 7		WBN2 PAMS System Requirements Specification TVA docketed WNA-DS-01617-WBT Rev. 1, "RRAS Watts Bar 2 NSSS Completion Program I&C Projects Post Accident Monitoring System- System Requirements Specification," dated December 2009.
			components. Please include a description of any NRC review for each of these components. (c) What other documents contain the requirements for the other software components?	documentation requirements for the Common Q PAMS and Section 11 "TVA Contract Compliance Matrix" submitted in TVA Letter to NRC, dated December 3, 2010 (Reference 1). ii. WNA-DS-01617-WBT-P, Revision 3, "Post Accident Monitoring System- System			NNC 2/3/11: The above due date has been missed by at least 2 months.			
			The WBN2 PAMS System Design Specification (WBN2 PAMS SDS) contains a table (see page iii) titled, "Document Traceability & Compliance," which states that the WBN2 PAMS SysRS was created to support the WBN2 PAMS SysRS. Section 1.1, "Purpose," of the WBN2 PAMS SDS states: "The purpose of this document is to define the hardware design requirements"	Requirements Specification," dated December 2010 (Attachment 1) iii. WNA-SD-00239-WBT-P, Revision 3, "Software Requirements Specification for the Post Accident Monitoring System," dated December 2010 (Attachment 7) iv. WNA-VR-00279-WBT, Revision 3, "Watts Bar 2			Please provide new due date.			
			(c) Do the WBN2 PAMS SRS and SDS, together, implement all of the requirements in the WBN2 PAMS SysRS?(e) Please briefly describe all of the documents that implement the WBN2 PAMS SysRS.	NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Post Accident Monitoring System" (available for NRC audit at the Westinghouse Rockville office) To the best of TVA's knowledge, no prior NRC review of the software components has been performed.						

No.	SE Sec.	FSAR Sec.	NRC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
144			The WBN2 PAMS Software Requirements Specification (WBN2 PAMS SRS) contains a table (see page iii) titled, "Document Traceability & Compliance," which states that the WBN2 PAMS SRS was created to support the three documents identified (two of these documents have been provided on the docket). (a) Please describe the third document (i.e., NABU-DP-00014-GEN Revision 2, "Design Process for Common Q Safety Systems"). (b) Please describe the flow of information between these three documents. (c) Does the PAMS SRS implement the requirements in these three documents? (d) Please describe if and how these three documents are used in the development of the PAMS Software Design Description. (e) Do the WBN2 V&V activities include verification that the requirements of these three documents have been incorporated into the WBN2 PAMS SRS.	(c) WNA-VR-00280-WBT, Revision 2, "Watts Bar 2 NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Reactor Vessel Level Indication System (RVLIS) Custom PC Elements" (available for NRC audit at the Westinghouse Rockville office) (d) No. Please see Item (e) below. (e) The documents that describe the requirements that implement the WBN Unit 2 SysRS are: i. WNA-VR-00279-WBT, Revision 3, "Watts Bar 2 NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Post Accident Monitoring System" (available for NRC audit at the Westinghouse Rockville office) ii. WNA-VR-00280-WBT, Revision 2, "Watts Bar 2 NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Reactor Vessel Level Indication System (RVLIS) Custom PC Elements" (available for NRC audit at the Westinghouse Rockville office) Source: E-mail from Westinghouse (Matthew A. Shakun) to 3echtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010 (Reference 13) Responder: WEC (a) The purpose of NABU-DP-00014-GEN document is to define the process for system level design, software design and implementation, and hardware design and mplementation for Common Q safety system development. This document supplements the Common Q SPM, WCAP-16096-NP-A. The scope of NABU-DP-00014-GEN includes the design and implementation processes for the application development. For a fuller description of the design process described in NABU-DP-00014-GEN please refer to the Design Process for AP1000 Common Q Safety Systems, WCAP-15927 on the AP1000 Common Q Safety Systems, WCAP-15927 on the AP1000 Common Q Safety Systems, WCAP-15927 on the AP1000 docket. Since this is a Westinghouse process document that is not specification WNA-SD-00239-WBT, Rev. 1) refers to Document Traceability & Compliance table on page iii. This table has hree entries; Design Process for Common Q Safety Systems (NABU-DP-00014-GEN, Rev. 2), RRAS Watts Bar 2 NSSS Completion Program I&C Projects Post Accident Monitoring System – S	10. N	letter dated 12/22/10 Response provided in letter dated 10/5/10 NRC Review and WEC to complete response. b-d to be addressed at public meeting and audit. Will require information to be docketed.	Open-TVA/WEC Due TBD – TVA to provide a date Responses to items a and e provided. NNC 11/18/10: (1) Items b-d closed to other Open Item nos. (2) The point of these questions was to understand how the origin of the requirements in the requirements specifications were documented. TVA stated that the origin of the requirements would be demonstrated in Rev. 2 of the CQ PAMS LTR. NNC 2/3/11: CQ PAMS LTR Rev. 2 Section 11 & 12 do not adequately demonstrate the origin of requirements in SysRS. TVA to describe how to address concern.	ML101650255, Item No. 8	TVA Letter dated 10/5/10	WBN2 PAMS Software Requirements Specification By letter dated April 8, 2010 (ML10101050203), TVA docketed WNA-SD-00239-WBT, Revision 1, ""RRAS Watts Bar 2 NSSS Completion Program I&C Projects, Software Requirements Specification for the Post Accident Monitoring System," dated February 2010 (ML101050202).

No. SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				 IV&V performed a Requirements Traceability Assessment during which it reviewed Software Requirements Specification (WBN2 PAMS SRS, WNA-SD-00239-WBT, Rev. 1) against System Requirements Specification (WNA-DS-01617-WBT, Rev. 1) and System Design Specification (WNA-DS-01667-WBT, Rev. 1). Requirements within Software Requirements Specification that are referring to NABU-DP-00014-GEN, Rev 2, Design Process for Common Q Safety Systems, have also been reviewed for traceability and compliance. During IV&V's RTA effort the anomaly reports V&V-769 and V&V- 770 have been initiated and reported in the IV&V Phase Summary Report for the System Definition Phase, WNA-VR-00283-WBT, Rev. 0. IV&V has verified that the requirements in SRS are derived from the specified documents listed in the Document Traceability and Compliance Table of WBN2 PAMS SRS. Item (a) in the original list, NABU-DP-00014-GEN Revision 2, "Design Process for Common Q Safety Systems," is available for NRC audit at the Westinghouse Rockville office. WNA-LI-00058-WT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1) contains the following change to address the NRC request: Section 11, "TVA Contract Compliance Matrix" showing the origin of the requirements was added. 						
145		EICB (Carte)	The WBN2 PAMS System Design Specification (WBN2 PAMS SDS) contains a table (see page iii) titled, "Document Traceability & Compliance," which states that the WBN2 PAMS SDS was created to support the WBN2 PAMS SysRS. (a) Does the WBN2 PAMS SDS implement all of the hardware requirements in the WBN2 PAMS SysRS? (b) Please briefly describe all of the documents that implement the hardware requirements of the WBN2 PAMS SysRS. This item is used to track all traceability issues with the System Design Specification (SDS). At the September 15 public meeting in Rockville, the following actions were agreed to. These items partially address the traceability concerns with the System Design Specification. This item will be updated with the results of the September 20 and 21 Commercial Grade Dedication and SDS RTM audit. 1. Westinghouse will perform completed a review of the Requirements Traceability Matrix(RT), using the issues identified at the 9/15 public meeting as a guide (documented below) and update the RTM as required.	Responder: WEC (1) The review and update of the RTM is complete. The revised RTM can be made available for NRC audit at the Westinghouse office in Rockville. (2) Please see letter Item 10 (NRC Matrix Item 142, sub item 13). (3) Please see letter Item 10 (NRC Matrix Item 142, sub item 12). (4) Section 11 "TVA Contract Compliance Matrix" was added to WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1). (5) WNA-VR-00283-WBT, Revision 1, "IV&V Summary Report for the Post Accident Monitoring System," submitted in TVA to NRC letter dated December 3, 2010 (Reference 1) includes the Requirements and Design phase reviews.		Response included in letter dated 12/22/10 During the September 20-21, 2010 audit at Westinghouse, it was acknowledged that TVA/Westinghouse had previously (in September 15, 2010 public meeting) stated: TVA would provide the RSED RTM. (see ML102920031 Item No 6) TVA would revise and resubmit the PAMS RTM to address all types of issues identified in the public meeting. (see ML102920031 Item No 7) TVA would revise and resubmit the Software Verification and		ML101650255, Item No. 9		WBN2 PAMS System Design Specification TVA docketed WNA-DS-01667-WBT Rev. 1, "RRAS Watts Bar 2 NSSS Completion Program I&C Projects Post Accident Monitoring System- System Design Specification," dated December 2009.

No. SE FSAF Sec. Sec.	R NRC Issue	TVA Response(s)	sponse eptable Status/ Current Actions Y/N	Resolution Path	RAI No. & Date RAI Resp. Date	Comments
		 (6) Per Westinghouse letter WBT-D-2268 "NRC Access to Common Q Documents at the Westinghouse Rockville Office" dated August 16, 2010 (Reference 9) "System Requirements Specification for the Common Q Generic Flat Panel Display," 00000-ICE-30155, Revision 9 is available for audit at the Westinghouse Rockville office. The generic AC160 specifications are contained in the documents listed below. The documents are available for NRC audit at the Westinghouse Rockville office in accordance with the letter number referenced. List is contained in letter. (7) A schedule was developed and is reviewed weekly by Westinghouse and TVA project management. (8) The revised document submittal schedule was included as item 3 NRC Request (Matrix Item Number 142, TVA Commitments Nos. 10 and 17) in TVA letter to NRC dated October 26, 2010. (9) The flow of documentation information was provided to the NRC inspector during the Common Q PAMS audit. Source: E-mail from Westinghouse (Andrew P. Drake) to Bechtel (Mark S. Clark), RE: RAI on SysRS, dated December 8, 2010 	Validation phase summary report for the requirements phase to document the completion of the requirements phase review. (see ML102920031 Item No 8)			
183	and even more so given the modifications to the standard listed in Regulatory Guide 1.172, which breaks with typical NRC use of the word "should" to say "Each identifiable requirement in an SRS must be traceable backwards to the system requirements and the	The generic Software Requirements Specification applies except as modified by the WBN Unit 2 System Requirements Specification. TVA Response to Follow-up NRC Request: Please see the response to RAI item 12 in letter dated 12/222/10, NRC Matrix Item 144.	Property of the provided in letter dated 12/22/10. Response provided in letter dated 10/21/10			
202 7.5.2	Sart	Responder: WEC 13. Revision 1 of the Licensing Technical Report will provide	N Open Response included in letter dated 12/22/10	Open-TVA/WEC	EICB RAI ML102980066 Item No. 4	NNC 1/5/11: See Also Open Item No. 81 and 86.

No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				will be expected to revise and resubmit their respective documentation, or submit justification for continued applicability of the topical report without revision of the respective documentation." Question No 81 identified many criteria changes; please revise the respective documentation or submit justification	more detailed information on the changes to the platform. Rev. 2 of the Licensing Technical Report will include the applicability of guidance. TVA Response to Follow-up NRC Request: WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" (LTR) submitted in TVA Letter to NRC dated December 3, 2010, contains the following change to address the NRC request: Section 9, "Compliance Evaluation of the Watts Bar 2 PAMS Software Requirements Specification to IEEE Standard 830-1998 and Regulatory Guide 1.172" to show the origin of the requirements has been added. The descriptions and commitments in the Topical Report (TR) still apply. The LTR provides compliance evidence to the new ISG-04 criteria. The statement in the SE means that the TR can be evaluated against later NRC criteria when it appears. Source: E-mail from Westinghouse (Matthew A. Shakun) to Bechtel (Mark S. Clark), RE: December 22 letter review, dated December 17, 2010		Partial Response provided in letter dated 10/5/10 NNC 1/5/11: Summary provided in Licensing Technical Report R2 has been reviewed and found to be unacceptable. LTR Section 9 evaluates the compliance of the SRS to IEEE 830-1998. There are two issues with this evaluiation: (1) IEEE 830-1998 is not the current SRP acceptance criteria. IEEE 830-1998 has not been formally endorsed by a regulatory guide. (2) Westinghouse committed to evaluate the SRS against 830 when the NRC identified several inconsistencies. Yes ISG-4 is one new criteria, and an evaluation against it has been provided. In addition, LTR Rev. 2 Section 13 states: "The applicable NRC regulatory guides, IEEE and EPRI industry standards fo the common Q PAMS are shown below. Compliance to these codes and standards are stated in Section 4 of Reference 1." Reference 1 is the common Q topical report.	requested. Due TBD			
213	7.5.2		EICB	 (1) Please provide the design basis (as described in IEEE 604 Clause 4) of the Common Q PAMS. (2) Please provide a regulatory evaluation of how the PAMs complies with the applicable regulatory requirements for the theory of operation. For example: Regarding IEEE 603 Clause 5.8.4 (1) What are the 	Responder: WEC Conformance with IEEE 603 is documented in the revised Common Q PAMS Licensing Technical Report and the Common Q PAMS System Design Specification. Attachment 1 contains the proprietary version of Westinghouse document "Tennessee Valley Authority (TVA), Watts Bar Unit 2 (WBN2), Post-Accident Monitoring System (PAMS), Licensing Technical Report, Revision 1, WNA-LI-00058-WBT-P, Dated October 2010" Attachment 8 contains the proprietary version of Westinghouse document "Nuclear Automation Watts Bar 2 NSSS Completion Program I&C Projects Post Accident Monitoring System – System Design Specification", WNA-DS-01667-WBT, Rev. 2 dated September 2010.		Open Response is included in letter dated 10/25/10 NNC to review and revise this question after LTR R2 is received.	Open-TVA/WEC Due TBD — TVA to provide a date NNC 2/3/11: The identified documentation does not include the design bases. Please provide schedule for providing the requested information.	EICB RAI ML102980066 Item No. 18		
244			∃IC Sart	8/3/2010 Section 8.2.2 of the Common Q SPM (ML050350234) states that	Responder: WEC The process related requirements have been removed from		Open Revised response is included in	Open-TVA/WEC NNC 2/2/11: Issues	EICB RAI ML102980066 Item No. 14	Response is provided in letter dated 10/25/10.	LIC-101 Rev. 3 Appendix B Section 4, "Safety Evaluation" states: "the information relied upon in the SE must

								T		-	
No.	SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
				the software. In addition Section 4.3.2.1 of the SPM states "Any alternatives to the SPM processes or additional project specific information for theSCMPshall be specified in the PQP. Contrary to these two statements in the SPM, the WBN2 PAMS SRS (ML101050202) contains many process related requirements, for example all seventeen requirements in Section 2.3.2, "Configuration Control," address process requirements for configuration control. Please explain how the above meets the intent of the approved SPM.	revision 2 of the Software Requirements Specification (SRS). Attachment 3 of letter dated 10/25/10 contains the proprietary version of Westinghouse document "Nuclear Automation, Watts Bar 2 NSSS Completion Program, I&C Projects, Software Requirements Specification for the Post Accident Monitoring System", WNA-SD-00239-WBT, Revision 2, Dated September 2010. TVA Response to Follow-up NRC Request: As shown is the listed documents, process related requirements have been deleted from the SRS and SysRS in Revision 3: Attachment 1 contains proprietary version of WNA-DS-01617-WBT-P, Revision 3, "Post Accident Monitoring System-System Requirements Specification," dated December 2010. Attachment 7 contains the proprietary version of WNA-SD-00239-WBT-P, Revision 3, "Software Requirements Specification for the Post Accident Monitoring System," dated December 2010. Source: E-mail from Westinghouse (Andrew P. Drake) to Bechtel (Mark S. Clark), RE: Common Q RAI concerns, dated December 8, 2010 (Reference 17)		letter dated 12/22/10 Response is provided in letter dated 10/25/10. NNC 11/18/10: SysRS Rev. 2 also contains process requirements that are more appropriately incorporated into process documentation.	with Common Q TR & SPM compliance were discussed in the weekly public meetings. Westinghouse to perform Common Q TR & SPM compliance self assessment; this will be discussed in detail on the next audit.			be docketed correspondence." LIC-101 Rev. 3 states: "The safety analysis that supports the change requested should include technical information in sufficient detail to enable the NRC staff to make an independent assessment regarding the acceptability of the proposal in terms of regulatory requirements and the protection of public health and safety."
245			EICB (Carte)	Common Q SPM. Please provide sufficient information for the NRC staff to independently assess whether the test plan for WBN2 PAMS, is as described in the SPM (e.g., Section 5.8.1).	Responder: WEC Relates to the commitment to provide the test plan and the SPM compliance matrix Attachment 9 contains the Westinghouse document "Post Accident Monitoring System Test Plan," WNA-PT-00138-WBT, Revision 0, dated November 2010. Attachment 10 contains the Westinghouse Application for Withholding for the "Post Accident Monitoring System Test Plan," WNA-PT-00138-WBT, Revision 0, dated November 2010. TVA Revised Response: This is to be addressed in the non-proprietary Common Q PAMS Test Summary Report scheduled to be submitted March 29, 2011.	16. N	Open Response included in letter dated 12/3/10 Common Q PAMS Test Summary Report scheduled to be submitted March 29, 2011.	Open-TVA/WEC NNC 2/2/11: Issues with the Common Q TR & SPM were discussed in the weekly public meetings. Westinghouse to perform Common Q TR & SPM compliance self assessment	EICB RAI ML102980066 Item No. 119		LIC-101 Rev. 3 Appendix B Section 4, "Safety Evaluation" states: "the information relied upon in the SE must be docketed correspondence." LIC-101 Rev. 3 states: "The safety analysis that supports the change requested should include technical information in sufficient detail to enable the NRC staff to make an independent assessment regarding the acceptability of the proposal in terms of regulatory requirements and the protection of public health and safety."
246			EICB (Carte)	(ML050350234) requires that a Project Quality Plan (PQP) be developed. Many other section of the SPM identify that this PQP should contain information required by ISG6. Please provide the PQP. If "PQP" is not the name of the documentation produced, please describe the documentation produced and provide the information that the SPM states should be in the PQP.	Responder: WEC As agreed ISG6 does not apply to the Common Q PAMS platform. The information required to address this question concerning the PQP and SPM has been added to compliance matrix in revision 1 of the Licensing Technical Report. Attachment 1 of letter dated 10/25/10 contains the proprietary version of Westinghouse document "Tennessee Valley Authority (TVA), Watts Bar Unit 2 (WBN2), Post-Accident Monitoring System (PAMS), Licensing Technical Report, Revision 1, WNA-LI-00058-WBT-P, Dated October 2010"	17. N	Open Response is provided in letter dated 10/25/10 NNC 11/18/10: PQP has not been provided and CQ PAMS LTR Rev. 1 does not contain comparable information.	Open-TVA/WEC NNC 2/2/11: Issues with the Common Q TR & SPM were discussed in the weekly public meetings. Westinghouse to perform Common Q TR & SPM compliance self assessment	EICB RAI ML102980066 Item No. 15	Response is provided in letter dated 10/25/10	LIC-101 Rev. 3 Appendix B Section 4, "Safety Evaluation" states: "the information relied upon in the SE must be docketed correspondence." LIC-101 Rev. 3 states: "The safety analysis that supports the change requested should include technical information in sufficient detail to enable the NRC staff to make an independent assessment regarding the acceptability of the proposal in terms of regulatory requirements and the protection of public health and safety."

No. SE Sec.	FSAR Sec.	NRC POC	Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments
251		EICB (Carte	The SPM describes the software testing and documents that will be created. The SPM also describes the testing tasks that are to be carried out. The acceptance criterion for software test implementation is that the tasks in the SPM have been carried out in their entirety. Please provide information that shows that testing been successfully accomplished.	Responder: WEC The software testing performed and documents created are addressed by the SPM Compliance matrix contained in Revision 1 of the Licensing Technical Report. Attachment 1 of the letter dated 10/25/10 contains the Proprietary version of Westinghouse's document titled: "Tennessee Valley Authority (TVA), Watts Bar Unit 2 (WBN2), Post-Accident Monitoring System (PAMS), Licensing Technical Report, Revision 1, WNA-LI-00058-WBT-P, Dated October 2010" TVA Response to Follow-up NRC Request: Please see the response to RAI item 21 in letter dated 12/22/10, NRC Matrix Item 250.	18. N	Open Revised response included in letter dated 12/22/10 Partial response is provided in letter dated 10/25/10	Open-TVA/WEC NNC 2/2/11: Issues with the Common Q TR & SPM were discussed in the weekly public meetings. Westinghouse to perform Common Q TR & SPM compliance self assessment			LIC-101 Rev. 3 Appendix B Section 4, "Safety Evaluation" states: "the information relied upon in the SE must be docketed correspondence." LIC-101 Rev. 3 states: "The safety analysis that supports the change requested should include technical information in sufficient detail to enable the NRC staff to make an independent assessment regarding the acceptability of the proposal in terms of regulatory requirements and the protection of public health and safety."
252		EICB	The SPM contain requirements for software requirements traceability analysis and associated documentation (see Section 5.4.5.3, "Requirements Traceability Analysis"). Please provide information that demonstrates that requirements traceability analysis has been successfully accomplished.	Responder: WEC Explain response to AP1000 audit report. RTM docketed NRC awaiting V&V evaluation of RTM. The following responses are based on WBN Unit 2 Common Q PAMS traceability: Software requirements traceability analysis is described in the following documents: 1. WNA-LI-00058-WBT-P, Revision 2, "Post-Accident Monitoring System (PAMS) Licensing Technical Report" submitted in TVA Letter to NRC dated December 3, 2010, (Reference 1) Section 11, "TVA Contract Compliance Matrix" 2. WNA-VR-00279-WBT, "Watts Bar 2 NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Post Accident Monitoring System" (available for NRC audit at the Westinghouse Rockville office) 3. WNA-VR-00280-WBT, "Watts Bar 2 NSSS Completion Program I&C Projects Requirements Traceability Matrix for the Reactor Vessel Level Indication System (RVLIS) Custom PC Elements" (available for NRC audit at the Westinghouse Rockville office) This document addresses the RSEDs used in the WBN Unit 2 Common Q PAMS. The V&V evaluation of the RTM is documented in section 2.2.2 of the following documents: 1. The Independent Verification & Validation (IV&V) report covering the Concept and Definition phases ("Nuclear Automation Watts Bar Unit 2 NSSS Completion Program I&C Projects, IV&V Summary Report for the Post Accident Monitoring System," (Proprietary), WNA-VR-00283-WBT, Revision 1, dated November 2010), submitted in TVA Letter to NRC		Open Response included in letter dated 12/22/10 Read ML091560352	Open-TVA/WEC Due 2/25/11 (document submittals) NNC 2/2/11: Updated RTMs and specifications to be provided. Requirements traceability to be addressed during he next audit.			LIC-101 Rev. 3 Appendix B Section 4, "Safety Evaluation" states: "the information relied upon in the SE must be docketed correspondence." LIC-101 Rev. 3 states: "The safety analysis that supports the change requested should include technical information in sufficient detail to enable the NRC staff to make an independent assessment regarding the acceptability of the proposal in terms of regulatory requirements and the protection of public health and safety."

			Telegoni with 1 V/ (Ide onapter / only)	164.16.16.16.16.16.16.16.16.16.16.16.16.16.					Open items to be received for CER Approval		
No	SE Sec.	FSAR Sec.	NRC POC Issue	TVA Response(s)	Response Acceptable Y/N	Status/ Current Actions	Resolution Path	RAI No. & Date	RAI Resp. Date	Comments	
				 dated December 3, 2010 (Reference 1). The Independent Verification &Validation (IV&V) report covering the Design and Implementation phases ("Nuclear Automation Watts Bar Unit 2 NSSS Completion Program I&C Projects, IV&V Summary Report for the Post Accident Monitoring System," (Proprietary), WNA-VR-00283-WBT, Revision 2, dated November 2010), submitted in TVA Letter to NRC dated December 3, 2010 (Reference 1). The integration phase is covered in Attachment 10, the proprietary version of "IV&V Summary Report for the Post Accident Monitoring System," WNA-VR-00283-WBT-P, Revision 3, dated December 2010. Attachment 11 contains the non-proprietary version of "IV&V Summary Report for the Post Accident Monitoring System," WNA-VR-00283-WBT-NP, Revision 3, dated December 2010. Attachment 12 contains the "Application For Withholding Proprietary Information From Public Disclosure WNA-VR-00283-WBT-P, Revision 3, "IV &V Summary Report for the Post Accident Monitoring System" (Proprietary)," dated December 2010. 							
33	7.6.1	7.6.7	LPMS: Reference to OI-331, sub item 2. Provide analysis, test, or combined analysis and test for normal operating radiation, temperature, and humidity environment per regulatory position C.1.g of RG 1.133. As an alternate TVA may confirm that the required equipment has been qualified for the environments stated in RG 1.133, position C.1.g and that TVA has reviewed the test report and found it acceptable.	Responder: WEC TVA has reviewed the information provided by Westinghouse describing how the Loose Part Monitoring System (LPMS) sensor is qualified for normal operating conditions provided in Westinghouse letter WBT-D-2782, dated December 17, 2010 (Reference 11) as addressed in regulatory position C.1.g of Reg. Guide 1.133 and found it acceptable. The qualification information on the softline cable and charge converter/preamplifier is being assembled and will be submitted by March 11, 2011.		Partial Response included in etter dated 12/22/10	Open-TVA/WEC Submit qual report by 3/11/11 as stated in TVA letter of 12/22/10, Encl 1, Item 28. Due 12/22/10				