

February 1, 2011

RECEIVED

FEB 10

United States Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-8064

Attn: Licensing Section

Request for License Amendment Re:

Dear Sir or Madam:

DNMS

As a result of a recent Radiation Safety Program review it has come to our attention that the following items need to be updated/included in Roxar, Inc's License Number 42-27765-01.

- 1. Due to restructuring within the Roxar organization, Roxar Inc. is now operating under Roxar Flow Measurement, Inc. There has been no change of control, license material will continue to be managed by Marie Benson, RSO & Norberto Ortigoza, Service Manager-Americas.
- 2. As a subsection to License Condition 10, please include that the licensed material may be used in offshore facilities located within Federal Waters under the jurisdiction of the U.S. Nuclear Regulatory Commission. Lalveady authorized in L.C.10

Roxar Flow Measurement, Inc. shall continue to abide by specific license conditions and Title 10 of the Code of Federal Regulations as applicable to uses under this license. If there are any questions or more information is desired please contact this office at (713)-334-2222.

Best Regards

Service Manager, America

ADAMS#____

574498

2-28-2011

This is to acknowledge the receipt of your letter/application dated

| Joing |

BETWEEN:	***************************************	[FOR ARPB USE]
Accounts Receivable/Payable and Regional Licensing Branches	TO COLUMN THE PROPERTY OF THE	Program Code: 03120 Status Code: Pending Amendment Fee Category: 3P Exp. Date: Fee Comments: Decom Fin Assur Reqd: N
License Fee Worksheet	- License Fee Transmittal	
A. REGION		Name of the Control o
1. APPLICATION ATTACHED Applicant/Licensee: ROXAR, INC Received Date: 02/10/2011 Docket Number: 3036402 Mail Control Number: 574498 License Number: 42-27765-0: Action Type: Amendment	ı	
2. FEE ATTACHED Amount: Check No.:		
3. COMMENTS		
Signed:		
Date:	2-24-2011	
B. LICENSE FEE MANAGEMENT BRAI 1. Fee Category and Amount:	ICH (Check when milestone 03 is entered / /	
2. Correct Fee Paid. Application may be	processed for:	
Amendment:		
Renewal:		
License:		

Signed:

Date:

From: (713) 334-2222 Marie Benson Roxar Flow Measurement, Inc. 3300 Walnut Bend Lane

Origin ID: NQIA

Ship Date: 01FEB11 ActWgt: 0.5 LB CAD: 5348802/INET3130

HOUSTON, TX 77042

SHIP TO: (800) 952-9677

BILL SENDER

Licensing Section

U.S. Nuclear Regulatory Commission 612 E LAMAR BLVD STE 400

ARLINGTON, TX 76011

Delivery Address Bar Code



Ref# Invoice #

PO# Dept#


> FRI - 04 FEB A1 **EXPRESS SAVER**

TRK# 0201 7943 8095 8167

SE FWHA

76011 TX-US

DFW



498

After printing this label:

1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.

2. Fold the printed page along the horizontal line.

3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com.FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, misdeliv costs, and other forms of damage whether direct, incidental,consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$500, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

> Fed Ex. TRK# 7943 8095 8167

SE FWHA

TUE - 08 FEB A1 EXPRESS SAVER



Emp# 739699 03FEBI1 SGRA 60AC1/82C2/183F