

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:7906140420 DOC.DATE: 79/05/25 NOTARIZED: NO DOCKET #
 FACIL:50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH.NAME AUTHOR AFFILIATION
 GILLELAND, J.E. Tennessee Valley Authority
 RECIP.NAME RECIPIENT AFFILIATION
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards deficiency rept re blown fuses in low voltage switchgear.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: -----

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	14 PM Bournia	1	1	15 BC Lwr #3	1	1
	20 LA Lwr #3	1	1	21 AD VASSALLO	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 IRE	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 GAB	1	1	11 STANDRDS DEV	1	1
	12 JORDAN, E/IE	1	1	13 FIELD COOR/IE	1	1
	16 AD FOR ENGR	1	1	17 AD PLANT SYS	1	1
	17 AD REAC SFTY	1	1	19 AD SYS/PROJ	1	1
	22 DIR DPM	1	1	23 DELO	1	1
	AD/SITE TECH	1	1	DIRECTOR DSE	1	1
	GEOSCIENCES BR	1	1	STRUCT ANLYS BR	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

JUN 13 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 43

ma
26

1E4Q5

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

MAY 25 1979

79 MAY 29 8:58

USNRC REGION II
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - BLOWN FUSES IN LOW VOLTAGE
SWITCHGEAR - NCR 994 - FIRST INTERIM REPORT

On April 25, 1979, Milton Hunt, NRC-OIE Region II, was informed that
the subject nonconformance was determined to be reportable in accord-
ance with 10 CFR 50.55(e). Enclosed is our first interim report. We
expect to submit our next report by July 25, 1979.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCKET FILE COPY

Bols
5/11

7906140420

790121