

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8003050461 DATE: 80/02/29 NOTAR: NO DOCKET #
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH. NAME: AUTHOR AFFILIATION: Tennessee Valley Authority
 MILLS, L.M. RECIPIENT AFFILIATION:
 RECIP. NAME:

SUBJECT: Fifth interim deficiency rept re tensile anchor capacities lower than design all owables. No further progress made. Next rept will be provided by 800508.

DISTRIBUTION CODE: 80195 COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: _____

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	14 PM BOURNIA	1		15 BC LWR#3	1
	20 LA LWR#3	1		21 AD LWR	1
INTERNAL:	01 REG FILE	1		02 NRC PDR	1
	05 ISE	2		07 EDO & STAFF	1
	08 MPA	1		09 DEPY DIR DPM	1
	10 QAB	1		11 STANDRDS DEV	1
	12 JORDAN, E/IE	1		13 FIELD COOR/IE	1
	16 AD FOR ENGR	1		17 AD PLANT SYS	1
	17 AD REAC SFTY	1		22 DIR DPM	1
	23 OELD	1		AD/SITE TECH	1
	AEOD	1		DIRECTOR DSE	1
	GEOSCIENCES BR	1		HANAUER, S.	1
	I&C SYS BR	1		MATL ENG BR	1
	MECH ENG BR	1		POWER SYS BR	1
	STRUCT ENG BR	1			
EXTERNAL:	03 LPDR	1		04 NSIC	1
	24 ACRS	16			

Ltr
 MOORE
 EPD#2
 KEBLUSER
 EPB#2

MAR 6 1980

T

TOTAL NUMBER OF COPIES REQUIRED: LTR 52 ENCL 0

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

February 29, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEVILLE NUCLEAR PLANT UNITS 1 AND 2 - TENSILE ANCHOR CAPACITIES
LOWER THAN DESIGN ALLOWABLES - NCR CEB 79-7 - FIFTH INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector T. Burdette on February 12, 1979, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated March 14, May 17, July 30, and December 17, 1979. There has been no further progress on this nonconformance to this time. We expect to submit our next written report by May 8, 1980. This deficiency was reported for Watts Bar, Sequoyah, Hartsville, and Phipps Bend Nuclear Plants.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555