

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

MA/1, JH

ACCESSION NBR:8005210513 DOC.DATE: 80/05/15 NOTARIZED: NO DOCKET #
 FACIL:50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH.NAME AUTHOR AFFILIATION
 * Tennessee Valley Authority
 RECIPI.NAME RECIPIENT AFFILIATION

SUBJECT: First interim deficiency rept re completion of visual insp records for structural steel annulus floor framing welds before welds made, TVA to invalidate records, re-inspect welds & re-instruct inspectors re proper QC records completion.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: _____

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	14 PM BOURNIA	1	1	15 BC LWR #3	1	1
	20 LA LWR #3	1	1	21 AD LWR	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 QAB	1	1	11 STANDRDS DEV	1	1
	13 FIELD COOR/IE	1	1	16 AD FOR ENGR	1	1
	17 AD PLANT SYS	1	1	17 AD REAC SFTY	1	1
	22 DIR DPM	1	1	23 QELD	1	1
	AD/RCI/IE	1	1	AD/SITE TECH	1	1
	AEOD	1	1	DIRECTOR DSE	1	1
	GEOSCIENCES BR	1	1	HANAUER, S.	1	1
	I&C SYS BR	1	1	MATL ENG BR	1	1
	MECH ENG BR	1	1	POWER SYS BR	1	1
	STRUCT ENG BR	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNIT 2
WELDING OF STRUCTURAL STEEL ANNULUS FLOOR FRAMING
NCR 1173
10 CFR 50.55(e)
FIRST INTERIM REPORT

Description of Deficiency

Welding inspector completed visual inspection records for welds of structural steel annulus floor framing before the welds had been made.

Interim Progress

TVA will determine whether this situation is generic or an isolated case.

TVA will invalidate those records completed improperly and reinspect the affected welds. TVA will reinstruct all inspectors on the importance of properly completing QC inspection records for the inspections they have made.

8005210513