

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNIT 2
WELDING OF STRUCTURAL STEEL ANNULUS FLOOR FRAMING
NCR 1173
10 CFR 50.55(e)
FIRST INTERIM REPORT

Description of Deficiency

Welding inspector completed visual inspection records for welds of structural steel annulus floor framing before the welds had been made.

Interim Progress

TVA will determine whether this situation is generic or an isolated case.

TVA will invalidate those records completed improperly and reinspect the affected welds. TVA will reinstruct all inspectors on the importance of properly completing QC inspection records for the inspections they have made.

8006110285