

ma/1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8006110328 DOC. DATE: 80/06/03 NOTARIZED: NO DOCKET #  
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438  
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au ~~05000439~~  
 AUTH. NAME AUTHOR AFFILIATION  
 MILLS, L.M. Tennessee Valley Authority  
 RECIP. NAME RECIPIENT AFFILIATION  
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards second interim deficiency rept re lack of internal  
 purge on two welds in chemical addition & boron recovery  
 sys. Next rept will be submitted by 800723.

DISTRIBUTION CODE: 8019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

| ACTION:   | RECIPIENT              | COPIES |      | RECIPIENT           | COPIES       |     |
|-----------|------------------------|--------|------|---------------------|--------------|-----|
|           | ID CODE/NAME           | LTR    | ENCL |                     | ID CODE/NAME | LTR |
|           | 14 PM <b>Bourbia</b>   | 1      | 1    | 15 BC <b>LWRA 3</b> | 1            | 1   |
|           | 20 LA <b>LWRA 3</b>    | 1      | 1    | 21 AB <b>LWR</b>    | 1            | 1   |
| INTERNAL: | 01 <del>REG FILE</del> | 1      | 1    | 02 NRC PDR          | 1            | 1   |
|           | 05 I&E                 | 2      | 2    | 07 EDO & STAFF      | 1            | 1   |
|           | 08 MPA                 | 1      | 1    | 09 DEPY DIR DPM     | 1            | 1   |
|           | 10 QAB                 | 1      | 1    | 11 STANDROS DEV     | 1            | 1   |
|           | 13 FIELD COOR/IE       | 1      | 1    | 16 AD FOR ENGR      | 1            | 1   |
|           | 17 AD PLANT SYS        | 1      | 1    | 17 AD/CORE&CONT     | 1            | 1   |
|           | 22 DIR DPM             | 1      | 1    | 23 OELD             | 1            | 1   |
|           | AD/RCI/IE              | 1      | 1    | AD/SITE TECH        | 1            | 1   |
|           | AEOD                   | 1      | 1    | DIRECTOR DSE        | 1            | 1   |
|           | GEOSCIENCES BR         | 1      | 1    | HANAUER, S.         | 1            | 1   |
|           | I&C SYS BR             | 1      | 1    | MATL ENG BR         | 1            | 1   |
|           | MECH ENG BR            | 1      | 1    | POWER SYS BR        | 1            | 1   |
|           | STRUCT ENG BR          | 1      | 1    |                     |              |     |
| EXTERNAL: | 03 LPDR                | 1      | 1    | 04 NSIC             | 1            | 1   |
|           | 24 ACRS                | 16     | 16   |                     |              |     |

JUN 19 1980

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

June 3, 1980

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - LACK OF INTERNAL PURGE ON  
TWO WELDS IN CHEMICAL ADDITION AND BORON RECOVERY SYSTEM - NCR 1171 -  
SECOND INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector J. D. Wilcox on April 17, 1980, in accordance with 10 CFR 50.55(e). This was followed by our first interim report dated May 16, 1980. This interim report is in response to the telephone conversation with Floyd Cantrell, NRC-OIE, on May 21, 1980. Enclosed is our second interim report. We expect to submit our next written report by July 23, 1980.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stallo, Jr., Director (Enclosure) ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

B019  
S  
1/1

8006110328