

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8009100401 DOC. DATE: 80/08/29 NOTARIZED: NO DOCKET #
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au ~~05000438~~
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH. NAME AUTHOR AFFILIATION
 MILLS, L.M. Tennessee Valley Authority
 RECIP. NAME RECIPIENT AFFILIATION

MA/1

SUBJECT: First interim deficiency rept re improperly tubed differential pressure indicators on air cleanup units. Appropriate tubing reworking method being investigated. Next written rept will be submitted by 801110.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
ACTION:	A/D LICENSNG 04	1	1	YOUNGBLOOD, B 05	1	1
	RUSHBROOK, M. 06	1	1	BOURNIA, T. 07	1	1
INTERNAL:	AD/RCI/IE 17	1	1	AEOD 18	1	1
	ASLBP/J.HARD	1	1	D/DIR HUM FAC15	1	1
	DIR, HUM FAC S10	1	1	EDO & STAFF 19	1	1
	EQUIP QUAL BR11	1	1	I&E 09	2	2
	LIC QUAL BR 12	1	1	MPA 20	1	1
	NRC PDR 02	1	1	OELD 21	1	1
	PROC/TST REV 13	1	1	QA BR 14	1	1
	REG FILE 01	1	1	RUTHERFORD, W. IE	1	1
STANDRDS DEV 21	1	1				
EXTERNAL:	ACRS 16	16	16	LPDR 03	1	1
	NSIC 08	1	1			

SEP 22 1980

R

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

August 29, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - DIFFERENTIAL PRESSURE INDICATORS
ON AIR CLEANUP UNITS - NCR 1237 - FIRST INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector
R. W. Wright on August 1, 1980, in accordance with 10 CFR 50.55(e).
Enclosed is our first interim report. We expect to submit our next written
report by November 10, 1980.

If you have any questions concerning this matter, please get in touch with
D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8009100401

An Equal Opportunity Employer

B019
S 1/1

R

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2
DIFFERENTIAL PRESSURE INDICATORS ON AIR CLEANUP UNITS
NCR 1237
10 CFR 50.55(e)
FIRST INTERIM REPORT

Description of Deficiency

The differential pressure indicators on the majority of the air cleanup units provided by CTI Nuclear are improperly tubed.

Interim Progress

TVA is investigating the appropriate method for reworking the tubing to comply with TVA specifications.